



Sikorsky Aircraft Corporation

6900 Main Street P.O. Box 9729  
Stratford, Connecticut 06615-9129  
(203) 386-4000

# 269C-1™ HELICOPTER

## ALERT SERVICE

## BULLETIN



NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

269C-1™ IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION.

ASB C1B-045

Basic Issue ▪ February 29/16

SUBJECT: POWER TRAIN – Belt Drive Clutch Control Installation – One-Time Inspection of Cable Pulley Bracket

### Section 1. PLANNING INFORMATION

- A. Effectivity All 269C-1 model helicopters up to and including serial number S0373.
- B. Purpose To perform a one-time inspection of cable pulley bracket.
- C. Background In multiple instances, Sikorsky has been informed of cable pulley bracket (269A5472) wear and failure. The lower mounting tab of the cable pulley bracket (269A5472) has fractured, which caused a reduction in cable tension allowing slippage and power loss of the transmission drive belt.
- D. Description Helicopter is prepared for inspection. Clutch actuator is fully extended. Access to belt drive clutch control installation is gained. Clutch cable pulley bracket assembly, lower pulley bracket assembly, and pulley groove is inspected. Belt drive clutch control spring assembly is removed. Clutch control pulley bracket installation and clutch control pulley bracket installation is disassembled. Center frame cluster fitting lug, bushing, spacers, and brackets are cleaned and inspected. Clutch cable pulley bracket installation is reassembled. Clutch Cable Pulley Bracket Assembly Inspection Data Sheet is completed and helicopter is returned to service.

ONE-TIME  
INSPECTION

Page 1 of 8

Section 1. PLANNING INFORMATION (Continued)

- E. Compliance Compliance is essential. The inspection outlined herein shall be accomplished within the next 100 flight hours or no later than April 29, 2016.
- F. Approval Inspection Item.
- G. Manpower (Estimated)

Task	No. of Men	No. of Hours	Man-Hours*
Inspection of cable pulley bracket assembly, lower pulley bracket assembly, and pulley groove with transmission belt drive clutch cable tension released.	1	0.10	0.10
Removal of belt drive clutch control spring assembly.	1	0.15	0.15
Disassembly of clutch control pulley bracket installation.	1	0.10	0.10
Inspection of center frame cluster fitting lug, bushing, spacers, and brackets.	1	0.30	0.30
Reassembly of clutch cable pulley bracket installation.	1	0.30	0.30
Installation of clutch control installation including cable tension.	1	0.50	<u>0.50</u>
Total Man-Hours			1.45

\*Estimate does not include time required to prepare helicopter or return it to flight status.

- H. Tooling  
None.
- I. Weight and Balance  
Not affected.
- J. Electrical Load Data  
Not affected.
- K. Software Load Data  
Not changed.
- L. References
  - (1) Handbook of Maintenance Instructions (HMI), CSP-C1-2.
  - (2) Temporary Revision No. 269C1-62, Removal of Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.

Section 1. PLANNING INFORMATION (Continued)

- (3) Temporary Revision No. 269C1-64, Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.
- (4) Temporary Revision No. 269C1-65, Installation and Adjustment of Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.

M. Publications Affected

- (1) Temporary Revision No. 269C1-62, Removal of Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.
- (2) Temporary Revision No. 269C1-63, Installation of Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.
- (3) Temporary Revision No. 269C1-64, Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.
- (4) Temporary Revision No. 269C1-65, Installation and Adjustment of Belt Drive Clutch Control Installation, against HMI, CSP-C1-2, Section 10, is issued concurrently with this ASB.
- (5) Temporary Revision No. 269C1-66, What to Inspect - 100-hour Inspection, against HMI, CSP-C1-2, Appendix B, is issued concurrently with this ASB.
- (6) Temporary Revision No. 269I-C1-11, Clutch Control Installation, against Illustrated Parts Catalog (IPC), CSP-C1-6, Section 3, is issued concurrently with this ASB.

N. Attachment

None.

Section 2. MATERIAL INFORMATION

A. Basis for Material Data

Per helicopter.

B. Bill of Material

None.

Section 2. MATERIAL INFORMATION (Continued)

C. Consumable Material



OBSERVE ALL CAUTIONS AND WARNINGS ON CONTAINERS WHEN USING CONSUMABLES. WHEN APPLICABLE, WEAR NECESSARY PROTECTIVE GEAR DURING HANDLING AND USE. IF A CONSUMABLE IS FLAMMABLE OR EXPLOSIVE, MAKE CERTAIN CONSUMABLE AND ITS VAPORS ARE KEPT AWAY FROM HEAT, SPARK AND FLAME. MAKE CERTAIN FIREFIGHTING EQUIPMENT IS READILY AVAILABLE PRIOR TO USE. FOR ADDITIONAL INFORMATION ON TOXICITY, FLASHPOINT AND FLAMMABILITY OF CHEMICALS, CONSULT YOUR MEDICAL PEOPLE OR THE MANUFACTURER OF THE CONSUMABLE.

<u>Qty</u>	<u>Nomenclature</u>	<u>Part No.</u>	<u>Source</u>
A/R	Abrasive Cloth	ANSI B74.18 or equivalent	(1)

- (1) Procure from local supply.

Section 3. ACCOMPLISHMENT INSTRUCTIONS

A. Prepare helicopter for inspection:

- (1) Make sure clutch actuator is fully extended as follows:
  - (a) Set BAT switch to the ON position and CLUTCH control switch to RELEASE; set BAT switch to OFF after motor stops.



TO PREVENT ELECTRICAL SHOCK OF PERSONNEL OR POSSIBLE DAMAGE TO HELICOPTER COMPONENTS, MAKE SURE TO TURN OFF ALL ELECTRICAL POWER.

- (2) Turn off all helicopter electrical power.
- (3) Gain access to belt drive clutch control installation. (Refer to HMI CSP-C1-2, Paragraph 10-23.)

NOTE: Bushing (HS12-4-028-028) is identified as a 0.25 inch outside diameter bushing, secured between the two cable pulley brackets (269A5472).

B. Perform inspection as follows:

- (1) With transmission belt drive clutch cable tension released, inspect the following prior to disassembly:
  - (a) Inspect the bracket lower tab bushing (HS12-4-028-028) as follows:



Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

1. Move clutch cable pulley bracket assembly by hand forward, aft, and laterally about the center frame cluster fitting lug. The bushing (HS12-4-028-028) must move freely in the inner diameter of the center frame cluster fitting lug with no sign of binding. Record results on Clutch Cable Pulley Bracket Installation Inspection Data Sheet (Step E.). (Refer to Temporary Revision No. 269C1-64.)
  - (b) Inspect cable pulley brackets (269A5472) as follows:
    1. Turn lower nut or bolt with hand force to make sure that there is no looseness between the bushing (HS12-4-028-028) and the two cable pulley brackets (269A5472). If the bolt, bushing, and nut show any evidence of looseness between the bracket plates, record results on Clutch Cable Pulley Bracket Installation Inspection Data Sheet (Step E.). (Refer to Temporary Revision No. 269C1-64.)
  - (c) Inspect the groove of pulley (AN219-4) for wear, cracks, and misalignment. Rotate pulley to inspect bearing for smoothness of operation, record results on Clutch Cable Pulley Bracket Installation Inspection Data Sheet (Step E.).
  - (d) Record any wear, damage and other conditions as applicable on Clutch Cable Pulley Bracket Installation Inspection Data Sheet. (Step E.)
- (2) Remove belt drive clutch control spring assembly. (Refer to HMI, CSP-C1-2, Paragraph 10-23, and Temporary Revision No. 269C1-62.)
  - (a) Disassemble clutch control pulley bracket installation, by removing all hardware including cotter pins, nuts, washers, bolts, guard pins, cable, pulley, pulley brackets, bushing, and spacers as required. Inspect parts and hardware as follows: (Refer to HMI, CSP-C1-2, and Temporary Revision No. 269C1-64.)
    1. Clean and inspect inner diameter of center frame cluster fitting lug for sharp edges, elongation, wear, and corrosion. Area may be smoothed using abrasive cloth (ANSI B74.18 or equivalent). Maximum blending 0.005 inch. (Refer to HMI, CSP-C1-2, Appendix D.)
    2. Inspect bushing (HS12-4-028-028) for wear on outer diameter. Roughness or minor wear may be smoothed using abrasive cloth (ANSI B74.18 or equivalent). Wear, damage, burrs, and sharp edges are cause for replacement.

**WARNING**

WEAR DAMAGE TO HOLE ON LOWER TAB OF THE CABLE PULLEY BRACKET (269A5472) COULD RESULT IN FAILURE AND LOSS OF BELT TENSION AND ENGINE POWER.

3. Inspect cable pulley brackets (269A5472) for corrosion, bending, cracks, fretting, wear, cleanliness, and security. Pay particular attention to the edges of the lower tab holes. Inspect edges of lower tab for fretting, sharp edges, burrs, and wear, which are cause for bracket replacement.

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

4. Inspect the two outer spacers (269A4337-003) for wear and to make sure they slide freely over bushing (HS12-4-028-028). Wear, burrs, and sharp edges are cause for replacement.
    - (b) For corrosion protection treatment, refer to HMI, CSP-C1-2, Appendix D.
  - (3) Reassemble clutch cable pulley bracket installation as follows:
    - (a) Install cable assembly on cable pulley and position pulley between cable pulley brackets (269A5472). Install clevis bolt, washer, and nut. Torque nut and install cotter pin. (Refer to HMI, CSP-C1-2, Table 2-3.)
    - (b) Install two guard pins (NAS427K8) in pulley brackets. Make sure that cable is positioned between pulley and guard pins.
    - (c) Install bushing (HS12-4-028-028) through center frame cluster fitting lug. Install two outer spacers (269A4337-003) on bushing (HS12-4-028-028), one spacer on each side of center frame cluster fitting lug. Install one bracket cable pulley bracket (269A5472) on each side of center from cluster fitting lug. Install clevis bolt, washer, and nut. Torque nut and install cotter pin. (Refer to HMI, CSP-C1-2, Table 2-3.)
  - (4) Complete assembly of clutch control installation including cable tension. (Refer to HMI, CSP-C1-2, Paragraph 10-30, Temporary Revision No. 269C1-65.)
- C. Complete Clutch Cable Pulley Bracket Assembly Inspection Data Sheet (Step E.) and Alert Service Bulletin Compliance Record Card. Send to Email Address: [S300ASB@sikorsky.com](mailto:S300ASB@sikorsky.com), Attn: SLH Engineering.
- D. Return helicopter to service.

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

E. Clutch Cable Pulley Bracket Installation Inspection Data Sheet

- (1) Report the following back to Sikorsky Aircraft Corporation Engineering (Email Address: [S300ASB@sikorsky.com](mailto:S300ASB@sikorsky.com)).

ASB No:  C1B-045

Date ASB is Performed: \_\_\_\_\_

Customer/Operator Name: \_\_\_\_\_

Helicopter Serial Number: \_\_\_\_\_

Helicopter Total Time Since New: \_\_\_\_\_

	Yes	No
Was bushing (HS12-4-028-028) moving freely in the center section frame cluster fitting lug?	___	___
Was bushing (HS12-4-028-028) found to be secure without movement between it and the cable pulley brackets (269A5472)?	___	___
Was there any evidence of cable pulley bracket (269A5472) cracking or wear around the lower bracket mounting hole?	___	___
Were lower pulley bracket assembly spacers (269A4337-003) found damaged?	___	___

Please describe details of findings in table below:

Specify issue (incorrect, binding, worn or loose hardware, cracked, nicked or worn bracket, etc.)	Specify damage location (bracket lower mounting hole, bushing inner diameter/outer diameter, cluster fitting lug bore)	Size of damage (inches)	Total time on part (Flight hours)

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

F. Record of compliance:

- (1) Make an appropriate helicopter logbook entry to show compliance with this ASB.
- (2) Upon compliance with the ASB, complete attached ALERT SERVICE BULLETIN COMPLIANCE RECORD CARD and return it to Sikorsky Aircraft Corporation.



(Fold over and tape closed)

**SIKORSKY AIRCRAFT CORPORATION**

**FACSIMILE NUMBER (860) 998-7565**

**EMAIL ADDRESS: GPSIKSASProductSafet@utc.com**

ATTENTION: PRODUCT SAFETY MANAGER  
SIKORSKY AIRCRAFT CORPORATION



**IMPORTANT NOTICE**

Upon **COMPLIANCE** with the attached ASB, Sikorsky requests your cooperation in completing and returning this **ENTIRE PAGE** by **MAIL, FAX, or scan & EMAIL**.

Please fill in the requested information at the bottom of the page, so we may maintain proper records documenting the configuration of your aircraft. This information is useful when determining configuration and effectivity of issues affecting fielded aircraft.

This request is in keeping with our policy to assure that our customers receive the latest information applicable for the maintenance of your aircraft. Thank you.

**ALERT SERVICE BULLETIN:**                      No. C1B-045                      **Compliance Record Card**

**TITLE:** POWER TRAIN – Belt Drive Clutch Control Installation – One-Time Inspection of  
Cable Pulley Bracket

**OWNER/OPERATOR:** \_\_\_\_\_

**SUBMITTED BY:** \_\_\_\_\_ **DATE:** \_\_\_\_\_

**FOLLOWING SERIAL NUMBERS ARE NOT AFFECTED BY THIS ASB**

**ASB HAS BEEN COMPLIED WITH ON HELICOPTER SERIAL NUMBERS:**

\_\_\_\_\_  
\_\_\_\_\_

(Fold Up to Arrows)



No Postage  
Necessary

---

**BUSINESS REPLY MAIL**  
**FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT**

---

**POSTAGE WILL BE PAID BY ADDRESSEE**

**SIKORSKY AIRCRAFT CORPORATION**  
**Commercial Systems and Services**  
**Mailstop K100**  
124 QUARRY ROAD  
TRUMBULL, CT 06611 U.S.A.  
ATTENTION: PRODUCT SAFETY MANAGER  
SIKORSKY AIRCRAFT CORPORATION

**Please complete the form on the reverse side and FAX to**

**FACSIMILE NUMBER (860) 998-7565**

**Or scan and email to:**

**EMAIL ADDRESS: [GPSIKSASProductSafet@utc.com](mailto:GPSIKSASProductSafet@utc.com)**

**or fold and return ENTIRE form to Sikorsky Aircraft Corporation**