



269C-1[®] HELICOPTER

ALERT SERVICE

BULLETIN

NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

EXPORT WARNING: THESE COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE PRIOR AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE. THE TERM "EXPORT" INCLUDES ANY DISCLOSURE AND/OR PROVISION OF ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE TO OR BY FOREIGN NATIONALS (WHETHER LOCATED IN THE UNITED STATES OR ABROAD). THIS REQUIREMENT ALSO APPLIES TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES.

269C-1[®] IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION.

ASB C1B-039
 BASIC ISSUE ▪ May 2/13

SUBJECT: One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer

Section 1. PLANNING INFORMATION

- A. **Effectivity** All 269C-1 model helicopters with T/R blade Serial Number (S/N) S4098, S4103, S4504, or S4751.

Component: T/R Blade Assembly, Part Number (P/N) 269A6035-023.
- B. **Purpose** To perform a one-time inspection of T/R blade with S/N S4098, S4103, S4504, or S4751.

As a result of excess primer collecting in the root end fiberglass airfoil area of a T/R blade, a Foreign Object Debris (F.O.D.) incident occurred.
- C. **Description** Helicopter is prepared for inspection. T/R blades are removed and inspected. If inspection criteria are not met, T/R blades are returned to Helicopter Support Inc. If inspection criteria are met, T/R blades are reinstalled and helicopter is returned to service.
- D. **Compliance** Compliance is essential. The one-time inspection outlined herein shall be accomplished within the next 50 flight hours or 60 calendar days, whichever occurs first.
- E. **Approval** Inspection Item.

Section 1. PLANNING INFORMATION (Continued)

F. Manpower (Estimated)

<u>Task</u>	<u>No. of Men</u>	<u>No. of Hours</u>	<u>Man-Hours*</u>
Cleaning and Inspection of Airfoil.	1	0.15	0.15
Removal of T/R Blades.	1	0.30	0.30
Borescope Inspection.	1	0.75	0.75
Installation of T/R Blades.	2	0.70	1.40
Total Man-Hours		1.9	2.6

*Estimate does not include time required to prepare helicopter or return it to flight status.

G. Material

None.

H. Tooling

<u>Qty</u>	<u>Nomenclature</u>	<u>Part No.</u>	<u>Source</u>
1	Borescope	BK6000, or equivalent	(1)

(1) Procure from local supply

I. Weight and Balance

Not Affected.

J. Electrical Load Data

Not affected.

K. Software Load Data

Not applicable.

L. References:

(1) Handbook of Maintenance Instructions (HMI) CSP-C1-2.

M. Publications Affected

None.

N. Attachment

None.

Section 2. MATERIAL INFORMATION

A. Basis for Material Data

Per helicopter.

B. Bill of Material

Refer to applicable HMI.

C. Consumable Material

Refer to applicable HMI.

Section 3. ACCOMPLISHMENT INSTRUCTIONS

A. Prepare helicopter for inspection:


- (1) Turn off all helicopter electrical power.

B. Perform T/R inspection:

- (1) Clean and visually inspect the airfoil in accordance with the HMI (Section 9).
- (2) Remove T/R blades from the T/R hub assembly in accordance with the HMI (Section 9).
- (3) Measure 1.75 inches from the tip of the blade and mark the location with a non-permanent marker. (Refer to Figure 1). Use the line shown in Figure 1 as a reference measurement. As the primer coating inside the spar is allowed to extend from the root end of the blade to a location no closer than 1.75 inches from the blade tip.
- (4) Using a Snap-On Borescope BK6000, or equivalent, inspect the inside primer coating of the T/R blade spar by inserting the borescope fiber optic cable (with mirror attachment, or built in 90° lens) into the root end of the T/R blade.
- (5) Slowly push the borescope cable into the blade until the end of the primer coating is visible on the borescope monitor. Figure 2 shows how the end of the primer coating typically appears. When the borescope reaches the “break line” of the end of the primer, hold the borescope cable steady and apply a wrap of tape to the borescope cable coming out of the root end of the blade so that the depth measurement (“break line” location) can be determined.
- (6) Remove the borescope cable and using the dimension from the mirror (or built in 90° lens) to the wrap of the tape, determine the distance from the tip of the blade where the break in the primer is located.
 - (a) If any primer coating extends into within 1.75 inches from the tip of the T/R blade, remove the blade from service and contact Customer Service Engineering at 1-800-WINGED-S for further blade disposition.


Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- (b) If the break line of the primer is not within 1.75 inches from the tip of the T/R blade, the blade inspection is complete and the blade may continue in service. (Refer to Figure 3).
 - (7) Reassemble T/R with serviceable blades to T/R hub and complete T/R assembly in accordance with HMI (Section 9)
- C. Return helicopter to service.




TD3067
SA

Figure 1: Reference Mark



TD3068
SA

Figure 2: Typical Borescope View – End of Primer Coating



TD3069
SA

Figure 3: Correct Length of Primer Coating

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

D. Record of Compliance:

- (1) Make an appropriate helicopter logbook entry to show compliance with this ASB.
- (2) Complete attached ALERT SERVICE BULLETIN COMPLIANCE RECORD CARD and return it to Sikorsky Aircraft Corporation.

(Fold over and tape closed)

SIKORSKY AIRCRAFT CORPORATION

FACSIMILE NUMBER (860) 998-7565

EMAIL ADDRESS: GPSIKSASProductSafet@utc.com

ATTENTION: SAS PRODUCT SAFETY MANAGER
SIKORSKY AEROSPACE SERVICES



IMPORTANT NOTICE

Upon **COMPLIANCE** with the attached ASB, Sikorsky requests your cooperation in completing and returning this **ENTIRE PAGE** by **MAIL, FAX, or scan & EMAIL**.

If you have internet access, you may go to www.sikorsky.com to record your compliance.

Please fill in the requested information at the bottom of the page, so we may maintain proper records documenting the configuration of your aircraft. This information is useful when determining configuration and effectivity of issues affecting fielded aircraft.

This request is in keeping with our policy to assure that our customers receive the latest information applicable for the maintenance of your aircraft. Thank you.

ALERT SERVICE BULLETIN: ASB No. C1B-039 **Compliance Record Card**

TITLE: One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer

OWNER/OPERATOR: _____

SUBMITTED BY: _____ **DATE:** _____

FOLLOWING SERIAL NUMBERS ARE NOT AFFECTED BY THIS ASB

ASB HAS BEEN COMPLIED WITH ON HELICOPTER SERIAL NUMBERS:

(Fold Up to Arrows)



No Postage
Necessary

BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT

POSTAGE WILL BE PAID BY ADDRESSEE

SIKORSKY AIRCRAFT CORPORATION
P.O. BOX 9729
6900 MAIN STREET
STRATFORD, CONNECTICUT 06615-9129 U.S.A.
MAILSTOP: **S328A**
ATTENTION: SAS PRODUCT SAFETY MANAGER
SIKORSKY AEROSPACE SERVICES

Please complete the form on the reverse side and FAX to
FACSIMILE NUMBER (860) 998-7565
Or scan and email to:
EMAIL ADDRESS: GPSIKSASProductSafet@utc.com
or fold and return ENTIRE form to Sikorsky Aircraft Corporation