

Sikorsky Aircraft Corporation

6900 Main Street P.O. Box 9729 Stratford, Connecticut 06615-9129 (203) 386-4000

269D® HELICOPTER ALERT SERVICE BULLETIN



NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

EXPORT WARNING: THESE COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE PRIOR AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE. THE TERM "EXPORT" INCLUDES ANY DISCLOSURE AND/OR PROVISION OF ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE TO OR BY FOREIGN NATIONALS (WHETHER LOCATED IN THE UNITED STATES OR ABROAD). THIS REQUIREMENT ALSO APPLIES TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES.

269C-1® IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION

ASB DB-050 BASIC ISSUE • May 2/13

SUBJECT: One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer

Section 1. PLANNING INFORMATION

A. Effectivity All 269D model helicopters with T/R blade serial number (S/N) S4098, S4103, S4504, or S4751.

Component: T/R Blade Assembly, Part Number (P/N) 269A6035-023.

B. Purpose To perform a one-time inspection of T/R blade with S/N S4098, S4103, S4504, or S4751.

As a result of excess primer collecting in the root end fiberglass airfoil area of a T/R blade, a Foreign Object Debris (F.O.D.) incident occurred.

C. Description Helicopter is prepared for Inspection. T/R blades are removed and inspected. If

inspection criteria are not met, T/R blades are returned to Helicopter Support Inc. If inspection criteria are met, T/R blades are reinstalled and helicopter is returned to

service.

D. Compliance Compliance is essential. The one-time inspection outlined herein shall be

accomplished within the next 50 hours of operations or 60 calendar days

whichever occurs first.

E. Approval Inspection Item.

One-Time Inspection

Section 1. PLANNING INFORMATION (Continued)

F. Manpower (Estimated)

<u>Task</u>	No. of Men	No. of Hours	Man-Hours*
Cleaning and Inspection of Airfoil.	1	0.15	0.15
Removal of T/R Blades.	1	0.30	0.30
Borescope Inspection.	1	0.75	0.75
Installation of T/R Blades.	2	0.80	1.60
Total Man-Hours		2.0	2.7
*Estimate does not include time required to	orepare helicopter or	r return it to flight state	us.

G. Material

None.

H. Tooling

<u>Qty</u>	<u>Nomenclature</u>	Part No.	<u>Source</u>
1	Borescope	BK6000, or equivalent	(1)

- (1) Procure from local supply
- I. Weight and Balance

Not Affected.

J. Electrical Load Data

Not affected.

K. Software Load Data

Not applicable.

- L. References:
 - (1) Handbook of Maintenance Instructions (HMI) CSP-D-2.
 - (2) HMI CSP-D-9.
- M. Publications Affected

None.

Section 1. PLANNING INFORMATION (Continued)

N. Attachment

None.

Section 2. MATERIAL INFORMATION

A. Basis for Material Data

Per helicopter.

B. Bill of Material

Refer to applicable HMI.

C. Consumable Material

Refer to applicable HMI.


Section 3. ACCOMPLISHMENT INSTRUCTIONS

- A. Prepare helicopter for inspection:
 - Turn off all helicopter electrical power.
- B. Perform T/R inspection:
 - (1) Clean and visually inspect the airfoil in accordance with the HMI (Section 9).
 - (2) Remove T/R blades from the T/R hub assembly in accordance with the HMI (Section 9).
 - (3) Measure 1.75 inches from the tip of the blade and mark the location with a non-permanent marker. (Refer to Figure 1). Use this line shown in Figure 1 as a reference measurement. As the primer coating inside the spar is allowed to extend from the root end of the blade to a location no closer than 1.75 inches from the blade tip.
 - (4) Using a Snap-On Borescope BK6000, or equivalent, inspect the inside primer coating of the T/R blade spar by inserting the borescope fiber optic cable (with mirror attachment, or built in 90° lens) into the root end of the T/R blade.
 - (5) Slowly push the borescope cable into the blade until the end of the primer coating is visible on the borescope monitor. Figure 2 shows how the end of the primer coating typically appears. When the borescope reaches the "break line" of the end of the primer, hold the borescope cable steady and apply a wrap of tape to the borescope cable coming out of the root end of the blade so that the depth measurement ("break line" location) can be determined.
 - (6) Remove the borescope cable and using the dimension from the mirror (or built in 90° lens) to the wrap of the tape, determine the distance from the tip of the blade where the break in the primer is located.

269D ALERT SERVICE BULLETIN

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- (a) If any primer coating extends to within 1.75 inches from the tip of the T/R blade, remove the blade from service and contact Customer Service Engineering at 1-800-WINGED-S for further blade disposition.
- (b) If the break line of the primer is not within 1.75 inches from the tip of the T/R blade, the blade inspection is complete and the blade may continue in service. (Refer to Figure 3).
- (7) Reassemble T/R with serviceable blades to T/R hub and complete T/R assembly in accordance with HMI (Section 9)
- C. Return helicopter to service.



TD3067

Figure 1: Reference Mark




Figure 2: Typical Borescope View – End of Primer Coating




Figure 3: Correct Length of Primer Coating

269D ALERT SERVICE BULLETIN

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- D. Record of Compliance:
 - (1) Make an appropriate helicopter logbook entry to show compliance with this ASB.
 - (2) Complete attached ALERT SERVICE BULLETIN COMPLIANCE RECORD CARD and return it to Sikorsky Aircraft Corporation.

SIKORSKY AIRCRAFT CORPORATION

FACSIMILE NUMBER (860) 998-7565

EMAIL ADDRESS: GPSIKSASProductSafet@utc.com

ATTENTION: SAS PRODUCT SAFETY MANAGER SIKORSKY AEROSPACE SERVICES

MPLIANCE with the returning this you have internet acc	s ENTIRE PAG		-	ration in comple	
ou have internet acc		•	AX, or scan & l	_	eting and
	cess, you may go	to <u>www.sikorsk</u>	<u>xy.com</u> to record	your compliance	₽.
	ng the configu	ration of you	r aircraft. This	s information is	s useful
	-	•			e latest
ERVICE BULLE	TIN:	ASB No. DB-05	50 Comp	iance Record (Card
One-Time Tail Rotor	(T/R) Blade Bore	escope Inspectio	on for Excess Pri	ner	
OPERATOR: _					
ГЕD ВҮ:]	DATE:		
LLOWING SERIA	AL NUMBERS	S ARE <u>NOT</u> A	AFFECTED B	Y THIS ASB	
B HAS BEEN CON	MPLIED WIT	H ON HELIC	COPTER SER	IAL NUMBER	RS:
n q' S - - [']	n determining confiquest is in keeping information application application application. SERVICE BULLE One-Time Tail Rotor COPERATOR: TED BY: OLLOWING SERIA	n determining configuration and quest is in keeping with our policinformation applicable for the material service bulletin: One-Time Tail Rotor (T/R) Blade Bore A/OPERATOR: TED BY: DLLOWING SERIAL NUMBERS	n determining configuration and effectivity of quest is in keeping with our policy to assure the information applicable for the maintenance of SERVICE BULLETIN: ASB No. DB-08 One-Time Tail Rotor (T/R) Blade Borescope Inspection COPERATOR: TED BY: DLLOWING SERIAL NUMBERS ARE NOT A	n determining configuration and effectivity of issues affection duest is in keeping with our policy to assure that our custom information applicable for the maintenance of your aircraft SERVICE BULLETIN: ASB No. DB-050 Complement Tail Rotor (T/R) Blade Borescope Inspection for Excess Print Pr	One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer R/OPERATOR:





BUSINESS REPLY MAIL

FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT

POSTAGE WILL BE PAID BY ADDRESSEE

SIKORSKY AIRCRAFT CORPORATION

P.O. BOX 9729 6900 MAIN STREET STRATFORD, CONNECTICUT 06615-9129 U.S.A. MAILSTOP: **\$328A**

ATTENTION: SAS PRODUCT SAFETY MANAGER SIKORSKY AEROSPACE SERVICES

Please complete the form on the reverse side and FAX to FACSIMILE NUMBER (860) 998-7565

Or scan and email to:

EMAIL ADDRESS: GPSIKSASProductSafet@utc.com or fold and return ENTIRE form to Sikorsky Aircraft Corporation