

Sikorsky Aircraft Corporation

6900 Main Street P.O. Box 9729 Stratford, Connecticut 06615-9129 (203) 386-4000

269D[™] HELICOPTER ALERT SERVICE BULLETIN

NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY ARCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY ARCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WITHOUT ON CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

EXPORT WARNING: THESE COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE PRIOR AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE. THE TERM "EXPORT" INCLUDES ANY DISCLOSURE AND/OR PROVISION OF ACCESS TO COMMODITES, TECHNICAL DATA OR SOFTWARE TO OR BY FOREIGN NATIONALS (WHETHER LOCATED IN THE UNITED STATES OR ABROAD). THIS REQUIREMENT ALSO APPLIES TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES.

269D[™] IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION.

ASB DB-060

Basic Issue • November 21/14

SUBJECT: One-Time Inspection of Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks for Damage and/or Wear, and Verification of Parts Configuration

Section 1. PLANNING INFORMATION

- A. Effectivity All 269D and 269D Configuration "A" model helicopters.
- B. Purpose To perform a one-time inspection of tail rotor flight control cables, pulleys, and forward and aft bellcranks for damage and/or wear, and verification of parts configuration.
- C. Description Helicopter is prepared for inspection. Access is gained to the tail rotor flight control cables, pulleys, and forward and aft bellcranks. Tail rotor flight control cables, pulleys, and forward and aft bellcranks are inspected. Routing and alignment of cables are inspected. Cleanliness and corrosion inspection is completed. If necessary, any worn and/or damaged parts are replaced. If necessary, tail rotor control cables are reinstalled. Cable rig check is completed. Results are recorded on Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks Inspection Data Sheet (attached). Helicopter is returned to service.
- D. Compliance Compliance is essential. The inspection outlined herein shall be accomplished no later than the next 100 hour inspection or 90 days from the issue date of this Alert Service Bulletin (ASB), whichever occurs first.
- E. Approval Inspection Item.

ONE-TIME INSPECTION

269D ALERT SERVICE BULLETIN

Section 1. PLANNING INFORMATION (Continued)

F. Manpower (Estimated)

Task	No. of Men	No. of Hours	Man-Hours*
Prepare aircraft for inspection.	1	0.25	0.25
Inspect tail rotor cables, cable tension, cable bellcranks, and associate hardware.**	2	0.60	0.80
Conduct rigging check of tail rotor controls.**	2	0.80	1.00
Reinstall/close access panels.	1	0.40	<u>0.40</u>
Total Man-Hours			2.45

*Estimate does not include time required to prepare helicopter or return it to flight status.

**Estimate does not require two people for entire task.

G. Tooling

None.

H. Weight and Balance

Not affected.

I. Electrical Load Data

Not affected.

J. Software Load Data

Not applicable.

- K. References
 - (1) Handbook of Maintenance Instructions (HMI) CSP-D-2.
 - (2) HMI, Appendix D, Corrosion Control Manual.
 - (3) HMI CSP-D-9.
 - (4) HMI, Section 13.
- L. Publications Affected
 - (1) Temporary Revision No. 269D-37 against HMI CSP-D-2, Appendix B, Section 2, Table B-2 will be issued at a later date.



Section 1. PLANNING INFORMATION (Continued)

- (2) Temporary Revision No. 269D-38 against HMI CSP-D-2, Appendix B, Section 2, Table B-2 will be issued at a later date.
- (3) Temporary Revision No. 269DA-41 against HMI CSP-D-9, Appendix B, Section 2, Table B-2 will be issued at a later date.
- (4) Temporary Revision No. 269DA-42 against HMI CSP-D-9, Appendix B, Section 2, Table B-2 will be issued at a later date.
- M. Attachment

None.

Section 2. MATERIAL INFORMATION

A. Basis for Material Data

Per helicopter.

B. Bill of Material

None.

C. Consumable Material

None.

Section 3. ACCOMPLISHMENT INSTRUCTIONS

- A. Prepare helicopter for inspection:
 - (1) Turn off all helicopter electrical power.
 - (2) Gain access to tail rotor flight control cables, pulleys, and forward and aft bellcranks.
- B. Perform tail rotor flight controls inspection as follows:
 - <u>NOTE:</u> Make sure to record inspection results on Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks Inspection Data Sheet. (Refer Step D, and Tables 1, 2, and 3).
 - (1) Inspect tail rotor flight control cables, pulleys, and forward and aft bellcranks, and measure initial cable tension. (Refer to HMI CSP-D-2, Paragraph 9-35 or HMI CSP-D-9, Paragraph 9-35). Record initial cable tension results on Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks Inspection Data Sheet.
 - (2) Inspect routing and alignment of cables around bellcranks, pulleys, and through routing holes on airframe. No rubbing or chafing is allowed. (Refer to HMI CSP-D-2, Paragraph 9-35 or HMI CSP-D-9, Paragraph 9-35).

ONE-TIME

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- (3) Inspect forward and aft pulleys, forward and aft bellcranks, and pulley bearings for freedom of movement. (Refer to HMI CSP-D-2, Paragraph 9-35 or HMI CSP-D-9, Paragraph 9-35).
- (4) Apply slight force to forward bellcrank, and make sure forward bellcrank mounting bolt is not loose or elongated. If repair is required, refer to HMI, section 13.

<u>NOTE:</u> Make sure forward bellcrank is secure, and not rubbing against the forward spacer and/or aft stop.

- (5) Inspect tail rotor control cable pulleys and aft bellcrank for worn cable grooves, worn bearings, and assure smooth operation. (Refer to HMI CSP-D-2, Paragraph 9-35 or HMI CSP-D-9, Paragraph 9-35).
- (6) Inspect all tail rotor control cable components, bellcranks, mounts, and hardware for cleanliness and corrosion. If corrosion is found or corrosion protection is required, refer to HMI Appendix D, Corrosion Control Manual.
- (7) Replace any worn and/or damaged cables, and/or any unserviceable parts. (Refer to HMI CSP-D-2, Paragraph 9-35 or HMI CSP-D-9, Paragraph 9-35).
- (8) If cables and/or controls were disconnected or removed, perform rig check of tail rotor controls. (Refer to HMI CSP-D-2, Paragraph 9-3 or HMI CSP-D-9, Paragraph 9-3).
- (9) Record inspection results on Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks Inspection Data Sheet. (Refer to Step D, and Tables 1, 2, and 3).
- C. Return helicopter to service.

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)	
--	--

D. Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks Inspection Data Sheet

(1) Report the following data to Sikorsky Airc	raft Corporation.	
Date ASB is Performed:		
Customer/Operator Name:		
Helicopter Serial Number:		
Helicopter Total Time Since New:		
Initial Tail Rotor Control Cable Tension:		
Tail Rotor Control Cables correctly installed per HMI: Wear and/or damage found on the tail rotor cables:	Yes Yes	
If Yes, complete Table 1.		
Damage to cables or airframe due to misrouting: If Yes, complete Table 2.	Yes	_ No
Any additional discrepancies, improper assembly, pulley damage, bellcrank damage, etc:	Yes	_ No
If Yes, complete Table 3.		

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

		ТАВ	LE 1		
Damage Type (Chafing, wear, or other damage)	Location (distance from feature)	Size of Damage (inches)	Part Number	Part Serial Number (if applicable)	Total Time on Discrepant Part (if applicable)

		TAB	LE 2		
Damage Type (Chafing, wear, or other damage)	Location (distance from feature)	Size of Damage (inches)	Part Number	Part Serial Number (if applicable)	Total Time on Discrepant Part (if applicable)

		TAB	LE 3		
Type and/or Condition	Location (distance from feature)	Size of Damage (inches)	Part Number	Part Serial Number (if applicable)	Total Time on Discrepant Part (if applicable)

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- E. Record of compliance:
 - (1) Make an appropriate helicopter logbook entry to show compliance with this ASB.
 - (2) Upon compliance with the ASB, complete attached ALERT SERVICE BULLETIN COMPLIANCE RECORD CARD and ASB Work Sheet and return it to Sikorsky Aircraft Corporation.

(Fold over and tape closed)

SIKORSKY AIRCRAFT CORPORATION

FACSIMILE NUMBER (860) 998-7565

EMAIL ADDRESS: <u>GPSIKSASProductSafet@utc.com</u>

ATTENTION: SAS PRODUCT SAFETY MANAGER SIKORSKY AEROSPACE SERVICES

-	OMPLIANCE with the attached ASB, Sikorsky requests your cooperation in completing an returning this ENTIRE PAGE by MAIL, FAX, or scan & EMAIL.
IJ	f you have internet access, you may go to <u>www.sikorsky.com</u> to record your compliance.
proper	e fill in the requested information at the bottom of the page, so we may maintain records documenting the configuration of your aircraft. This information is usefuen and effectivity of issues affecting fielded aircraft.
This re	quest is in keeping with our policy to assure that our customers receive the latest information applicable for the maintenance of your aircraft. Thank you.
ALERT	SERVICE BULLETIN: <u>ASB No. DB-060</u> Compliance Record Card
TITLE:	One-Time Inspection of Tail Rotor Flight Control Cables, Pulleys, and Forward
	and Aft Bellcranks for Damage and/or Wear, and Verification of Parts
	Configuration
OWNEI	R/OPERATOR:
CI IDN/I	TTED BY: DATE:
SURMI	DLLOWING SERIAL NUMBERS ARE <u>NOT</u> AFFECTED BY THIS ASB
	LEO WING BERIAE NUMBERS ARE <u>NOT</u> AFFECTED DT THIS ASD
F	BB <u>HAS BEEN COMPLIED</u> WITH ON HELICOPTER SERIAL NUMBERS:



No Postage Necessary

BUSINESS REPLY MAIL FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT

POSTAGE WILL BE PAID BY ADDRESSEE

SIKORSKY AIRCRAFT CORPORATION

P.O. BOX 9729 6900 MAIN STREET STRATFORD, CONNECTICUT 06615-9129 U.S.A. MAILSTOP: **S328A** ATTENTION: SAS PRODUCT SAFETY MANAGER SIKORSKY AEROSPACE SERVICES

Please complete the form on the reverse side and FAX to FACSIMILE NUMBER (860) 998-7565

Or scan and email to: EMAIL ADDRESS: GPSIKSASProductSafet@utc.com or fold and return ENTIRE form to Sikorsky Aircraft Corporation