SCHWEIZER AIRCRAFT CORP.

Supplement to the Approved Rotorcraft Flight Manual

For

Schweizer 300C Model 269C Helicopter

See Page 2 for Effectivity

Special Requirements for Aircraft Exported to China

Part No. 269A0053

Date of Approval:

JUN 4 2002

Approved By:

Vito A. Pulera 🤚 💮 💮

1

ROTORCRAFT FLIGHT MANUAL SUPPLEMENT FOR 300C MODEL 269C HELICOPTERS WITH SPECIAL REQUIREMENTS FOR CHINA

S/N 1796 & Subs.

LOG OF PAGES

PAGE	DATE	PAGE	DATE
1	04 Jun 2002	7	04 Jun 2002
2	04 Jun 2002	8	04 Jun 2002
3	04 Jun 2002	9	04 Jun 2002
4	04 Jun 2002	10	04 Jun 2002
5	04 Jun 2002	11	04 Jun 2002
6	04 Jun 2002	12	04 Jun 2002

NOTE: The change bar (1) defines the latest FAA Approved changes.

REVISION TABLE

Revision Number	Date	Description
	,	
	5	

This page is intentionally left blank.

Table of Contents

Section No.	Title	Page No.
Section I	Introduction and General	7
Section II	Limitations	8
Section III	Emergency Procedures	10
Section IV	Normal Procedures	11
Section V	Performance Data	11
Section VI	Weight & Balance	12
Section VII	Aircraft Handling, Service, and Maintenance	12
Section VIII	Additional Operations and Performance Data	12

This page is intentionally left blank.

Section I Introduction and General

This Supplement is provided for 300C Model 269C Helicopters with special requirements for China.

Except as modified by this Rotorcraft Flight Manual Supplement, operation in compliance with Section II thru V of the basic Approved Rotorcraft Flight Manual is mandatory. Other sections of the RFM or Supplement are recommended procedures.

Issued: 04 Jun 2002 7

Section II Limitations

2-1. RPM Limitations

 The engine RPM limitation of 3000 corresponds to the main rotor RPM of 442; the engine RPM limitation of 3200 corresponds to the main rotor RPM of 471.

2-2. Placards for Passengers

 The following placards shall be displayed on all helicopters adjacent to their English counterparts exported to China:

座位间有变矩杆禁止堆放物品

269A9886-181 [No Stowage Between Seats With Collective Installed]

座 位 间 禁 止堆 放 物 品

269A9886-277 [No Storage Between Seats]

右座乘客

269A9889-233 [Right Hand Passenger]

中座乘客

269A9889-235 [Center Passenger]

抬 起

269A9889-3 [Lift]







269A9889-1 [First Aid Kit], Apply placard over existing text

禁止蹬踏

269A9889-19 [No Step]

禁止吸烟

269A9889-47 [No Smoking]

储物箱最大重量20磅(9千克)

269A9889-263 [20 Lbs Max Gross Weight In Glove Box]



269A9889-219 [To Open], if triple latch doors are installed



269A9889-220 [To Open], if triple latch doors are installed



269A9889-216 [To Open], if triple latch doors are installed



269A9889-215 [To Open], if triple latch doors are installed



闭

269A9889-223 [Closed], if triple latch doors are installed.

Section III Emergency Procedures

3-1, Main Rotor Low Speed Warning

Refer to CSP-C-1W RFM Supplement.

Section IV Normal Procedures

4-1. Mandatory Equipment (269A0053)

- 300C Aircraft (S/N 1796 & Subs.) shall be equipped in accordance with 269A0053 including the following mandatory equipment required for export to China.
 - 269Λ9532 Low Rotor Warning and AES/Engine Overspeed System
 - 2) CSP-C-1V Supplement
 - 3) CSP-C-1W Supplement
 - 4) 269A9889 Passenger Placards (Identified in Chinese)
 - 5) 269A4398 External Power Receptacle

4-2. Pilot's Preflight Inspection

Seat Belts and Shoulder Harnesses.

Check

- The pilot is required to ensure that each passenger is briefed on when and how to fasten and unfasten the seat belt and shoulder harness. All occupants must keep the seat belt and shoulder harness fastened while seated in the aircraft.
- For each seat that is unoccupied, the pilot must ensure that the seat belt and shoulder harness is properly stowed or secured to prevent any obstruction or interference with flight controls or any other equipment installed in the aircraft.

Section V

Performance

5-1. Additional Performance Data

• The best glide angle speed and minimum rate of decent speed is 52 KIAS.

FAA Approved: 04 Jun 2002

Section VI Weight and Balance

Not affected

Section VII

Aircraft Handling, Servicing and Maintenance

Not affected

Section VIII

Additional Operations and Performance Data

Not affected