

PUBLICATIONS INDEX

FOR

SCHWEIZER

MODELS 269A, TH-55A, A-1, B & C HELICOPTERS

NO. CSP-P-1 REISSUED 23 JAN 2020

Warning:

This document, or an embodiment of it in any media, discloses information which is proprietary, is the property of Schweizer RSG and/or its subsidiaries, is an unpublished work protected under applicable copyright laws, and is delivered on the express condition that it is not to be used, disclosed, reproduced, in whole or in part (including reproduction as a derivative work), or used for manufacture for anyone other than Schweizer RSG and/or its subsidiaries without its written consent, and that no right is granted to disclose or so use any information contained herein. All rights reserved. Any act in violation of applicable law may result in civil and criminal penalties

Models 269A, TH-55A, A-1, B & C – Publication Index

LIST OF EFFECTIVE PAGES

INSERT LATEST CHANGED PAGES, DESTROY SUPERSEDED PAGES.

PAGEISSUED/REVISED

Title.....	23 Jan 2020
i.....	23 Jan 2020
ii.....	23 Jan 2020
iii.....	23 Jan 2020

Section 1

Service Publications and Kits

1-1.....	02 May 2013
1-2.....	19 Jan 2019
1-3.....	15 May 2014
1-4 thru 1-6.....	30 Nov 2015
1-7 thru 1-9.....	24 Oct 2008
1-10.....	30 Nov 2015

Section 2

Service Information Notices and Service Bulletins

2-1.....	Original – 12 Mar 1999
2-2 thru 2-3.....	21 Sep 2012
2-4.....	Original – 12 Mar 1999
2-5 thru 2-11.....	21 Sep 2012
2-12.....	Original – 12 Mar 1999
2-13 thru 2-17.....	21 Sep 2012
2-18.....	Original – 12 Mar 1999
2-19.....	21 Sep 2012
2-20.....	Original – 12 Mar 1999
2-21.....	21 Sep 2012
2-22.....	Original – 12 Mar 1999
2-23 thru 2-30.....	21 Sep 2012
2-31.....	Original – 12 Mar 1999
2-32 thru 2-33.....	21 Sep 2012
2-34 thru 2-35.....	Original – 12 Mar 1999
2-36 thru 2-37.....	21 Sep 2012
2-38.....	Original – 12 Mar 1999
2-39.....	21 Sep 2012
2-40.....	Original – 12 Mar 1999
2-41.....	21 Sep 2012
2-42.....	Original – 12 Mar 1999
2-43 thru 2-44.....	02 May 2013
2-45.....	24 Aug 2010
2-46.....	02 May 2013
2-47.....	30 Jun 2015
2-48.....	01 Mar 2016
2-49 thru 2-50.....	30 June 2016

Models 269A, TH-55A, A-1, B & C – Publication Index

LIST OF EFFECTIVE PAGES

INSERT LATEST CHANGED PAGES, DESTROY SUPERSEDED PAGES.

PAGE	ISSUED/REVISED
Section 3	
Service Letters	
3-1	21 Sep 2012
3-2 thru 3-3	Original – 12 Mar 1999
3-4 thru 3-5	21 Sep 2012
3-6	Original – 12 Mar 1999
3-7 thru 3-10	21 Sep 2012
Section 4	
Temporary Revisions	
4-1	30 Sep 2013
4-2	13 Jul 2015
4-2 thru 4-7	30 Nov 2015
4-8	30 Jun 2016
4-9 thru 4-16	30 Nov 2016

This page is intentionally left blank

SERVICE PUBLICATIONS AND KITS**NOTE**

The following index provides a complete list of publications available to support Schweizer Models 269A, TH-55A, A-1, B & C Helicopters. Refer to Service Letter L-147 for explanation of intended scope and revision process.

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-A-1	Service Procedures Manual	Feb 2003	
CSP-A-2	Labor Allowance Manual	20 Mar 1978	7 Aug 1985
CSP-AS-8	Service Information Notice, Bulletin and Letter Set	(See Sections 2 and 3)	(See Sections 2 and 3)

269A/A-1 FLIGHT MANUAL

CSP-AA-1	269A Rotorcraft (Configuration a)	07 Apr 1964 (FAA)	30 Oct 2003 (FAA)
CSP-AA-2	269A-1 Rotorcraft	13 May 1964	30 Oct 2003 (FAA)
CSP-AB-1	269A Rotorcraft , Supplement Pages (Configuration b)	08 Apr 1964	30 Oct 2003 (FAA)
CSP-AC-1	269A Rotorcraft Supplemental Pages (Configuration c)	09 Jul 1964	30 Oct 2003 (FAA)
CSP-AD-1	269A Owner's Manual (U.S. Army TH-55A Primary Trainer) (Configuration d)	05 Nov 1964	30 Oct 2003 (FAA)

269A/A-1 FLIGHT MANUAL SUPPLEMENTS

CSP-AA-1A	Rotorcraft Combination Dispersal Ag Kit PN 269A4153	07 Nov 1973 (FAA)	—
CSP-AA-1B	Amphibious Float Landing Gear PN 4300	23 Feb 1967	—
CSP-AA-1C	Low RPM Warning System PN M10098 (TH-55A)	31 Jan 1977	—

269B FLIGHT MANUAL

CSP-BA-1	269B Rotorcraft (Configuration a)	30 Dec 1963 (FAA)	30 Oct 2003 (FAA)
CSP-BB-1	269B Rotorcraft Supplemental Pages (Configuration b)	05 Feb 1968 (FAA)	30 Oct 2003 (FAA)

269B FLIGHT MANUAL SUPPLEMENTS

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-B-1A	Rotorcraft Combination Dispersal Ag Kit PN 269A4153	07 Nov 1973 (FAA)	
CSP-B-1B	Amphibious Float Landing Gear PN 269A4300	18 Jun 1973 (FAA)	
CSP-B-1C	Rotorcraft Right Hand Litter PN 269A4301	22 Mar 1966 (FAA)	
CSP-B-1D	Rotorcraft Right Hand Litter and Float PN 269A4301-39	18 Jun 1973 (FAA)	

269C FLIGHT MANUAL

CSP-C-1	269C Pilot's Flight Manual	16 Jan 2019	
---------	----------------------------	-------------	--

269C FLIGHT MANUAL SUPPLEMENTS

CSP-C-1A	Amphibious Float Landing Gear PN269A4300-9	26 Jun 1970 (FAA)	21 Sep 1988
CSP-C-1B	Amphibious Float Landing Gear PN269A4300-15	27 May 1998 (FAA)	
CSP-C-1C	Rotorcraft Combination Dispersal Ag Kit PN269A4153	07 Oct 1971 (DOA/FAA)	21 Sep 1988
CSP-C-1D	Right Hand Litter and Litter Float PN269A4301-51 and PN269A4301-39	21 Sep 1988 (FAA)	04 Oct 1996
CSP-C-1E	CANCELED (Refer to the Precision Supplement supplied with Baggage Rack Kit PN 269A4887-1.)		
CSP-C-1F	Rotorcraft Dual Engine RPM Operation	18 Dec 1973 (FAA)	21 Sep 1988
CSP-C-1G	Cargo Hook Installation (PN 269A4971)	23 Mar 1976 (FAA)	21 Sep 1988
CSP-C-1H	Siren Installation (Federal PA-100) PN269A4960	23 Mar 1976 (FAA)	21 Sep 1988
CSP-C-1I	Engine Throttle Governor PN 269A4995	18 Dec 1980 (FAA)	08 Feb 2006 (FAA)
CSP-C-1J	Nickel-Cadmium Battery PN 269A4987	1 Sep 1983 (FAA)	21 Sep 1988

269C FLIGHT MANUAL SUPPLEMENTS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-C-1K	Engine Overspeed Installation PN269A4997-1 or -3	21 Sep 1988	13 Mar 1997
CSP-C-1L	Rotorcraft Combination Dispersal Ag Kit PN269A4153-3	30 May 1986	21 Sep 1988
CSP-C-1M	Optional Instrument Panel/Console Installation PN269A4540	12 Aug 1988	—
CSP-C-1N Part 1	Optional Instrument/Avionics Inst.	12 Aug 1988	15 May 2014
CSP-C-1N Part 2	Optional Instrument/Avionics Inst.	15 May 2014	—
CSP-C-1P	Pakistan Army Model TH-300C Helicopter Optional Instrument/ Avionics Inst.	28 Oct 1993	—
CSP-C-1Q	Garmin GP150/GPS150XL Navigation Sys. Operating Procedures	09 Mar 1994	13 Apr 1999
CSP-C-1R	65.2 Gallon Auxiliary Fuel System Installation (PN269A8359-7)	27 Feb 1997	18 Dec 2006
CSP-C-1S	Cabin Heater Kit Installation (PN 269A4451-105, -107, -115, -117)	18 Jul 1997	06 May 2003
CSP-C-1T	Extended Height Landing Gear (PN 269A3260-1)	12 Nov 1997	—
CSP-C-1U	66.0 Gallon Auxiliary Fuel System Installation (PN 269A8700-9)	23 Mar 2000	18 Dec 2006
CSP-C-1V	Special Requirements for Aircraft Exported to China (PN 269A0053)	04 Jun 2002	—
CSP-C-1W	“STAR” System Startup RPM Limiter/Automatic Engagement/Rotor Low RPM Warning Installation (PN 269A9532-1)	04 Jun 2002	24 Oct 2002

MODEL 269C HANDBOOK OF MAINTENANCE INSTRUCTIONS

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-C-2	Basic Handbook of Maintenance Instructions (Basic HMI):	15 Mar 1982	30 Nov 2015
	Section 1	24 Sep 2004	—
	Section 2	30 Aug 1994	30 Nov 2015
	Section 3	17 Oct 2008	30 Nov 2015
	Section 4	17 Oct 2008	30 Sep 2013
	Section 5	17 Oct 2008	30 Sep 2013
	Section 6	17 Oct 2008	30 Sep 2013
	Section 7	17 Oct 2008	30 Sep 2013
	Section 8	20 May 1994	30 Nov 2015
	Section 9	10 Apr 2003	30 Nov 2015
	Section 10	17 Oct 2008	30 Nov 2015
	Section 11	14 Aug 2003	30 Sep 2013
	Section 12	18 Sep 2009	30 Sep 2013
	Section 13	14 Aug 2003	15 Oct 2014
	Section 14	17 Oct 2008	30 Sep 2013
	Section 15	17 Oct 2008	30 Sep 2013
	Section 16	17 Oct 2008	30 Sep 2013
Section 17	17 Oct 2008	—	
CSP-C-2A	Configuration Supplement A/A-1 (Model 269A and 269A-1)	29 Jan 2010	30 Sep 2013
CSP-C-2B	Configuration Supplement B (Model 269B)	29 Jan 2010	30 Sep 2013
CSP-C-2C	Configuration Supplement C (Model 269C)	29 Jan 2010	30 Sep 2013
CSP-C-2D	Configuration Supplement TH-55A [Model 269A (TH-55A)]	29 Jan 2010	30 Sep 2013
CSP-C-3	Optional Equipment (HMI Appx A)	02 Jun 2006	30 Sep 2013

MODEL 269C HANDBOOK OF MAINTENANCE INSTRUCTIONS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-C-4	Periodic Inspections Overhaul and Retirement Schedule and Weight and Balance Procedures (HMI Appx B)	20 May 1993	30 Nov 2015
CSP-C-5	Component Overhaul (HMI Appendix C)	Listed on Part Column	—
	Part I- Main Transmission	Deleted	
	Part II - High Tip Speed Tail Rotor Transmission	Deleted	
	Part III - Low Tip Speed Tail Rotor Transmission	Deleted	
	Part IV - Main Rotor Blade Dampers	18 Sep 2009	07 Dec 2012
	Part V - Landing Gear Damper	18 Sep 2009	07 Dec 2012
	Part VI - Landing Gear Damper – Poppet Type	30 Jan 1995	30 Nov 2015
	Part VII - LTS Tail Rotor and Pitch Control	17 Mar 2006	30 Sep 2013
CSP-A-3	Corrosion Control Manual (HMI Appx D)	30 Aug 1994	30 Sep 2013

MODEL 269C (1809 & SUBS.) HANDBOOK OF MAINTENANCE INSTRUCTIONS

Publication No.	Title	Issued/Reissued	Latest Revision
CSP-C-10	Basic Handbook of Maintenance Instructions (Basic HMI):	03 Oct 2003	30 Nov 2015
	Section 1	03 Oct 2003	30 Nov 2015
	Section 2	03 Oct 2003	30 Nov 2015
	Section 3	03 Oct 2003	30 Nov 2015
	Section 4	03 Oct 2003	21 May 2010
	Section 5	03 Oct 2003	30 Sep 2013
	Section 6	03 Oct 2003	30 Sep 2013
	Section 7	03 Oct 2003	30 Sep 2013
	Section 8	05 Jan 2007	30 Nov 2015

MODEL 269C (1809 & SUBS.) HANDBOOK OF MAINTENANCE INSTRUCTIONS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
	Section 9	05 Jan 2007	30 Nov 2015
	Section 10	03 Oct 2003	30 Nov 2015
	Section 11	03 Oct 2003	30 Sep 2013
	Section 12	03 Oct 2003	30 Sep 2013
	Section 13	03 Oct 2003	30 Nov 2015
	Section 14	03 Oct 2003	30 Sep 2013
	Section 15	03 Oct 2003	—
	Section 16	03 Oct 2003	30 Sep 2013
	Section 17	03 Oct 2003	07 Dec 2012
CSP-C-11	Optional Equipment (HMI Appx A)	03 Oct 2003	30 Sep 2013
CSP-C-12	Periodic Inspections Overhaul and Retirement Schedule and Weight and Balance Procedures (HMI Appx B)	03 Oct 2003	30 Nov 2015
CSP-C-13	Component Overhaul (HMI Appendix C)	Listed on Part Column	—
	Part I- Main Transmission	Deleted	
	Part II - Tail Rotor Transmission	Deleted	
	Part III - Landing Gear Damper	03 Oct 2003	30 Nov 2015
	Part IV - Tail Rotor and Pitch Control Assembly	03 Oct 2003	30 Sep 2013
CSP-A-3	Corrosion Control Manual (HMI Appx D)	30 Aug 1994	30 Sep 2013

ILLUSTRATED PARTS CATALOGS

CSP-C-7 (V1)	Illustrated Parts Catalog (IPC)	15 Sep 1981	30 Nov 2015
CSP-C-7 (V2)	Illustrated Optional Accessories and Modification Kit Catalog	01 Feb 1978	30 Sep 2013
CSP-C-9	Illustrated Parts Catalog (IPC) (Model 269C, S/N 1166 & Subs)	30 Apr 2004	30 Nov 2015

KITS

Publication No.	Title	Issued/Reissued	Latest Revision
CKP-C-1	SA-269K-001, Heavy Duty Skid Shoe	13 Oct 1989	—
CKP-C-2	SA-269K-002-1 and SA-269K-002-3, Alternator Control Unit Kits	19 Feb 1992	—
CKP-C-3	In process	—	—
CKP-C-4.2	SA-269K-004-1, H-Frame Kit	24 Nov 1992	10 Jul 1997
CKP-C-5.1	SA-269K-005-1 and SA-269K-005-3, Instrument Console Kits	13 Feb 1992	03 Feb 1997
CKP-C-6 thru CKP-C-39	Never Issued	—	—
	SA-269DK-024, T/R Driveshaft Mod Kit	20 Nov 2001	
CKP-C-40	SA-269K-056, Rivet Installation Kit, Tail Rotor Blade Abrasion Strip	31 Aug 1989	27 Oct 1989
CKP-C-41	SA-269K-057-1, Main Rotor Thrust Bearing Kit	09 Jun 1994	—
CKP-C-42	SA-269K-058-1 & SA-269K-058-03, Elastomeric Damper Kits	06 Jan 1993	—
CKP-C-43.1	SA-269K-059-01/-05 & SA-269K-059-3, Engine Overspeed Control Kits	08 Jun 2001	—
CKP-C-44.1	SA-269K-060, Triple Latch Door	04 Mar 1998	—
CKP-C-45	In process	—	
CKP-C-46	Cancelled	—	—
CKP-C-47.1	SA-269K-063-01 & -03, Exhaust Pipe Installation Kit	29 Sep 1994	14 Jul 2000
CKP-C-48.1	SA-269K-064-01, One-Piece Upper Pulley Hub Kit	25 Sep 2001	—
CKP-C-49.1	SA-269K-065-01, Aluminum Canopy Slat Kit	26 Sep 1995	—
CKP-C-50	Canceled		—
CKP-C-51.1	SA-269K-067-01, Main Transmission Electric Chip Detector Kit	19 Dec 1994	05 Jan 2007
CKP-C-52	SA-269K-068-01 & -03, Cabin Door Window Kits	03 Feb 1997	04 Mar 1997

KITS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
CKP-C-53	SA-269K-069-01, Large Capacity Oil Hose Kit	03 Feb 1997	—
CKP-C-54	Canceled		—
CKP-C-55 thru CKP-C-56	In process		—
	SA-269K-072-01, Drive Belt-Tie Bar/Strut Modification Kit	27 Apr 1999	—
CKP-C-57	SA-269K-073-01, Aluminum Canopy Slat V Bracket Kit	10 Aug 1995	—
CKP-C-58	Refer to Model 269C-1 Publications Index		—
CKP-C-59.1	Refer to Model 269C-1 Publications Index	13 Aug 1997	20 Apr 1998
CKP-C-60	SA-269K-076-01, 20596A Primary Oil Cooler/Oil Filter Kit	18 Jul 1996	—
CKP-C-61.2	SA-269K-077-01, Primary Oil Cooler/Oil Filter, Auxiliary Oil Cooler, and Instrument Cluster Kit	15 Jan 1997	03 Aug 1998
CKP-C-62.1	Refer to Model 269C-1 Publications Index	30 Jan 1996	
CKP-C-63.1	SA-269K-079-01 and -03, Field Installation of 269A2320-17 or -15 Tailboom Assemblies in Place of 269A2320-7, -11 or -13 Tailboom Assemblies	03 Apr 1996	08 May 1996
CKP-C-64	Not applicable		
CKP-C-65.1	SA-269K-080-01, 20596A Primary Oil Cooler/Oil Filter Kit (Installed in Conjunction with 269A4551 or 269A4684 Auxiliary Oil Cooler)	15 Jan 1997	28 Jan 1997
	SA-269K-081-01, Field Replacement of 269A8418 Bellcrank Assembly Kit	05 Jul 1996	
CKP-C-66.1	SA-269K-083-01, Over Center Ground Handling Wheels Kit	12 Jul 1996	04 Aug 1997
	SA-269K-082, Tail Rotor Transmission Overhaul Kit	27 Apr 1998	
CKP-C-67	SA-269K-084-01, Over Center Ground Handling Wheels Kit (Robocopter only)	17 Sep 1996	

KITS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
CKP-C-68.1	Refer to Model 269C-1 Publications Index	15 May 1997	
CKP-C-69	SA-269K-086-01, RPM Limiter Testbox Kit	27 Nov 1996	—
CKP-C-70	SA-269K-087-01 & -03, Swashplate Bearing Retainer Kits	18 Dec 1996	—
CKP-C-71	Refer to Model 269C-1 Publications Index	11 Apr 1997	—
CKP-C-72 thru CKP-C-74	In process		—
	SA-269K-089, Fuel System Installation Kit - 65 Gallon Aux System, (S/N 0120-1742 & 1745) Sheet 1 and Sheet 2	24 Jun 1998	25 Jun 1998
	SA-269K-092, Fuel System Installation Kit - 65 Gallon Aux System, (S/N 1743 1744, 1746 & Subs)	11 Aug 1997	
CKP-C-75.1	SA-269K-093-01 & -03, Cabin Heater Kit (Superseded by CKP-C-81)	16 Apr 1999	04 Oct 1999
	SA-269K-094, Knob Installation- Cyclic Pitch Control Stick Assembly Kit	08 Nov 1997	—
	SA-269K-095, Oil Filler Dipstick Installation Kit	11 Mar 1998	—
CKP-C-76	Refer to Model 269C-1 Publications Index	23 Apr 1998	—
CKP-C-77	SA-269K-097, Extended Height Landing Gear Kit	02 Jul 1999	—
CKP-C-78	Installation Instructions for Model 269C Tailboom Modification	12 Mar 1999	—
	SA-269K-098, Switch Installation Kit- Weight-On-Skids	10 Jan 1998	27 Jan 1999
	SA-269K-099, Reversing Trim Installation Kit	18 Aug 1998	—
	SA-269K-100, Tail Rotor-Elastomeric Bearing Kit	25 May 1999	—
	SA-269K-101, Rollover Fuel Vent Installation	08 Aug 2000	16 Aug 2000

KITS (cont)

Publication No.	Title	Issued/Reissued	Latest Revision
	SA-269K-102, Conversion Kit - 100 Amp Skytronics Alternator to 130 Amp Electrosystems Alternator Kit	14 Jul 1999	31 Aug 1999
	SA-269K-104, T/R Control Rod (Spring Loaded) Kit Installation	04 Dec 2000	—
	SA-269K-105, Installation of Splined M/R Driveshaft and Hub	15 Jan 2002	18 Jul 2003
	SA-269K-106, Rear Aft. Cluster Fitting Mod. Kit	13 Mar 2002	12 Sep 2002
	SA-269K-107, Installation of 269A3227 Bushing in Landing Gear Skid Tube	09 May 2002	—
CKP-C-79 thru CKP-C-80	In process		
CKP-C-81.2	SA-269K-093-05 & -07, Cabin Heater Kits	10 Dec 2002	18 Mar 2003
CKP-C-108.1	SA-269K-108, Kit, Fuel Injection Conversion	09 Apr 2003	—
CKP-C-110.2	SA-269K-110-01 & -03, Star System Kits	05 Aug 2003	17 Nov 2003
	SA-269K-111, Installation of 269A5590-15 Cable Sub-Assy.	07 Feb 2003	21 Feb 2003
	SA-269K-112, 269A5483 Spring Assy. - Cable Replacement Installation	04 Aug 2003	—
CKP-C-113.1	SA-269K-113-01, 269A3202-109/-110 Over Center Ground Handling Wheels Kit	05 Nov 2003	12 Sep 2008
	SA-269K-114, Retrofit Installation of 269A5800-1 Spring Assy.	23 Jan 2004	—

MODEL 269A-C COMPONENT MAINTENANCE MANUAL (CCM)

CSP-C-5A	Component Maintenance Manual (CMM)	25 Jan 2013	30 Nov 2015
CSP-C-13A	Component Maintenance Manual (CMM)	25 Jan 2013	30 Nov 2015

- NOTES:**
- a. Refer to Service Information Letter L-147 for explanation of Publications Index.
 - b. Check helicopter aircraft records to ensure that all applicable status † Service Information Notices and Service Bulletins have been accomplished. Obtain copy of document and perform applicable procedure(s) if compliance is not indicated.
 - c. Where conflicts exist between the Publications Index and the document (i.e. Notice or Bulletin), the document shall prevail.
 - d. Red letterhead Service Information Notices and Service Bulletins are mandatory and must be performed on the helicopter models indicated.
-

STATUS NOTATION KEY

- © Indicates document which is current. This document must be maintained as part of the Model 269 Series Service Information Notice, Service Bulletin and Service Letter Set.
- † Indicates outdated Service Information Notice or Service Bulletin outlining one-time procedures. Check helicopter aircraft records for compliance, as applicable.
- k Indicates optional Kit Installation Instructions, available upon request (or when kit is ordered).
- ‡ Indicates optional Maintenance Information, available upon request only.
- ⇒ Indicates that Status is specified under Notes column.
-

MODELS AFFECTED KEY

- N/A Indicates that the document is Not Applicable to the helicopter model indicated.
- X Indicates that the document may be applicable to the helicopter model indicated.
- ALL Indicates that the document is applicable to all serial numbers of the helicopter model indicated.

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-1.4	†	Field Modification - Idler Pulley Assembly P/N 269A5514	15 Sep 71	Red	0011 thru 0415	0004 thru 0034	0001 thru 0224	N/A	AD 71-20-05	Notice available upon request
N-2.1	“	Modification - Fuel Injection Lines, Cylinders No. 1 and 3	2 Aug 66	Red	N/A	0001 Thru 0041	See Note	N/A		269B 0001 thru 0168, 0170 thru 0196, 0199 thru 0201, 0205 thru 0212 and 0214
N-3	‡	Retrofit - Clutch Engagement Spring Assembly Guide	4 May 66	Blue		N/A	0193 thru 0235	N/A		
N-4	†	Modification - Fuel Injection System Bendix RSA-5AB1	4 May 66	Red	0315 and subs	All	All	N/A		
N-5	⇒	Inspection - Belt Drive Transmission Strut P/N 5423	18 May 66	Red	All	All	All	N/A		Incorporated in HMI
N-6	k	Float Kit - Removable Skid Extension	16 Jul 66	Blue	N/A	All	All	N/A		Equipped with floats
N-7	‡	Modification - Engine Fuel Pump Drain Line	18 Jul 66	Blue	0315 thru 0575	0001 Thru 0042	0001 Thru 0273	N/A		
N-8	⇒	Inspection - Belt Drive Idler Pulley Arm P/N 5506	15 Jul 66	Red	All	All	All	N/A		Incorporated in HMI

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-9.2	⇒	Inspection - Possible Retirement, Main Rotor Blade	3 Oct 77	Red	All	All	All	N/A	77-23-08	Incorporated in HMI Notice available upon request
N-10.2	⇒	25 Hour Inspection - Main Rotor Blade	7 Aug 72	Red	0011 and subs	0001 thru 0041	0001 and subs	N/A	64-28-02	Incorporated in HMI Appendix B - Notice available upon request
N-11.1	k	Field Replacement - Auxiliary Fuel Boost Pump	29 Nov 68	Blue	0011 thru 0575	0001 thru 0041	0001 thru 0268	N/A		
N-12	†	Field Modification - Belt Drive Idler Pulley Clutch Shaft P/N 5456	1 Sep 66	Red	0011 thru 0667	0001 thru 0041	0001 thru 0273	N/A		
N-13	‡	Field Modification - Engine Cooling Scroll	29 Sep 66	Blue	0315 and subs	N/A	N/A	N/A		
N-14	k	Modification - Throttle Bellcrank and Control Cover Clearance	27 Jun 67	Red	See Note	N/A	N/A	N/A		Refer to Models Affected for Serial Numbers Affected
N-15	k	Field Installation - Chip Detector Engine and Transmission	4 Nov 66	Blue	0315 thru 500	N/A	N/A	N/A		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-16.1	k	Field Modification - Tail Rotor Assembly	27 Sep 67	Blue	All	All	All	N/A		
N-17	‡	Field Modification - Fuel Injector System Rosette Fitting	17 Nov 66	Red	0315 thru 0667	0001 thru 0018	0123 thru 0173	N/A		
N-18	⇒	Tape Application Area – Tail Rotor Blades	1 Dec 66	Red	All	All	All	N/A	Incorporated in HMI	
N-19	k	Field Modification – Induction System Air Filter Housing P/N 8143	2 Dec 66	Blue	0011 thru 0632	0001 and subs	0001 thru 0246 and 0249	N/A		
N-20	k	Field Installation - Spring Longitudinal Bungee	20 Feb 67	Blue	0011 and subs	0001 thru 0041	N/A	N/A		
N-21	⇒	Bellcrank Installation Servo Fuel Injector Throttle Control	23 Aug 67	Blue	0315 thru 0667	N/A	N/A	N/A	Incorporated in HMI	
N-22	‡	Reverse Installation - Collective Bungee Assembly	22 Feb 67	Blue	All	All	All	N/A		
N-23	⇒	Field Replacement - Main Rotor Drive Shaft	20 Feb 67	Blue	0315 and subs	N/A	N/A	N/A	Incorporated in HMI	

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-24	⇒	Main Rotor Blades, P/N 269B1145 Single Configuration, Painted	19 Sep 67	Red	All	All	All	N/A		Incorporated in HMI
N-25	‡	Bracket Installation – Scroll Assembly	1 Nov 67	Blue	See Note	See Note	See Note	N/A		
N-26	k	Kit Installation - Low Tip Speed Tail Rotor Assembly	22 Aug 67	Blue	X	All	All	N/A		
N-27	k	Kit Installation - Exhaust Heater Support	22 Feb 67	Blue	All	All		N/A		
N-28	†	Removal AN960-416L Washers, Engine Cooling Shroud Side Panel Assemblies	1 Apr 67	Blue	All	All	N/A	N/A		
N-29.1	⇒	Inspection and Field Modification - Main Rotor Gear Drive Assembly P/N 269A5175	24 Jul 67	Red	All	All	All	N/A	67-11-03	Notice available upon request – Superseded by N-114.3
N-29 Addendum X1	⇒	Inspection and Field Modification - Main Rotor Gear Drive Assembly	6 Apr 67	Red	All	All	All	N/A		
N-30	†	Exhaust Manifold Assembly – Field Modification to Accommodate New Exhaust Adapter Flange	8 Nov 67	Red	All	All	All	N/A		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-31.1	k	Field Installation and Modification - Dual Bolt Tail Skid Mounting Hardware	23 Apr 73	Blue	All	All	All	N/A		
N-32	‡	Rerouting - Alternator Wiring Ties	1 Apr 67	Blue	All	All	All	N/A		
N-33.2	†	Kit Installation - Cabin Sealing RE: Carbon Monoxide Ingestion	13 Dec 67	Red	0011 thru 0713	0001 thru 0041	0001 thru 029	N/A	67-21-01	Notice available upon request
N-34	†	Locknut Installation – Center Collective Pitch Stick Assembly P/N 269A9962 (Dual Control)	7 Aug 67	Red	N/A	N/A	0001 thru 0223	N/A		
N-35	⇒	Inspection - P/N 269A5513 Bumper Plug, Lower Coupling Drive Shaft	26 Jul 67	Red	All	All	All	N/A		Incorporated in HMI
N-36	⇒	Inspection - Tail Rotor Drive Shaft, Excessive End Play	26 Jul 67	Red	All	All	All	N/A		Incorporated in HMI
N-37.2	†	Retirement – Bellcrank Assembly, Lateral Pitch Mixer Idler P/N 269A7506	10 Mar 69	Red	0011 thru 1033	0001 thru 0041	0001 thru 0398	N/A	70-01-06	AD related to Notice, but Notice in not directly mentioned in AD
N-38	⇒	Inspection - Cable, Belt Drive Clutch Control	27 Feb 68	Red	All	All	All	N/A		Incorporated in HMI
N-39.2	†	Installation - Stiffener, Canopy Slat	14 Aug 68	Red	All	All	All	N/A		Limited to 269A2297 Canopy Slat Assembly

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-40	⇒	Tail Rotor Repair - Erosion, Blade Leading Edge	15 Mar 68	Blue	0315 and subs	N/A	N/A	N/A	Incorporated in HMI	
N-41	†	AC Engine Mounted Full – Flow Oil Filter – Installation	15 Mar 68	Blue	See Note	See Note	See Note	N/A	All 269 Series Helicopters with Lycoming O-360 or HIO-360 Aircraft Engine Installed	
N-42	‡	Installation - Jumper Wires	15 Mar 68	Blue	0315 thru 0713	N/A	N/A	N/A		
N-43	‡	Retrofit - Dual Clutch Spring Attachment Fitting PN 269A5436-13 and 269A5436-19	28 Mar 68	Red	0011 thru 0713	0001 thru 0041	0001 thru 0333	N/A		
N-43 Addendum X1	‡	Retrofit or Inspection - Dual-Strap Clutch Spring Attachment Fitting PN 269A5436-5 and 269A5436-7	23 Apr 68	Red	0452 thru 0713	N/A	N/A	N/A		
N-44	k	Kit Installation - Utility Lights	29 Mar 68	Blue	0714 thru 0773	N/A	N/A	N/A		
N-45	k	Rework Electrical Components Radio Noise Level Control	29 Mar 68	Blue	0714 thru 0782	N/A	N/A	N/A		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-46	⇒	Inspection - Main Rotor Blade Flapping Hinge Bearing	18 Apr 68	Red	0315 and subs	N/A	N/A	N/A		Incorporated in HMI
N-47	⇒	Inspection - Main Rotor Blade Flapping Hinge Bearings	18 Apr 68	Red	All	All	All	N/A	64-28-02	Incorporated in HMI Notice available upon request
N-48	k	Retrofit Kit - Alternate Battery Location	2 May 68	Blue	N/A	N/A	All	N/A		
N-49	‡	Shim Installation - Bearing, Upper Pulley Assembly	8 May 68	Blue	All	All	All	N/A		
N-50	k	Retrofit - Throttle, Governor Control System	8 May 68	Blue	0337 thru 0667	N/A	N/A	N/A		
N-51	k	Kit Installation – Alternator Mounting Assembly - M10024	5 Jun 68	Blue	0315 and subs	0040 and 0041	0001 and subs	N/A		
N-52.1	†	Rework - Tail Rotor Pedal Arms PN 269A7336-5	12 Nov 68	Red	All	All		N/A		All 269 Series Helicopters Equipped with 269A7336-5 Pedal Arm and 269A7333-3 Rubber Pedal Support Tube.
N-53	⇒	Inspection - Tail Boom Center Attachment Fitting PN 269A2324	24 Jun 68	Red	All	All	All	N/A		Incorporated in HMI

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-54	k	Dashpot Installation – Throttle Control Modification Kit M10040	26 Jul 68	Blue	0315 and subs	N/A	N/A	N/A		
N-55.1	†	Inspection - Engine Lower Coupling Drive Shaft (PN 269A5504-3) or Engine Lower Coupling Drive Shaft Assembly PN 269A5504-5 or 80-269A5504-5	9 Dec 68	Red	0011 thru 0893	0001 thru 0041	0001 thru 0359	N/A	68-26-01	Does not Include 269A Military THY-55A Helicopters which have Magnetic Particle Inspection Notice available upon request
N-56.4	⇒	Inspection - Main Rotor Mast	06 May 81	Red	All	All	All	All		Incorporated in HMI
N-57	k	Support Clamp Installation - PN 269A4869 Exhaust Heater Kit	11 Sep 68	Blue	N/A	N/A	See Note	N/A		All Model 269B Helicopters with 269A4869 Exhaust Heater Kit Installed
N-58	⇒	Inspection - Tail Rotor Blade Assembly PN 269A6124	12 Sep 68	Red	All	All	All	N/A		Incorporated in HMI
N-59	©	Inspection and Retirement, Main Rotor Thrust Bearing PN 269A5050-50 and -51. Inspection, Field Modification - Main Rotor Mast, Thrust Bearing Nut and Spacer Tube	9 Oct 68	Red	0011 thru 0979	0001 thru 0041	0001 thru 0370	N/A	97-05-06	See L-162

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-60.1	k	Balance Weight Assembly Installation - Low Tip Speed Tail Rotor	20 Feb 69	Blue	All	All	N/A	N/A	Limited to Helicopters Equipped with 269A6034 Series (LTS) tail rotor Assy.	
N-61	†	Inspection - Tail Rotor Fork Bolts PN 269A6235	30 Oct 68	Red	All	All		N/A	Limited to Helicopters Equipped with 269A6003 or 269A6004 Series (HTS) tail rotor Assy.	
N-62.1	k	Kit - Floor Beam Reinforcement	4 Aug 71	Blue	0011 thru 0884	0001 thru 0041	0001 thru 0471	N/A		
N-63	‡	Inspection - Tail Rotor Drive Shaft Damper Bearing Block PN 269A5722 and 269A5722-3	8 Nov 68	Red	0796 thru 0993	N/A	See Note	N/A	Refer to Models Affected for Serial Numbers Affected	
N-64.1	⇒	Inspection and Installation - Belt Drive Upper Pulley Assembly	20 Jun 72	Blue	All	All	All	All	Incorporated in HMI	
N-65	k	Kit Modification - Air Intake Assembly Re: Amphibious Float Landing Installation	15 Nov 68	Red	0011 thru 0314	N/A	N/A	N/A	Limited to Helicopters Equipped with Floatation Gear	
N-66	⇒	Blade Weight Installation – PN 269B1145 Series Main Rotor Blades	10 Dec 68	Blue	See Note	See Note	See Note	N/A	(Refer to Models Affected) Incorporated in HMI	

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-67	†	Inspection Main Rotor Swashplate Scissor Link Assemblies PN 269A1335 and 269A1336	21 Feb 69	Red	All	All	All	N/A		
N-68	‡	Control Covers - Bonding, Upper and Lower	10 Mar 69	Red	N/A	N/A	0001 thru 0454	N/A		
N-69	⇒	Inspection, Corrosion Damage - Main Rotor Drive Shaft PN 269A5305-3	8 Oct 69	Red	All	All	All	N/A	Incorporated in HMI	
N-70	‡	Installation - Improved Fuel Injector Assembly	8 Oct 69	Blue	0315 and subs	N/A	N/A	N/A		
N-71.1	†	Inspection - Tail Rotor Transmission Assembly PN 269A6027 or 369A5400	6 Oct 69	Red	All	All	All	All	69-21-01	Notice available upon request
N-71.1 Addendum X1	†	Inspection - Tail Rotor Transmission Assembly PN 269A6027 or 369A5400	27 Oct 69	Red	All	All	All	All	69-21-01	Notice available upon request
N-72	⇒	Periodic and conditional Inspection - Main Rotor Mast Assembly PN 269A2020	17 Oct 69	Red	All	All	All	All		Incorporated in HMI
N-73.1	‡	Inspection - Idler Pulley Assembly, Axial Play	24 Mar 70	Red	All	All	All	All		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-74.1	⇒	Inspection - Main Rotor Mast Internal Corrosion	16 Feb 72	Red	All	All	All	All		Incorporated in HMI
N-75.2	‡	Inspection - Main Rotor Lead-Lag and Flapping Hinge Bolts PN HS1446-10-68	14 Apr 70	Red	All	All	All	N/A	70-08-01	Notice available upon request
N-76.2	k	Kit Installation - Main Rotor Thrust Bearing M10044	22 Mar 71		0011 thru 1109	0001 thru 0041	0001 thru 0444	N/A		See CKP-C-41 See L-162 Ref AD 97-05-06
N-77.1	k	Installation - Belt Drive Clutch Cable Guard Kit M10041	14 Feb 72	Blue	0315 and subs	N/A	0001 and subs	0001 and subs		
N-78	‡	Inspection - PN HS1446-10-68 Bolt, Lead Lag and Flapping Hinge	31 Jul 70	Red	All	All	All	All	70-17-03	Notice available upon request
N-79	⇒	Relocation - Oil Pressure Sender PN 5654912 and Fuel Pressure Sender PN 5654913	4 Sep 70	Blue	0011 thru 1109	N/A	0001 thru 0460	0001 thru 0016		Incorporated in HMI
N-80.2	k	Static Source Relocation - Modification Kit NO. M10059-5	1 May 72	Blue	N/A	N/A	N/A	0001 thru 0139		
N-81	†	Modification - King KY-90A or KY-95 Transceiver Installation	9 Nov 70	Blue	0011 thru 0314	0001 thru 0041	0001 and subs	0001 thru 0078		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-82.3	©	Inspection - Tailboom Center Attachment Fitting P/N 269A2324 and Center Frame Aft Cluster Fitting P/N 269A2234 and 269A2235	19 Sep 77	Red	All	All	All	0004 thru 0569	76-18-01	
N-83	k	Installation - Exhaust Heater Modification Kit NO. M10065-1	27 Jan 71	Blue	0315 and subs	N/A	N/A	N/A		
N-84	k	Retrofit Kit - Alternate Battery Location	25 Feb 71	Blue	N/A	N/A	N/A	0001 thru 0079		Model 269C equipped with muffler 269A8801
N-85.3	†	Installation - Adapter-Mounted Idler Pulley Clutch Assembly Kit, PN 269A5447	18 Jun 76	Red	0011 thru 1109	0001 thru 0041	0001 thru 0472	0001 thru 0149		
N-86	k	Desensitized Throttle Modification Kit NO. M10061	26 Feb 71	Blue	0011 and subs	N/A	N/A	N/A		
N-87.2	©	Installation - Pitch Control Links, Low-Tip Speed Rotor Assembly (Kit NO. M10067)	25 Mar 75	Red	0011 thru 1109	0001 thru 0041	0001 thru 0457	0004 thru 0083		
N-88.1	⇒	100 Hour Inspection – Engine Exhaust System	10 Nov 71	Red	0011 thru 0314	0004 thru 0041	0001 and subs	0001 and subs		Incorporated in HMI

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-89	⇒	Installation - Mounting Brackets Dual Head Alternator	16 Apr 71	Blue	N/A	N/A	X	X		Incorporated in HMI
N-90.1	©	Replacement - Idler Pulley Bearing P/N 269A5050-62	7 Sep 71	Red	N/A	N/A	N/A	0004 thru 0092	AD 73-11-01	
N-91	k	Main Rotor Transmission Modification Kit NO. M10062	9 Jun 71	Blue	0315 and subs	N/A	N/A	N/A		
N-92	k	Relocation - Warning Indicator Light, Searchlight Control Handle	6 Jul 71	Red	X	X	X	X		Helicopters Equipped with P/N 269A4333 Manually Operated Searchlight Kit (Extendable Type)
N-93	†	Inspection - Main Rotor Hub and Shaft Assemblies P/N 269A5305 and /-9	19 Jul 71	Red	0011 and subs	0001 thru 004	0001 thru 0457	0001 thru 0100		
N-94	‡	Runout (TIR) Inspection – Main Rotor Thrust Bearing P/N 269A5050-73	26 Jul 71	Red	0011 thru 1109	0001 thru 0444	0001 thru 0444	N/A		Applicability Limited to Helicopters having 269A5050-73 M/R Thrust Bearings Installed per N-76.2
N-94 Addendum X1	‡	Runout (TIR) Inspection – Main Rotor Thrust Bearing P/N 269A5050-73	8 Oct 71	Red	0011 thru 1109	0001 thru 0444	0001 thru 0444	N/A		Applicability Limited to Helicopters having 269A5050-73 M/R Thrust Bearings Installed per N-76.2

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-95		200-Hour Periodic Replacement Idler Pulley Bearings	15 Sep 71	Red	0011 and subs	0001 and subs	0001 and subs	N/A	AD 71-20-05	Incorporated in HMI
N-96	†	Modification - Center Back Cushion Assembly P/N 269A4042	8 Oct 71	N/A	N/A	N/A	N/A	0004 thru 0050		
N-97	†	Modification - Cyclic Pitch Control Installation	8 Oct 71	Red	N/A	N/A	N/A	0001 thru 0091		
N-98	†	Inspection - Tail Rotor Control Stop P/N 269A7326	29 Nov 71	Red	0011 and subs	N/A	0001 thru 0457	0001 thru 0104		
N-99	†	Inspection - Latch, Belt Drive Clutch Handle, P/N 269A2210	15 Dec 71	Red	0011 thru 0314	0001 thru 0041	N/A	N/A		
N-100	⇒	Repair of Tail Rotor Blades, P/N 269A6035 Series	21 Dec 71	Red	ALL	ALL	ALL	ALL		Incorporated in HMI
N-101	‡	Shim Installation - Tail Rotor Hub at Fork (Teeter) Bearings; Replacement - Tail Rotor Fork Bearings	27 Mar 72	Blue	X	X	X	X		Helicopters Equipped with P/N 269A6034 (LTS) Tail Rotor Assembly.

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-102	‡	Inspection - Landing Gear Damper (poppet type) Assembly P/N 269A3150	23 Oct 72	Red	N/A	N/A	N/A	See Note	269C Helicopters Serial No. 0001 thru 0113, 0116 thru 0118, 0120 thru 0149.	
N-103	k	University Sound System Kit Installation P/N 269A4190-1/ -3 Modification of MA-500 Amplifier	14 Nov 72	Blue	N/A	N/A	See Note	See Note	Applicability Limited to Helicopters Equipped with University Sound and Siren System (24/28 vdc).	
N-104	‡	Manually Operated Searchlight Installation P/N 269A4333 Series Wire Replacement Alternator Switch to Circuit Breaker	26 Feb 73	Red	N/A	N/A	N/A	See Note	269C Helicopters Equipped with 269A4333 Dual Searchlight Kit.	
N-105	⇒	Inspection - Belt Drive Idler Pulley Clutch Assembly PN 269A5447 and 269A5447-3	7 Mar 73	Red	0011 thru 1109	0001 thru 0041	0001 thru 0472	0004 thru 0149	Superseded by N-107	
N-106	‡	Rework - Flotation Gear Installation Kit NO. 269A4300-15	17 Mar 73	Red	N/A	N/A	N/A	See Note	269C Helicopters Equipped with Flotation Gear Configuration.	
N-107	‡	Modification and Inspection Belt Drive Idler Pulley Clutch Assembly P/N 269A5447 and 269A5447-3	6 Apr 73	Red	0011 thru 1109	0001 thru 0041	0001 thru 0472	0004 thru 0189	269C Helicopters equipped with 269A5447-3 Belt Drive Idler Pulley Clutch Assembly	

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-108	‡	Serialization - Tailboom Support Assembly P/N 269A2015-5	21 May 73	Red	N/A	N/A	N/A	See Note	76-18-01, 2001-25-52, 2003-13-15R-1	269C Helicopters Serial No. 0004 thru 0141, 0143 thru 0188 Notice available upon request
N-109.2	©	Inspection of Tailboom Support Strut Aluminum End Fitting P/N 269A2016-3 and -5; Replacement of Aluminum End Fittings with Stainless Steel End Fittings (Modification Kit NO. M10070)	1 Sep 76	Red	0011 thru 1109	0001 thru 0041	0001 thru 0462	0004 thru 0219	76-18-01, 2001-25-52, 2003-13-15R-1	
N-110	k	Configuration Modification - 2050 LB Gross Weight Conversion Kit NO. M10078	24 Sep 73	Blue	N/A	N/A	N/A	0004 thru 0209		
N-111.3	k	Conversion of 12V to 24V Electrical System - Modification Kit NO. M10068-1 and Installation of 24V, 100-Ampere Capacity Alternator - Kit NO. 269A4929-1	24 Jan 86	Blue	N/A	N/A	N/A	0004 and subs		
N-112.1	‡	Wiring Modification – Auxiliary Fuel Pump P/N 269A8311-1 and 269A8303-5	26 Apr 76	Blue	0315 thru 1110	N/A	N/A	0004 thru 0487		
N-113	⇒	Grease Quantity Requirements - Belt Drive Transmission Lower Pulley Bearing P/N 269A505-57	3 Mar 74	Red	All	All	All	X		Incorporated in HMI

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-114.3	⇒	Inspection and Modification - P/N 269A5179 Drive Shaft and Coupling Assembly, Main Rotor Gear Drive Assembly P/N 269A5175 Basic, -3, or -5	19 Sep 77	Red	X	X	X	X	81-17-04	Superseded by N-179.1 Notice available upon request
N-115.1	‡	Rework of Engine Mounting Hangar Assemblies P/N 269A8617 and 269A8618 to Eliminate Possible Engine Crankcase to Hangar Assembly Interference	3 Oct 75	Blue	All	All	All	0001 thru 0264		
N-116	⇒	Replacement - Plug P/N 269A5157 with Cork P/N 23425-166 in Main Gear Box Pinion Assembly of Main Rotor Gear Drive Assemblies P/N 269A5125-1, -3, and -5	25 Mar 74	Red	All	All	All	All		Superseded by N-128
N-117.2	‡	Dual RPM and Quiet Operation Configuration P/N 269A4957-3	11 Jul 77	Blue	N/A	N/A	N/A	0004 and subs		
N-118	⇒	Corrosion Prevention/Inspection Main Rotor Blade, P/N 269A1165 Blade Tip Weight Area and Tip Cap	20 May 74	Blue	N/A	N/A	N/A	See Note		Incorporated in HMI

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-119	⇒	Inspection - Replacement Main Rotor Blade Root Fitting Bolts; Main Rotor Blade Damper Bolts	23 May 74	Red	X	X	X	N/A		Incorporated in HMI
N-120	k	Wiring Modification – Integrated Dual Communication Console (ATI)	29 Jul 74	Red	N/A	N/A	N/A	0190 and subs		269C Helicopters Equipped with Police Pac.
N-121.2	©	Inspection and Rework – Tail Rotor Control System, Rudder Pedal Installation	10 Apr 2003	Red	See Note	See Note	See Note	See Note	78-02-02	Refer to Models Affected Section for Serial Numbers
N-122	†	Inspection - Impeller Bolt Installation	4 Dec 74	Red	0011 and subs	0001 thru 0041	0001 and subs	0004 thru 0389		
N-123	‡	Inspection and Rework of Main Transmission Strut Assembly P/N 269A5015	4 Dec 74	Red	N/A	N/A	N/A	See Note		269C Helicopter Serial No. 0273 thru 0288, 0290 thru 0304, 0306 thru 0310, 0312, 0315, 0316, 0320 thru 0322
N-124.1	‡	Inspection - Main Rotor Mast; Left and Right Mast Support Tubes; and Replacement of all Attaching Hardware	3 Oct 75	Red	0011 and subs	0004 thru 0041	0001 and subs	0004 thru 033		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-125	k	Static System - Line Restrictor and Drain Fitting Modification Kit P/N M10094 and M10094-3	2 Jan 75	Blue	N/A	N/A	N/A	0001 thru 0389		
N-126	†	Inspection/Replacement Clutch Actuator Retaining Screws	24 Feb 75	Red	All	All	All	See Note	75-08-12	269C Helicopter Serial No. 0001 thru 0288, 290 thru 0329, 0331 thru 0341, 0343 thru 0363, 0365 thru 0371, and 0373. Notice available upon request
N-127	‡	Reinforcement and Field Repair Canopy Slat P/N 269A2297 or 269A2297-7	5 Mar 75	Red	All	All	All	0001 thru 0390	74-21-04	Notice available upon request
N-128	‡	Replacement of Plug P/N 23425-166 in Pinion Assembly P/N 269A5103 and -9 in Main Rotor Gear Drive Assemblies P/N 269A5175, -3, and -5 with Modification Kit P/N M10104; Securing of P/N 269A5050-1 or -20 Roller Bearing	25 Mar 75	Red	All	All	All	All		
N-129	k	Inspection/Replacement Searchlight Mount Bolts	31 Mar 75	Red	N/A	All	All	All		Helicopters Equipped with 269A4333-27, -29, or 269A4335 Searchlight.

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-130	‡	Inspection - Fiberglass Tail Rotor Blades P/N 269A6124, -9, 269A6035, -9, -17, -19, -M, 269ASK15, and 269-6100	28 Aug 75	Red	All	All	All	All	79-23-03RI	Tail Rotor Blades Serial No.'s Affected are Listed on Last Page of N-130 Notice available upon request
N-131	‡	Inspection and Possible Replacement - Throttle Gear P/N 269A7223; Pilot and Copilot's Collective Pitch Sticks	11 Aug 75	Red	All	All	All	N/A	75-15-02	AD related to Notice, but Notice is not directly mentioned in AD
N-132	⇒	Inspection - Horizontal Stabilizer Forward Boom Attach Fitting P/N 269A2518-3	7 Nov 75	Red	N/A	N/A	N/A	All		Incorporated in HMI
N-133	⇒	Installation of Engine Exhaust Seals P/N 269A8255	7 Nov 75	Blue	0011 thru 1109	0001 thru 0041	0001 and subs	0003 thru 0209		Incorporated in HMI
N-134.3	⇒	Revised Engine Operating Procedures and Maintenance Practices	3 Jul 89	Red	N/A	N/A	N/A	All		Incorporated in Flight Manual
N-135	‡	Field Modification and Repair - Manually Operated Searchlight Installation P/N 269A4333-27, -29, -39 and 269A4335-1	23 Jan 76	Red	N/A	N/A	All	All		269B and 269C Helicopters Equipped with Subject Searchlights

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-136	‡	Longitudinal Cyclic Trim Assembly - Installation of Limit Switch	1 Mar 76	Blue	0315 thru 0339	N/A	N/A	0004 thru 0409		269C Helicopter Applicable Only if M10068-1 Electrical Conversion Kit Installed
N-137.1	k	Wire Modification - Wet/dry AG Kit P/N 269A4153, -3, or -5	18 Jun 76	Red	All	All	All	All		Limited to Helicopters Equipped with Subject Wet/Dry Ag Kit
N-138	†	Inspection - Lateral cyclic Trim Control Assembly P/N 269A7316-3, -5, -7, -9, or -11	30 Apr 76	Red	X	X	X	X	76-10-02	Limited to Helicopters Equipped with Subject Control Assembly Notice available upon request
N-139	‡	Modification - Left Hand Front Engine Cooling Shroud Panel Assembly P/N 269A8508-15 or -25 and Engine Mounting Bolt Installation	20 May 76	Blue	N/A	N/A	0124 and subs	0001 thru 0408		Limited to Helicopters Equipped with Subject Panel Assembly
N-140	‡	Field Modification – Fuselage Frame Assembly	1 Sep 76	Blue	All	All	All	0004 thru 0539		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-141.1	‡	Field Modification and Interim Inspections - Belt Drive Clutch Linear Actuator Assembly	8 Mar 77	Red	0315 thru 1109	0001 thru 0041	0001 and subs	0004 thru 0569	77-07-01	Helicopters with 24-volt Electrical System and Equipped with 269A4564-5 Clutch Actuator Assembly are not Affected by this Notice. Notice available upon request
N-142.1	©	Initial Installation of P/N 269A5194 Main Rotor Drive Ring Gear Carrier Assembly; Modification of P/N 269A5182 Main Gear Drive Upper Housing Assembly	31 May 77	Red	All	All	All	All	81-17-04	
N-143	⇒	Periodic Inspection - P/N 269A5179-3 Drive Shaft and Coupling Assembly, Main Rotor Gear Drive Assembly P/N 269A5175, -3, or -5	31 May 77	Red	All	All	All	N/A		Incorporated in HMI
N-144	†	Inspection - Throttle Control Cable Assembly	8 Aug 77	Red	0011 and subs	0001 thru 0041	0001 and subs	See Note		Serial Numbers 0004 thru 0538; 0542 thru 0544; 0547 thru 0552
N-145	‡	Replacement of P/N 269A8244 or -7 Tailboom Clamp Assembly for Muffler/Resonator Kit P/N 269A8245 or -3	11 Jul 77	Blue	N/A	N/A	N/A	See Note		269C Helicopters Equipped with Muffler/Resonator Kit

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-146.2	‡	Belt Drive Transmission Assembly Inspection of Lower Pulley Bearings and Shimming of Lower Pulley Bearing Straps; Periodic Torque Checks of Forward Bearing Retaining Nut	7 Dec 79	Red	0011 thru 1109	0001 thru 0041	0001 thru 0462	0004 thru 0589	94-12-06	Notice available upon request
N-147.4	†	Relocation of Starter Vibrator Circuit Wiring	23 Feb 82	Red	0315 and subs	N/A	0001 and subs	0001 thru 1119		
N-148		Inspection of Sump Cap Attach Hardware - Main and Auxiliary Fuel tank Assemblies	19 Sep 77	Red	All	All	All	All		
N-149	†	Installation of Placard P/N 269A4646-191 "Declutched Operation Prohibited Above 1600 RPM"	28 Dec 77	Red	0315 thru 1109	0001 thru 0041	0001 thru 0458	0004 thru 0066		
N-150	†	Inspection and Possible Replacement Seat Belt and Shoulder Harness Assembly, P/N 269A4345 (American Safety Flight Systems P/N 500987-401)	15 Jul 78	Red	N/A	N/A	N/A	See Note		269C Helicopters delivered prior to 1 June 1977.
N-151.2	‡	Inspection - Main Transmission Pinion Assembly P/N 269A5103-9	7 Nov 78	Red	All	All	All	See Note	78-25-04	269C Helicopters See Models Affedted Section Notice available upon request
N-152		No Record								

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-153.1	‡	Inspection and Rework of LTS Tail Rotor Hub P/N 369A1725, -5, and -501	28 Oct 81	Red	All	All	All	0004 thru 0716	78-26-04	Limited to Helicopters Equipped with 269A6034 Series (LTS) Tail Rotor Assembly. Notice available upon request
N-154	‡	Field Modification of New Four Bolt Attachment Configuration - Tail Skid Tube, Tailboom Adapter and Transmission Housing	25 Sep 78	Blue	All	All	All	0004 thru 0687		
N-155.2	†	Replacement of P/N 269A6092 or 369A1602 Tail Rotor Drive Fork Hinge Bolt and P/N 269A6093 or 369A1603 Nut; New Assembly Procedure for Tail Rotor Hub and Drive Fork Unit; Periodic Check of Flapping Hinge Bolt Preload	20 Jan 81	Red	All	All	All	0004 thru 0750		Incorporated in HMI
N-156	⇒	Field Repair or Removal – Trim Tab Main Rotor Blade P/N 269A1160 Series, 269A1185 Series, 269A1190 Series, and 269B1145 Series	15 Feb 79	Blue	All	All	All	All		Incorporated in HMI
N-157	‡	Replacement of Radio Transmit/Intercom trigger Switch; Rework of Cyclic	10 May 79	Blue	All	All	All	0004 thru 0739		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-158	⇒	P/N 269A4564-5 Clutch Linear Actuator Assembly - Installation of Drain Hole in Actuator Cover	20 Jul 79	Blue	All	All	All	All		Incorporated in HMI
N-159.1	‡	Field Installation of P/N 269A5160 Anti-Fretting Liner for P/N 269A5179-3 Drive Shaft and Coupling Assembly and P/N 269A5194 Ring Gear Carrier Assembly	18 Dec 79	Blue	All	All	All	All		Incorporated in HMI Appendix C
N-160.1	©	Rework of Main Rotor Mast Assembly for Improved Corrosion Protection	12 Aug 81	Red	All	All	All	All		
N-161	⇒	100-Ampere Capacity Alternator Installation - Torque Inspection of Pivot Bolts P/N AN7-12 and NAS1306-21	28 Sep 79	Red	All	All	All	All		Incorporated in HMI
N-162	‡	Inspection of Tail Rotor Blade Assembly P/N 269A6035-21 and -23	12 Oct 79	Red	All	All	All	All	79-23-03R1	Notice available upon request

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-163	†	P/N 269A6050 Series and 369A1800-3 - Tail Rotor Pitch Control Assembly - Seating of Bearing Inner Race; Torque Increase for P/N 269A6258 Locknut	26 Nov 79	Red	All	All	All	0004 thru 0789		
N-164	†	Inspection of P/N 269A5573-11 H-Frame Assembly	7 Dec 79	Red	X	X	X	X	94-12-06	Incorporated in HMI Notice available upon request
N-165.1	⇒	Inspection of Tailboom and Center Support (saddle) Fitting Assemblies	9 Apr 82	Red	All	All	All	All	80-05-05	Superseded by B-238/B-239 and AD 93-21-03
N-166	†	Replacement of Seat Belt Assemblies having Fabric to Metal Latching Devices	17 Mar 80	Red	All	All	All	N/A		Applicability Limited to Helicopters Equipped with P/N 269A4580, 269A4699 and 269A4881 Seat Belt Assemblies.
N-167	†	Identification and Possible Rework of Seat Belt and Shoulder Harness Assemblies	11 Jul 80	Red	All	All	All	See Note		269C Helicopters delivered prior to 19 May 1980
N-168	†	Rework of Pilot's Seat Cushion Assembly P/N 269A4039	18 Jul 80	Red	N/A	N/A	N/A	0003 thru 0959		
N-169.1	k	Alternator Out Indicating Light	28 Feb 86	Blue	All	All	All	All		

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-170	⇒	Inspection of Main Transmission Assembly P/N 269A5175-7 and -9	18 Aug 80	Red	All	All	All	All		Superseded by N-216
N-171	⇒	Periodic Check of Main Rotor Blade Elastomeric Damper Assemblies P/N 269A1290-1	31 Dec 80	Red	All	All	All	All		Incorporated in HMI
N-172	‡	Installation of Transmission Chips Warning Light for P/N 269A6027 Tail Rotor Transmission Assembly	12 Sep 80	Blue	N/A	N/A	N/A	0004 thru 0949		
N-173	⇒	Sealing of Interfaces of Abrasion Strip and Main Rotor Blade Skin	30 Jan 81	Red	All	All	All	All		Incorporated in HMI
N-174	†	Inspection of P/N 269A5050-73 Thrust Bearing; MRC P/N 9210-UPZ-2 S/N 539 thru 647	23 Feb 81	Red	All	All	All	N/A		
N-175.1	©	Installation of P/N 269A5593-3 H-Frame with P/N 269A5050-78 Bearing	9 Apr 87	Blue	All	All	All	0001 thru 0849		
N-176.2	⇒	Installation of Main Rotor Blade Elastomeric Damper Assemblies P/N 269A1290-1	25 Mar 87	Blue	0011 thru 1109	0001 thru 0041	0001 thru 0462	0004 thru 1019		Incorporated in HMI

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes	
					269A TH-55A	269A-1	269B	269C			
N-177	⇒	Field Inspection and Repair of Tail Rotor Transmission Main Housing Assembly P/N 369A5401	15 Apr 81	Red	All	All	All	N/A		Incorporated in HMI	
N-178.1	†	Instrument Cluster 3-Pack Conversion - AC to Rochester (28 volt)	19 Apr 82	Red	0315 thru 1110	0019 thru 0041	0001 thru 0463	0001 thru 0949			
N-179.1	©	Inspection and Retirement - P/N 269A5179 and -3 Drive Shaft and Coupling Assembly, Main Rotor Gear Drive Assembly P/N 269A5175 Basic, -3 or, -5	17 Aug 82	Red	All	All	All	All, Equipped with 269A5175 BSC, -3 or -5	81-17-04		
N-180	k	Engine Throttle Governor Kit Installation P/N 269A4995-301	18 Jan 82	Blue	N/A	N/A	N/A	0004 and subs			
N-181	†	Inspection, Replacement and New Torque Requirement - P/N 269A5104 Main Transmission Ring Gear, P/N 269A5194 Ring Gear Carrier Assembly and Attach Hardware	9 Apr 82	Red	All	All	All	0001 thru 1074	82-15-01RI	Notice available upon request	
N-182	©	Periodic Inspection of Idler Pulley Support Bracket Assembly P/N 269A5575 and -3	26 May 82	Red	All	All	All	All	82-15-03	Incorporated in HMI Appendix B	

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-183.3	©	Pilot Preflight Check of Tail Rotor Blade (TRB) Leading Edge Abrasion Strip; Detail Inspection of TRB Leading Edge Abrasion Strip Bonding; Installation of Rivets on TRB Leading Edge Abrasion Strip	15 Sep 89	Red	All	All	All	All	89-20-3R1	Helicopters Equipped with 269A6035 Series Tail Rotor Blades
N-184.1	©	Periodic Check and Initial Replacement - Belt Drive Pulley H-Frame Tie Bar Bracket Assembly, P/N 269A5517-7	21 Nov 83	Red	All	All	All	0004 thru 1149		
N-185	⇒	Operational Check - Fuel Low Warning System	12 Oct 82	Red	All	All	All	All		Incorporated in HMI
N-186	⇒	Corrosion Inspection - Transmission Oil Pressure Switch P/N 269A4576	15 Mar 83	Red	All	All	All	All		Incorporated in Basic HMI and Appendix B
N-187	†	Inspection and Overhaul of Fuel Shutoff Valve P/N 269A4598	29 Jul 83	Red	All	All	All	All		Helicopters Equipped with 269A4598 Fuel Shutoff Valves.
N-188.4	©	Installation of New Higher Strength Tail Rotor Retention Bolt P/N LWB22-6-22, LWB22D-6-22 or HS4441-6-22; and Inspection of Tail Rotor Blade Attachment Bushing Holes	12 Feb 99	Red	All	All	All	All		See N-188.4 for Effectivity.

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-189.1	©	Main Rotor Damper Pitch Bearing Case Attach Hole Inspection and Spacer P/N 269A1207 Installation	2 Sep 86	Red	All	All	All	0001 thru 1165		
N-190	k	Bungee Installation Kit P/N M10123 - Collective pitch stick	15 Dec 83	Red	X	X	X	N/A	Helicopters Equipped with 269A1190-1 Main Rotor Blades	
N-191		Never Issued								
N-192	†	One-time Inspection of Main Rotor Hubs and Shafts; P/N 269A5305 and - 9	7 May 84	Red	All	All	All	All		
N-193	©	Installation of P/N 269A5192 Pinion Aft Bearing Oil Strainer Assembly in Main Transmission Assembly	9 Jan 85	Red	All	All	All	All		
N-194	†	One-time Inspection and Rework of P/N 269A4262 Inertia Reel Shoulder Harness Assemblies and Installation	9 Jan 85	Red	All	All	All	All		
N-195	©	Inspection of Main Transmission Assembly P/N 269A5175-11, -13, -15 and -17	28 Feb 86	Red	All	All	All	All		

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-196	†	Inspection of Throttle and Governor Control Cable Assemblies	28 Feb 86	Red	All	All	All	All		
N-197	⇒	Inspection of Clutch Cable Assembly P/N 269A5590	28 Feb 86	Red	N/A	N/A	N/A	0490 and subs	Superseded by Service Bulletin B-251	
N-198	©	Inspection and Rework of Tail Rotor Pitch Control Link Assembly, P/N 269A6091-5 and 369A1807-7	28 Feb 86	Red	All	All	All	All		
N-199.1	†	One-time Inspection of Main Rotor Drive Shaft P/N 269A5305-11	15 Jul 87	Red	N/A	N/A	N/A	All	Refer to Model Affected: for 269A5305-9 Main Rotor Hub and Drive Shaft Assemblies Serial No.'s	
N-200	†	One-time Inspection of Bolt Holes at Tail Rotor Transmission Attachment Area	30 Mar 87	Red	N/A	N/A	N/A	All	Helicopters Equipped with Tailboom Assembly Serial Numbers S001 thru S171	
N-201.1	©	Inspection and Sealing of Main Rotor Blade Elastomeric Dampers	23 Mar 87	Red	All	All	All	All		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-202	©	Improved Methods for Checking Idle Mixture and Speed, Operational Check of Fuel System	23 Feb 87	Red	All	All	All	All		
N-203	⇒	Visual Check to Ensure that Proper Thrust Bearing Tube is Installed	19 Nov 86	Red	All	All	All	All	Incorporated in HMI	
N-204	©	Identification and Possible Replacement of Collective Pitch Mixer Bellcrank	16 Jun 87	Red	All	All	All	0001 thru 1274		
N-205	©	© Identification and Possible Replacement of Radio Communication Relay	22 Aug 86	Red	N/A	N/A	N/A	See Note	Refer to Models Affected Section for Serial Numbers	
N-206	©	United Instruments Inc. Altimeters P/N 369H4505	17 Nov 86	Red	N/A	N/A	N/A		Refer to Models Affected Section for Serial Numbers	
N-207	©	Installation and Replacement of Protective Sleeve (Speedi-Sleeve P/N 084956) on Tail Rotor Transmission Output Gearshaft	10 Nov 86	Blue	All	All	All	All	Helicopters Equipped with 369A5400 Series Tail Rotor Transmissions	
N-208	©	Identification and Possible Replacement of Tail Rotor Fork Bolt	19 Nov 86	Red	All	All	All	All	Helicopters Equipped with 269A6034 Tail Rotor Assembly	

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-209	†	One-time Inspection of Belt Drive Upper Pulley Assembly	9 Apr 87	Red	N/A	N/A	N/A	1166 thru 1259		
N-210.1	⇒	Identification of Throttle Cable Assemblies; Inspection of P/N 269A4683(BSC) or -3 Throttle Cable Assemblies having Threaded End Fittings; Replacement of P/N 269A4683(BSC) or -3 Throttle Cable Assemblies having Threaded and/or Aluminum End Fitting	30 May 91	Red	All	All	All	0004 thru 0819	90-06-10	Date requirement expired Notice available upon request
N-211	⇒	Periodic Inspection of Engine Lower Coupling Drive Shaft Boot P/N 269A5473	3 Nov 87	Red	All	All	All	All		Incorporated in HMI
N-212	†	One-time X-ray Inspection of Tail Rotor Blade Spar P/N 269A6035-21 and -23	10 Mar 88	Red	X	X	X	X		
N-213	⇒	Daily Visual Inspection of Droop Stop Nut; One-time Dye Stop Nut P/N 269A1340 Penetrant Inspection of Droop	29 Sep 87	Red	All	All	All	All		Date requirement expired

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-214	⇒	Reduced Service Lives for P/N 269A6065 and 369A1706 Tail Rotor Retention Strap Assemblies	3 Nov 87	Red	All	All	All	All	88-12-02	Incorporated in Appendix B – AD related to Notice, but Notice is not directly mentioned in AD
N-215	⊙	Update of Model 269B and 269C Pilot's Flight Manual; Installation of P/N 269A9928-5 and -7 Center Cover Support Bracket	21 Sep 88	Red	N/A	N/A	All	All		
N-216	†	Magnetic Particle Inspection of Main Transmission Pinion Assy	3 Nov 87	Red	X	X	X	X		
N-217	†	Identification of Center Frame Aft Cluster Fittings; Installation of P/N 269A4646-19 Support Strut Placards	29 Jan 88	Red	All	All	All	0004 Thru 1289	88-17-04	Notice available upon request
N-218	‡	Replacement of Auxiliary Fuel Quantity Placard; Installation of P/N 269A4106-3 Instrument Cluster as Replacement for P/N 269A4106 Instrument Cluster	22 Jan 88	Red	See Note	See Note	N/A	See Note		Refer to Models Affected for Serial Numbers
N-219	⇒	Detail Inspections of Upper Pulley Stack-up	24 Aug 90	Red	See Note	See Note	See Note	See Note		Incorporated in HMI

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-220	†	One-time Inspection of P/N 269A2234-3 and 269A2235-3 Aft Cluster Fittings	29 Jan 88		N/A	N/A	N/A	1166 thru 1289	88-17-04	Notice available upon request
N-221	†	Return of Aft Cluster Fittings in Spares Inventory; Dye Penetrant Inspection of Aft Cluster Fittings; Removal of Sample Piece from Aft Cluster Fittings; Daily Visual Inspection of Aft Cluster Fittings	29 Jan 88	Red	All	All	All	1166 thru 1289	88-17-04	Notice available upon request
N-222	†	Textron Lycoming Service Bulletins: No. 480 Oil and Filter Change and Cleaning; No. 369G Engine Inspection after Overspeed or Overboost	21 Sep 88	Red	X	X	X	X		See Lycoming Index for current issue
N-223		Never Issued								
N-224	†	Inspection and Possible Replacement of P/N 33-199-915 Fuel Filter Element (Wire Mesh Screen Without Stiffeners)	21 Sep 88	Red	All	All	All	0004 thru 131		
N-225		Never Issued								

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-226	©	Identification of Belt Drive Clutch Spring Assembly, Inspection of Belt Drive Clutch Engagement Cable, Field Retrofit of P/N 269A5483-1 and -3 Belt Drive Clutch Spring Assemblies with New Cable Sub-Assemblies	3 Jul 89	Red	All	All	All	All		
N-227	†	Inspection of Main Rotor Pitch Bearing Snap Ring Lockwasher	3 Jul 89	Red	N/A	N/A	N/A	1166 thru 1336		
N-228	⇒	269 Series Basic HMI Appendix B and Appendix C Temporary Revisions R-14, R-15, R-16, R-17, R-18 and R-19 to Main Rotor Blade Damper Overhaul Instructions.	3 Jul 89	Red	All	All	All	All	Cancelled	
N-229.1	©	Part Number Conversion of 369(Series) Part Numbers to 269(Series) Part Numbers	10 Feb 92	Red	X	X	X	X		
N-230	⇒	Bendix Fuel Injector System Model RSA-7AA1, P/L2524347 (Lycoming P/N 77885); Precision Airmotive Corporation Service Bulletin PRS-91	6 Oct 89	Red	N/A	N/A	N/A	0004 thru 1387	Superseded by B-248	

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
N-231	†	Identification and Possible Repair of Precision Airmotive Fuel Injector Model RSA-7AA1, Precision Airmotive Service Bulletin PRS-92	31 May 89	Red	N/A	N/A	N/A	See Note	Refer to Model Affected for Serial Numbers See Precision Index for current issue	
N-232	†	Inspection of Tail Rotor Drive Shaft Damper Block Assembly P/N 269A2330-3	6 Oct 89	Red	N/A	N/A	N/A	X		
In accordance with Service Letter 149 (L-149), 24 Aug 1990, Service Information Notices change to Service Bulletins at Number 233										
B-233	†	One Time Inspection - Engine Oil Cooler	10 Feb 92	Red	N/A	N/A	N/A	See Note	Model 269C Helicopters with Serial Numbers 0001-1473, 1475, 1476 and 1478	
B-234	†	Inspection and Modification of Longitudinal Trim Mounting Plate and Trim Arm Stop	16 Dec 91	Red	N/A	N/A	N/A	See Note	Model 269C Helicopters with Serial Numbers 0001-1415, 1417 -1439, 1441 and 1443	
B-235.1	©	Possible Restriction of Throttle Controls	20 Mar 92	Red	See Note	See Note	See Note	See Note	93-05-11	Refer to Model Affected for Serial Numbers. Bulletin available upon request

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-236	†	Inspection of Low Tip Speed Tail Rotor Swashplate Bellcrank Assembly Hole	4 Sep 91	Red	N/A	N/A	N/A	See Note		Model 269C Helicopters with Serial Numbers 1291 through 1432, inclusive, EXCEPT 1413 AND 1416
B-237.1	⇒	Possible Restriction of Cyclic Pitch Control	30 May 91	Red	N/A	N/A	N/A	0004 thru 1456	90-09-07	Incorporated in HMI Bulletin available upon request
B-238.1	©	Inspection and Retirement of 269A2324(BSC) and -7 Tailboom Center Attachment Fittings	7 Nov 91	Red	ALL	All	All	N/A	93-21-03	
B-239.1	©	Inspection and Retirement of P/N 269A2324-7 Tailboom Center Attachment Fitting	7 Nov 91	Red	N/A	N/A	N/A	ALL	91-05-18	
B-240	†	One Time Inspection – Thrust Bearing Nut P/N 269A1315 with Possible Incomplete Threads	8 May 92	Red	N/A			See Note		Refer to Models Affected Section for Serial Numbers
B-241	⇒	Inspection of Seat Belt Snap Hook End Fittings	10 Feb 92	Red	All	All	All	All		Incorporated in Appendix B
B-242	†	One Time Inspection of Main Rotor Blades	10 Feb 92	Red	All	All	All	All		

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-243	⇒	Corrosion Damage Inspection of Main Rotor Drive Shaft P/N 269A5305	08 May 92	Red	ALL	ALL	ALL	ALL		Incorporated in Appendix B
B-244.3	©	Possible Deterioration of Certain Main Transmission Pinion Assembly Teeth and Ring Gear Teeth	06 Apr 1998	Red	ALL	ALL	ALL	ALL	97-23-06	Letter L-153
B-245	©	Maintenance and Operation Requirements for Safe Operation of Surplus TH-55A Helicopters	08 May 92	Red	0315 thru 1109	N/A	N/A	N/A		
B-246		Never Issued								
B-247	†	Tail Rotor Pedal Bulkhead (Floor Beam) Gusset	30 Oct 1992	Red	All	ALL	ALL	All	94-16-04	Bulletin available upon request
B-248	†	Bendix Fuel Injector System Model RSA-7AA1, P/L 2524347 (Lycoming P/N 77885) and Precision Airmotive Corporation Service Bulletin PRS-94 and PRS-94 Supp. 1	07 Nov 91	Red	N/A	N/A	N/A	ALL		
B-249	†	One-Time Inspection of Throttle Override Bellcrank Assembly	20 Mar 92	Red	N/A	N/A	N/A	1166 thru 1543		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-250	⇒	Triple-Latch Door - Lower Latch Bolt and Collective Friction Guide Assembly Interference	20 Mar 92	Red	N/A	N/A	N/A	See Note		Date requirement expired
B-251	†	Inspection of Clutch Cable Assembly and Terminal End (P/N AN669L3RH or MS21260L3RH)	20 Mar 92	Red	All	All	All			Incorporated in HMI
B-252	†	Precision Airmotive Corporation Bulletins PRS-97 and PRS-98	1 Jun 92	Red	See Note	All	All	All		All helicopters with Fuel Injection
B-253	⇒	Tailboom Support Struts Corrosion Inspection	03 Sep 93	Red	All	All	All	All		Incorporated in HMI
B-254		Never Issued								
B-255.1	⇒	Main Rotor Drive Shaft Inspection	01 Feb 93	Red	All	All	All	All	95-21-02	Incorporated in HMI Bulletin available upon request
B-256.2	©	Inspection of Clutch Control Spring Assembly Installation	11 Jun 93	Red	All	All	All	See Note	95-03-12 94-13-04	Refer to Models Affected Section for Serial Numbers
B-257.1	⇒	One-Time Inspection of Lower Coupling Drive Shafts, and New Engine/Rotor Tachometer Markings	21 May 93	Red	All	All	All	See Note	93-17-13	Bulletin available upon request
B-258		Never Issued								

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-259.2	©	50-Hour Inspection of Main Rotor Blade Abrasion Strip	02 Nov 1998	Red	All	All	All	All	98-18-11	See B-259.2 for Blade S/N Effectivity AD related to Bulletin, but Bulletin is not directly mentioned in AD
B-260	©	Corrosion Inspection and Treatment of Lower Coupling Drive Shaft	19 Oct 1994	Red	See Note	See Note	See Note	See Note		Helicopters with Drive Shaft Serial Number S478 thru S712
B-261	©	Periodic Inspection of Main Transmission Pinion Input Shaft Assembly	19 Oct 1994	Red	See Note	See	See	See Note		Helicopters with P/N 269A5103 BSC or -9 Pinion Input Shaft
B-262		NOT USED								
B-263	©	Inspection of Aft Cluster Fittings	24 May 1995	Red	See Note	See Note	See Note	See Note		Helicopters with P/N 269A2234-3 or 269A2235-3 Aft Cluster Fittings
B-264	©	One-Time Inspection of Tail Rotor Blades	15 Sep 1995	Red	N/A	N/A	N/A	See Note		See B-264 for Blade S/N Effectivity
B-265.1	©	269A6050-005 LTS Tail Rotor Pitch Control Assembly, Torque Verification of 269A6258 Nut, and Application of Torque Stripes	23 Jul 1996	Red	All	All	All	All		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-266	©	Textron Lycoming Service Bulletin No. 525	15 Oct 1996	Red	See Note	See Note	See Note	See Note		See Textron Lycoming Service Bulletin No. 525 for Effectivity
B-267	©	Textron Lycoming Service Bulletin No. 527C	24 Jul 1997	Red	See Note	See Note	See Note	See Note		See Textron Lycoming Service Bulletin No. 527C for Effectivity
B-268	©	One-Time Inspection of Main Rotor Hub and Shaft, and New Assembly Procedure	24 Jun 1998	Red	See Note	See Note	See Note	See Note		See B-268 for Effectivity
B-269.1	©	Replacement of Old Style Tail Rotor Drive Fork Hinge Bolt and Clarification of Torque Value	26 Dec 2002	Red	See Note	See Note	See Note	See Note		See B-269.1 for Effectivity
B-270.2	©	Inspection of 269A5104-007 Main Transmission Ring Gears with Specific Serial Numbers and Reporting of Inspection Results	12 Mar 2001	Red	See Note	See Note	See Note	See Note		See B-270.2 for Effectivity
B-271.1	©	Tail Rotor Swashplate Shaft Inspection	14 Oct 1999	Red	See Note	See Note	See Note	See Note	2000-16-05	See B-271.1 for Effectivity
B-272	©	Inspection/Replacement Criteria for Certain Upper H-Frame Bearings (Sikorsky P/N 269A5050-78)	18 Feb 2000	Red	See Note	See Note	See Note	See Note		See B-272 for Effectivity

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-273	©	Replacement of Shoulder Harness and Inertia Reel Assembly. (Sikorsky P/N 269A4262-27)	23 Aug 2000	Red	See Note	See Note	See Note	See Note		See B-273 for Effectivity
B-274	©	Textron Lycoming Special Advisory No. 63-1200	02 Jan 2001	Red	See Note	See Note	See Note	See Note		See B-274 for Effectivity
B-275	©	One-Time Inspection for Condition and Modification of Certain Idler Pulley Support Assemblies	12 Mar 2001	Red				See Note		See B-275 for Effectivity
B-276	©	Main Rotor Swashplate Bearings P/N 269A1301	26 Oct 2001	Red	See Note	See Note	See Note	See Note		See B-276 for Effectivity
B-277	©	One-Time Inspection of Certain 269A2234-3 (LH) and 269A2235-3 (RH) Aft Cluster Fittings	25 Jan 2002	Red	See Note	See Note	See Note	See Note	2003-13-15R-1	See B-277 for Effectivity
B-278	©	269A2234 BSC and 269A2235 BSC Aft Cluster Fitting Modification	06 Sep 2002	Red	See Note	See Note	See Note	See Note		See B-278 for Effectivity
B-279		Never Issued								
B-280.1	©	Modification of 269A5590-1, and 269A5483-1/-3 Clutch Spring Assemblies	06 Apr 2004	Red	See Note	See Note	See Note	See Note		See B-280.1 for Effectivity
B-281	©	Throttle Governor Bellcrank	05 Sep 2003	Red						

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-282.1	©	Support Bracket (269A8460-3) Throttle Bellcrank, Inspection for Cracks	24 Sep 2004	Red	See Note	See Note	See Note	See Note		See B-282.1 for Effectivity
B-283.1	©	Inspection and Modification of 269A7316-13 Lateral Control Trim Assembly	04 Mar 2005	Red	See Note	See Note	See Note	See Note	2005-10-12	See B-283.1 for Effectivity
B-284.1	©	Modification of 269A4564-5 and -7 Linear Actuators	18 Sep 2006	Red	See Note	See Note	See Note	See Note		See B-284.1 for Effectivity
B-285.1	©	Modification of Locknut/Hoist Eye Assembly	17 Mar 2006	Red	See Note	See Note	See Note	See Note		See B-285.1 for Effectivity
B-286	©	Tail Rotor Swashplate Bellcrank Assembly Safety Washer Installation	04 Oct 2006	Red	See Note	See Note	See Note	See Note		See B-286 for Effectivity
B-287.1	©	Main Transmission Input Pinion Corrosion Protection	24 Aug 2010	Red	See Note	See Note	See Note	See Note		See B-287.1 for Effectivity
B-288.1	©	Tail Rotor Drive Shaft Splined Fittings Inspection	21 Apr 2008	Red	See Note	See Note	See Note	See Note		See B-288.1 for Effectivity
B-289.1	©	Installation of Single Wheel Ground Handling Wheel Locking Device	26 Sep 2008	Red	See Note	See Note	See Note	See Note		See B-289.1 for Effectivity

Models 269A, TH-55A, A-1, B & C - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-290	©	Landing Gear Skid Tube Aft Sleeve Inspection	26 Sep 2008	Red	See Note	See Note	See Note	See Note	See B-290 for Effectivity	
B-291	©	Fuel Strainer Leak Check	03 Oct 2008	Red	See Note	See Note	See Note	See Note	See B-291 for Effectivity	
B-292	©	Modification of Cabin Door Hinges	24 Oct 2008	Red	See Note	See Note	See Note	See Note	See B-292 for Effectivity	
B-293	©	Incorrect Grease Identification in Certain Serial Number Helicopters	09 Jan 2009	Red	See Note	See Note	See Note	See Note	See B-293 for Effectivity	
B-294	©	Incorrect Bushing used in 269C Flight Controls	24 Aug 2010	Red	See Note	See Note	See Note	See Note	See B-294 for Effectivity	
B-295.1	©	Inspection and Modification of Tailboom Support Strut Adjustable Biameter Bolt	28 Feb 2012	Red	X	X	X	X	Refer to Models Affected	
B-296	©	Clevis Pin Chaffing Bottom of Fuel Tank	05 Jan 2011	Red	N/A	N/A	N/A	ALL		
B-297.1	©	Inspection of Main Rotor Drive and Thrust Bearing Journal Radius	06 Oct 2011	Red	N/A	N/A	N/A	See Note	269 C Helicopters delivered after 1 Jun 1999 including serial number 1783 thru 1953 with 269 A1318-008 main rotor thrust bearing spacer tube installed	

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-298	©	Powertrain: One-Time Inspection of Belt Drive Idler Pulley Hardware For Presence and Security	04 Jan 2012	Red	ALL	ALL	ALL	ALL		
B-299.1	©	Drive Train - Tail Rotor Drive Shaft Splined Fittings - Perform a One-Time Inspection and Implement a Recurring Inspection for Wear	13 Feb 2012	Red	ALL	ALL	ALL	ALL		
B-300	©	One-Time Inspection to Remove from Service Engine and/or Rotor Tachometer Cables with a Hexagonal Connector on One End	18 Apr 2012	Red	ALL	ALL	ALL	ALL		
B-302	†	One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer	2 May 2013	Red	N/A	ALL	ALL	ALL		
B-303	†	One-Time Inspection of the Belt Drive Transmission Upper Pulley Installation for Correct Torque, Parts Configuration and Stack-up, Damage and/or Wear	30 Jun 2015	Red	See Note	See Note	See Note	See Note	Model 269C Helicopters with Serial Numbers S1809-S1961	
B-304	†	One-Time Load/Stroke Inspection of Landing Gear Dampers to be Performed at an Overhaul or Repair Facility.	15 Apr 2014	Red	N/A	ALL	ALL	ALL		

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-305	†	One-Time Inspection of the Belt Drive Transmission Upper Pulley Installation for Aft Pinion Nut Torque, Parts Configuration and Stack-up, Damage and/or Wear	30 Jun 2015	Red	ALL	ALL	ALL	See Note	Model 269C Helicopters with Serial Numbers S0001-S1808	
B-306	†	One-Time Inspection of Tail Rotor Flight Control Cables, Pulleys, and Forward and Aft Bellcranks for Damage and/or Wear, and Verification of Parts Configuration	21 Nov 2014	Red	ALL	ALL	ALL	ALL		
B-307	†	POWER TRAIN – Lower Coupling Drive Shaft – One-Time Inspection of Lower Coupling Drive Shaft and Shaft Assembly	18 Dec 2014	Red	ALL	ALL	ALL	ALL		
B-308A	†	MAIN ROTOR AND CONTROL SYSTEM – Pilot’s Collective Pitch Control Stick - One-Time Inspection of Collective Pitch Control Torque Tube	4 Aug 2015	Red	ALL	ALL	ALL	ALL		
B-309	†	POWER TRAIN – Belt Drive Clutch Control Installation – One-Time Inspection of Cable Pulley Bracket	1 Mar 2016	Red	ALL	ALL	ALL	ALL		

Models 269 - Publications Index

Section 2
Service Information Notices and Service Bulletins

Notice No.	Status Notation	Subject	Date Issued	Letterhead	Models Affected				Related FAA AD	Notes
					269A TH-55A	269A-1	269B	269C		
B-310	†	MAIN ROTOR AND CONTROL SYSTEM AND TAIL ROTOR AND CONTROL SYSTEM – Main Rotor and Tail Rotor Control Rods – One-time Inspection of Flight Control Pushrods with Adjustable Rod Ends	3 Mar 2016	Red	ALL	ALL	ALL	ALL		
B-311	†	CABIN AND CENTER FRAME SECTION – Cabin Doors – One-time Inspection of Airframe and Door Mounted Hinge-Halves for Proper Sizing and Plunger Pin to Lug Engagement	30 Jun 2016	Red	ALL	ALL	ALL	ALL		

This page is intentionally left blank.

Number	Status	Nomenclature	Date
L-1	Incorporated	Input Spline Coupling PN 269A5607 Time Increase – Tail Rotor Transmission	8 Jun 66
L-2	Incorporated	Recommended Overhaul Period - Rotorcraft Powerplants	8 Jun 66
L-3.1	Incorporated	Interim Revision - Handbook of Maintenance Instruction (HMI) Re: 1200 Hour Periodic Inspection of Main Rotor Gear Drive Assembly	5 Oct 66
L-4	Cancelled	Rebate Time Allowance - Lower Coupling Drive Shaft Assembly PN 5504-5	21 Jul 66
L-5	Incorporated	Replacement of Thermostatic Oil Cooler By Pass Valves, Per AVCO, Lycoming Division, Service Bulletin No. 304A (Red Bordered Mandatory) (dated), 24 June 66	1 Aug 66
L-6.1	Incorporated	Bendix Fuel Injection System, RSA Series Trouble Shooting Technique for Identifying Fuel to Air Seal Leak	23 Nov 66
L-7	Incorporated	Belt Drive Clutch Engagement Spring PN 5476 - Availability and Utilization	22 Aug 66
L-8	Incorporated	Illumination Intensity - Engine Instrument	4 Oct 66
L-9	Active	Replacement - Fuel Flow Tubing Assembly	13 Oct 66
L-10	Incorporated	Pressure Variation with Temperature - Amphibious Float Landing Gear	7 Nov 66
L-11	Incorporated	Intake Pipe Replacement Per AVCO - Lycoming Division Service Instruction No. 1162 (dated), 16 Sept 1966	1 Dec 66
L-12	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Main and Tail Rotor Overspeed Criteria	5 Dec 66
L-13	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Limited Life and Component Overhaul List	11 Jan 67
L-14	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Inspection Sudden Stoppage Drive System	20 Feb 67
L-15.1	Incorporated	Definition - Limited Parts	21 Feb 67
L-16	Active	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Maintenance Instructions for Low Tip Speed Tail	23 Aug 67
L-17	Incorporated	Retrofit - Clutch Spring Attachment Strap	29 Mar 67
L-18	Cancelled	Ordering - Main Rotor Blades	1 Apr 67

Number	Status	Nomenclature	Date
L-19	Incorporated	Replacement - Internal Seal, Fuel Drain Valve	1 Apr 67
L-20	Superseded N-41	Lycoming Service Letter No. L157A (dated), 9 Dec 66; Engine Mounted Full-flow Oil Filter	1 Apr 67
L-21	Incorporated	Chemical Attack - Re: Bolteron and Royalite Parts	1 Apr 67
L-22	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Installation Pitch Control Rod Inspection of Pitch Bearing Cases, Main Rotor Swashplate Assembly and Swashplate Scissors Link	22 Aug 67
L-23	Incorporated	Approved Fuels for Allison Model 250 Series Engine	16 Jun 67
L-24	Incorporated	Proper Height of Contact Spring in - 200 Bendix Magneto Distributor Block	5 May 67
L-25	Active	Parts Replacement - Main Rotor Shaft PN 5305-3, Hub 5305-5 and Lifting Eye 5305-7	5 Sep 67
L-26	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: PN B1145-1 Main Rotor Blade Assembly	7 Jul 67
L-27	Incorporated	Allison Model 250 Engine - Sales and Service	10 Jul 67
L-28	Cancelled	Conversion of HO-360-B1A or HO-360-B1B Carbureted Engine to HiO-360-B1B Fuel Injection Engine	27 Jul 67
L-29	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Lower Coupling Drive Shaft PN 269A5504(basic) and -5 Shaft Assembly- Wear Tolerance	22 Sep 67
L-30	Incorporated	New Tail Rotor Blade PN 6124-9	25 Sep 67
L-31	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Inspection and Maintenance Procedures for Landing Gear Oleo Dampers	2 Oct 67
L-32	Incorporated	Bendix Corporation; RS Fuel Injection Service Bulletin No. 23 (dated), 10 Jan 1967	31 Oct 67
L-33	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Overhaul Cycle, Tail Rotor Drive Transmission Assembly	17 Nov 67
L-34	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Special Torque Data - Forward Nut, Lower Pulley Drive Shaft	13 Dec 67
L-35	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: 25 Hour Periodic Inspection	14 Dec 67

Number	Status	Nomenclature	Date
L-36	Active	Lycoming Service Instruction No. 1141 (dated), 20 Oct 1967 - Subject: Replacement of Worn Starter Ring Gears	28 Dec 67
L-37	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Overhaul Cycle; Main Rotor Gear Drive Assembly	2 Jan 68
L-38.1	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Inspection - Possible Retirement, Main Rotor Blades	31 Jan 68
L-39	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Inspection - Cable Belt Drive Clutch Control	27 Feb 68
L-40	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: 400 Hour Inspection - Droop Stop Retainer Ring	14 Mar 68
L-41	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: 600 Hour Inspection - Droop Stop Retainer Ring	14 Mar 68
L-42	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Limited Life; Main Rotor Drive Shaft and Main Rotor Gear Box Pinion Assembly	14 Mar 68
L-43	Incorporated	Mixing Main Rotor Transmission Gears	5 Apr 68
L-44	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Sudden Stoppage Inspection; Lateral Control Bellcrank PN 269A7506	18 Apr 68
L-45.2	Superseded L-145	Salvage Parts - 269 Series Helicopters	10 Feb 84
L-46.2		Bendix Energy Controls Division - Field Service Representation	18 Feb 73
L-47	Incorporated	Interim Revision - Handbook of Maintenance Instructions (HMI) Re: Wear Tolerances - PN 269A5618 Output Shaft. Tail Rotor Transmission	16 Jul 68
L-48	Incorporated	Balance Weight Installation - Main Rotor Blades	11 Sep 68
L-49.1	Active	Grommet PN 269A2309, Tail Rotor Control Rod Guide Assembly	12 Mar 69
L-50.8	Superseded L- 113.6	Exchange Program - Major Helicopter Components	14 Feb 78
L-51	Incorporated	Main Rotor Blade Categories A, B, C and D	18 Oct 68
L-52	Incorporated	Parts Replacement Kit PN 269A5540-901 Belt Drive Clutch Damper Assembly	22 Nov 68

Number	Status	Nomenclature	Date
L-53	Incorporated	Inspection of Landing Gear Skid Assembly	9 Dec 68
L-54	Active	Tail Boom Spoiler PN 269A2320-5	20 Feb 69
L-55	Incorporated	Tail Boom Center Support (Saddle) Fitting PN 269A2324-7	29 Apr 70
L-56	Incorporated	Oil Pressure Limitations	12 Jun 70
L-57	Incorporated	New Attaching Hardware - Engine Cooling Shroud Side Panels	4 Nov 70
L-58	Incorporated	New Heavy Wall Drive Shaft for High Speed Tail Rotor System	19 Apr 71
L-59	Incorporated	Ordering Replacement Engine Air Intake Pipes	6 Jul 71
L-60.1	Incorporated	Timing of Magneto and Engine Ignition System	6 Apr 72
L-61	Incorporated	Increased Overhaul Time Interval for Main and Tail Rotor Transmissions	23 Aug 71
L-62	Incorporated	Bendix Electrical Components Division - Service Bulletin No. 551 (dated), September 1971 - New Distributor Block Lubricant	8 Oct 71
L-63	Active	Lycoming Service Bulletin Nos. 340 and 341 (dated), 27 August 1971	1 Nov 71
L-64	Incorporated	Lamp Replacement - PN 269A4322 Anticollision Light Assembly (Grimes)	13 Dec 71
L-65	Incorporated	Abrasion Tape Application - Main Rotor Blades PN 269B1145, -1 and 269A1160	21 Jan 72
L-66	Incorporated	Desert Oil Cooler Kit	14 Feb 72
L-67	Active	Improved Main Rotor Blade Damper Assembly PN 269A1927-5	6 Apr 72
L-68.1	Incorporated	Lycoming Service Bulletins, No. 336B (dated), 19 June 1972 and No. 343A (dated), 18 February 1972 - Periodic Inspection - Lubrication and Parts Replacement for Bendix S4LN-1208 Magnetos	7 Aug 72
L-69	Incorporated	Tail Rotor Gearbox PN 269A6027 - Interchangeability Between Model 269 Series Helicopters	1 May 72
L-70	Incorporated	Lycoming Service Bulletin No. 336B (dated), 19 June 1972 Re: Periodic Inspection and Lubrication of Magneto Distributor Bushing; Periodic Parts Replacement of Left Magneto	24 Jul 72

Number	Status	Nomenclature	Date
L-71	Active	Lycoming Service Bulletin No. 355 (dated), 4 August 1972 - Alternator Fan Replacement (Prestolite Bulletin No. ASM-8)	12 Sep 72
L-72	Incorporated	Lycoming Service Instruction No. 1255 (dated), 4 August 1972 - Thermostatic Oil Cooler Bypass Valve Replacement	1 Nov 72
L-73	Incorporated	Inflated Float Installation - Battery Acid Spillage	2 Jan 73
L-74	Incorporated	Fuel Shutoff Control Cable - Rerouting to Reduce Operating Friction	2 Jan 73
L-75	Incorporated	Increase Ring Gear to Carrier Torque	13 Feb 73
L-76	Incorporated	Corporate Name Change	1 Mar 73
L-77	Incorporated	Avco Lycoming Service Bulletin No. 365 (dated), 1 June 1973 - Bendix Magneto Conversion to Incorporate Flexible Drive	31 Jul 73
L-78	Incorporated	New Main Transmission Input Pinion Forward Roller Bearing PN 269A5051-20	22 Oct 73
L-79	Incorporated	Vendor Warranty and Repair - Police Patrol Equipment	24 Dec 73
L-80	Active	High Tip Speed Tail Rotor PN 269A6004 - Spare Assembly and Component Availability	1 Apr 74
L-81	Incorporated	Discussion of Hughes Serial Numbering Method	31 May 74
L-82	Incorporated	Inflatable Floats - Service, Maintenance and Repair Facilities	5 Aug 74
L-83	Available Upon Request	Replacement - Tail Rotor Control Pedal Retaining Pins	11 Nov 74
L-84	Incorporated	Replacement - 24V Clutch Actuator Noise Filter Capacitors	18 Nov 74
L-85	Incorporated	Bendix Fuel Injection System Flow Divider Installation on HiO-360 Series Engine - Inspection/Modification	5 May 75
L-86.2	Incorporated	Main Transmission - Ring, Pinion Gear Compatibility	5 Nov 79
L-87	Incorporated	New Conical Type Teeter Bearings for LTS Tail Rotor Assembly	11 Aug 75
L-88	Incorporated	Proper Correlation of Throttle and Collective Pitch Controls	10 Nov 79
L-89	Incorporated	New Fiberglass Canopy Slat Installation PN 269A269A2216	11 Dec 75
L-90	Incorporated	New Tail Rotor Blades with Cadmium Plated Spar Assembly for Improved Corrosion Protection	26 Jul 76
L-91	Incorporated	Alternate Lamp for Engine Instrument 3-Pack Units PN 269A4112 Series	26 Jul 76

Number	Status	Nomenclature	Date
L-92	Incorporated	New PN 269B1145-25 Main Rotor Blade with Trim Tab	11 Oct 76
L-93	Incorporated	New Aluminum Isolator Brackets for Mounting Engine Cooling Scroll Reduce Stress Levels in Engine Hanger Assemblies	8 Aug 77
L-94	Active	Fiberglass Canopy Slat Installation PN 269A2216 – Attachment of Night Flying Position Lights	22 Jul 77
L-95	Active	New PN 269A1185-1 and 269A1190-1 Main Rotor Blade Assemblies with Leading Edge Abrasion Strip	15 Dec 77
L-96	Incorporated	Paint Schedules and Ordering Procedures	10 Apr 78
L-97	Incorporated	Inspection and Serviceability - Main Rotor Thrust Bearing PN 269A5050-63 and -73	22 May 78
L-98.1	Incorporated	Approved Grease for Drive System Rotating Bearings	2 Nov 81
L-99	Incorporated	Installation of Engine Exhaust Flange Gaskets	15 Jul 78
L-100.1	Cancelled	Exchange Program - Major Helicopter Components	7 Jan 80
L-101	Incorporated	Limited Life Increase for PN 269A5050-63 and -73 Main Rotor Thrust Bearings; Unlimited Service Life for PN 369A5408 Series Tail Rotor Transmission (LTS) Output Shaft	1 Aug 79
L-102	Incorporated	New PN 269A8251 Heat Insulation Kit for Model 269C Engine Exhaust System	28 Sep 79
L-103	Incorporated	Main Transmission Input Pinion Shaft PN 269A5103 and -9 - Limited Life Increased to 6000 Hours	27 Aug 79
L-104	Active	Installation of Engine Exhaust Collector Required for 2050 LB Gross Weight Helicopter Operation	28 Sep 79
L-105	Incorporated	Belt Drive Transmission PN 269A5559-3 Coupling Shaft - Limited Life Increase to 6000 Hours	19 Nov 79
L-106.1	Incorporated	Drive System Rotating Bearings - Daily Purge with Mobil 28 Grease	1 Feb 82
L-107	Incorporated	New Comfort Clips for Sam Browne Seat Belt and Shoulder Harness Assemblies	10 Dec 79
L-108	Incorporated	New Wedge Base Lamp Socket PN 2973932 for Both Instrument Cluster Assemblies	1 Jan 80
L-109	Incorporated	Bushing Requirements for PN 269A2324-7 Tailboom Center Support (Saddle) Fitting Installation	24 Mar 80

Number	Status	Nomenclature	Date
L-110.1	Active	12V Battery Relay PN MS24166D1 - Corrosion Protection and Relay Replacement	19 Nov 82
L-111	Superseded by L-156	New Seal Requirement for Overhaul of PN 269A3150-5 and -7 Landing Gear Damper Assemblies	9 Jun 80
L-112	Incorporated	Periodic Cleaning and Lubrication of Sealed Bearing – Upper Pulley, Lower Coupling Drive Pulley, Idler Pulley and Main Rotor Drive Shaft Thruster Bearing	9 Jun 80
L-113.6	Incorporated	Exchange Program - Selective Helicopter Components	12 Feb 85
L-114.2	Incorporated	New Drive Belt H-Frame with PN 269A5050-78 Upper Pulley Bearing Having Service Life of 3000 Hours	15 Feb 83
L-115	Active	Compliance with FAA Airworthiness Directives and Hughes Mandatory (Red Border) Service Information Notices	30 Sep 80
L-116	Cancelled	Customer Request for Original Weight and Balance Data	8 Dec 80
L-117.1	Incorporated	Periodic Inspection and Replacement - Main Rotor Hub Attaching Bolts PN 269A1229 and 269A1232	21 Jul 81
L-118.5	Cancelled	Biannual Listing of Airworthiness Directives versus the Associated Hughes Service Information Notice	1 Jul 83
L-119.1	Incorporated	Aeroshell 14 Grease Only Approved Lubricant for Rotor System Oscillating Bearings	2 Nov 81
L-120	Incorporated	Ground Handling Precautions for Main Rotor Systems Equipped with Elastomeric dampers	31 Jul 81
L-121	Incorporated	Corrosion Control Manual now Available for General Distribution and Purchase	21 Aug 81
L-122	Superseded N-214	Finite Life Increase for PN 269A6065 and 369A1706 Tail Rotor Retention Straps Installed on Model 269C Helicopters	1 Sep 81
L-123	Incorporated	New Protective Boot for 269A6034 Series LTS Tail Rotor Assembly	1 Sep 81
L-124	Incorporated	Torque Value Established for PN 269A5714 Tail Rotor Drive Shaft Forward Retaining Nut	1 Sep 81
L-125	Incorporated	New PN 269A5498-5 Lower Coupling Pulley Drive Shaft Provides as Replacement for PN 269A5498-3 Drive Shafts	1 Oct 81
L-126.1	Available upon request	Summary of FAA Supplemental Type Certificates for Hughes Model 269 Series Helicopters	1 Sep 82

Number	Status	Nomenclature	Date
L-127.1	Active	Unlimited Service Life PN 269A5430 and -1 Driving Spline Fitting and 269A6030 Driven Spline and Inspection Criteria	9 Apr 82
L-128	Never Issued		
L-129	Incorporated	PN 269A5050-74 Idler Pulley Bearing and PN 269A5050-78 Belt Drive H-Frame Upper Bearing - Service Life Increased to 3000 Hours	15 Feb 82
L-130	Incorporated	New PN 269A3150-9 Aft Landing Gear Damper Assemblies Increase Static Height of Tail Skid for 269C Helicopters Operating in Cold Weather or with Increased Gross Weight	26 Mar 82
L-131.1	Active	Distribution and Shipment of Schweizer-Hughes Model 300 Publications	1 Feb 84
L-132	Active	New Tail Boom Assembly PN 269A2320-9	24 Nov 82
L-133	Active	Unauthorized Tailboom Assemblies for 269 Series Helicopters	27 Feb 84
L-134	Cancelled	Return of Parts/Components to Schweizer Aircraft Corp	9 Mar 84
L-135	Superseded N-214	Service Life Cutoff Limit	11 Feb 86
L-136	Cancelled	Loan of Schweizer Throttle Governor Wire Harness Test Box PN 269A4995-301-99801-3	8 Mar 86
L-137	Active	Replace Aircraft Identification Plates	11 Feb 86
L-138	Active	Service Life Cutoff Limit	11 Feb 86
L-139	Incorporated	Cleaning of Elastomeric Dampers	2 Jan 87
L-140	Active	Proper Operation of Trim Controls	2 Jan 87
L-141	Active	Explanation of Temporary Revision System	2 Jan 87
L-142	Incorporated	Life Limit Update	2 Jan 87
L-143	Incorporated	Overhaul Schedule Update	2 Jan 87
L-144	Incorporated	Breakaway Torque Increase - MR Bearing Assembly	29 Sep 87
L-145	Active	Company Policy - Unapproved Parts	10 Mar 88
L-146	Active	Avco Lycoming Service Bulletins - No. 454B Replacement of Oil Pump Impellers, No. 456C Replacement of Oil Pump Impellers and No. 477A Inspection and Rework of PN LW-18790 Rocker Arm Assembly	1 Sep 87

Number	Status	Nomenclature	Date
L-147	Active	Publication Index - Major Change in Scope and Revision Process	15 Dec 87
L-148	Active	Avco Lycoming Service Instructions No. 1014K and 1409A	1 Feb 89
L-149	Active	Changes to Notice and Letter Nomenclature	24 Aug 90
L-150.2	Active	New Belt Drive Transmission H-Frame	24 Jul 96
L-151	Active	Printer Errors in Notice and Letter Sets January 1990	5 Oct 90
L-152	Active	New Part Numbers for Tail Rotor Transmission Assembly	7 Nov 91
L-153	Active	Extended Warranty Policy for Pinion and Ring Gears Installed in Main Rotor Transmissions Affected by Service Bulletin B-244	7 Nov 91
L-154	Active	Service Facilities, for Corrosion Damage Inspection and Repair of the Main Rotor Drive Shaft P/N 269A5305. Ref. Service Bulletin B-243	8 May 92
L-155	Active	Main Rotor Rod End Bearings and Lead-Lag Bushings	29 Apr 93
L-156	Incorporated	New Improved Landing Gear Dampers	29 Apr 93
L-157	Active	Overhaul Kits for Fuel Shut-Off and Drain Valves	29 Apr 93
L-158	Active	Improper Maintenance Procedures in Installation of the 269A2324 Series Tail Boom Support Fitting (Saddle Fitting) Which Results in a Hazardous Flight Condition	29 Apr 93
L-159	Incorporated	Additional Lubricants for Lower Coupling Drive Shaft	30 Apr 1995
L-160	Active	Strut and Bracket Assembly - Belt Drive Installation	14 Oct 1996
L-161	Active	New Improved Clutch Spring Retainer	07 Apr 1997
L-162	Active	Compliance of Service Notice N-59, AD 68-21-05, and AD 97-05-06 against 269A5050-50, -53, and -73 Main Rotor Drive Shaft Thrust Bearing (Applicable to Models 269A, TH-55A, 269A-1 & 269B)	15 Apr 1997
L-163	Active	Exchange Program for Elastomeric Tail Rotor Fork	27 Sep 1999
L-164	Active	New Electric Driven Airframe Fuel Pump	27 Sep 1999
L-165	Active	Compliance with Airworthiness Directive 99-17-10	02 Sep 1999
L-166	Active	New Retirement Time Life for 269A5103-51 Input Pinion and 269A5194 Carrier Assembly Installed in Model 269C-1 Helicopters	13 Dec 1999

Number	Status	Nomenclature	Date
L-167	Active	300CB Engine Time Between Overhaul Extension	06 Jun 2000
L-168	Active (UK Only)	New SA-269K-101 Fuel System Vent Kits	10 Aug 2000
L-169	Active	New SA-269K-101 Fuel System Vent Kits	01 Sep 2000
L-170	Active	Introduction of New 269A5175-35 and -37 Main Rotor Transmission Assemblies	01 Dec 2000
L-171	Active	Orientation of Main Rotor Transmission Backlash Shim	01 Dec 2000
L-172.1	Active	New Design - Tail Rotor Drive Shaft	25 Jan 2002
L-173	Active	Special Inspection of Main Rotor Transmission Magnetic Plug	22 Aug 2001
L-174	Active	Introduction of New Lower Pulley Bearing Removal Tool	11 Sep 2001
L-175	Active	Optional Anti-Collision Light Conduit in New 269A2320-17 Tailboom Assemblies	11 Sep 2001
L-176	Not Issued		
L-177	Active	AFT Cluster Fitting Modification Kit (P/N SA-269K-0106-1)	13 Sep 2002
L-178	Active	Upgrade of 269A4564-5 Linear Actuator	13 Sep 2005
L-179	Active	Verification of Mandatory Cluster Fitting Replacement	13 Sep 2005
L-180	Active	Function of Tail Rotor Drive Shaft Damper Block	26 Sep 2008
L-181	Active	Retirement of Certain Engine and Rotor Tachometer Cables	09 Jan 2009
L-182	Active	ELT Direct Replacement Authorization	17 Jun 2009
L-183	Active	Technical Publications - Policy & Price Changes, 2010	11 Mar 2010
L-184	Active	2010 Publications Schedule	11 Mar 2010

Number	Status	Subject	Publication No.	Date
269A-1	Incorporated	New Warning related to the use of components from aircraft with crash damage.	CSP-C-2	Aug 2011
269A-2	Incorporated*	Caution related to fretting that may occur in the Ring Gear Carrier Assembly P/N 269A5194.	CSP-C-5A	12 Dec 11
269A-3	Incorporated*	Incorporates a Ring Gear Mounting Surface Inspection for fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C-5A	12 Dec 11
269A-4	Incorporated*	Incorporates a Note to gear mating areas for fretting and adds inspection for gear mating areas for cracks of Ring Gear Carrier Assembly P/N 269A5194.	CSP-C-5A	12 Dec 11
269A-5	Incorporated*	Incorporates procedures to repair Ring Gear Carrier Assembly P/N 269A5194 fretting that may occur.	CSP-C-5A	12 Dec 11
269A-6	Incorporated*	Incorporates Changes to maintenance instructions for ring gear to carrier assembly due to fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C-5A	12 Dec 11
269A-7	Incorporated	100-Hour Periodic Inspection Requirement.	CSP-C-2	15 Mar 12
269A-8	Incorporated	300-Hour Periodic Inspection Requirement.	CSP-C-2	15 Mar 12
269A-9	Incorporated	Adds step to inspect the Damper Assembly	CSP-C-2	1 Mar 13
269A-10	Incorporated	Incorporates changes to Assembly of LTS Tail Rotor Driveshaft and Damper Assembly.	CSP-C-2	1 Mar 13
269A-11	Incorporated	100-Hour Periodic Inspection Requirement.	CSP-C-2	1 Mar 13
269A-12	Incorporated	Adds new step to inspect the tail rotor damper block assembly.	CSP-C-2	26 Aug 13
269A-13	Incorporated	Updates inspection of tail rotor damper block and adds a new paragraph to inspect installed damper assembly.	CSP-C-2	26 Aug 13
269A-14	Incorporated	Updates inspection of splined drive sleeve.	CSP-C-2	26 Aug 13
269A-15	Incorporated	Updates inspection of driven spline.	CSP-C-2	26 Aug 13

* Data moved from HMI to CMM

Number	Status	Subject	Publication No.	Date
269A-16	Incorporated	Modifies Table 2-1. Servicing Materials (Operating Supplies), Item No 2., 3., and 6.		24 Jan 2014
269A-17	Incorporated	Modifies Table 2-1. Servicing Materials (Operating Supplies), Footnote 3 and adds Footnote 11.		24 Jan 2014
269A-18	Incorporated	Replaces Figure 2-9. Lubrication Chart (Sheet 1 of 5).	CSP-C-2	24 Jan 2014
269A-19	Incorporated	Revises step o. (1), step o. (2), and step o. (3) of paragraph 5-3, Reassembly.	CSP-C-2	15 Apr 2014
269A-20	Incorporated	Revises step b of paragraph 5-5, Leakage Check and adds new paragraph 5-5A, Load/Stroke Inspection to Section 5, Reassembly, Charging and Leakage Check.	CSP-C-2	15 Apr 2014
269A-21	Incorporated	Revises step c. (2) of paragraph 13-30, Inspection of Main Rotor Mast.	CSP-C-2	6 Aug 2014
269A-22	Incorporated	Revises step 17. of Table B-2, Periodic Inspections, What to Inspect – 100-Hour Inspection.	CSP-C-2	6 Aug 2014
269A-23	Incorporated	Revises steps g. and h. of paragraph 10-29, Inspection of Clutch Control Assemblies.	CSP-C-2	6 Aug 2014
269A-24	Incorporated	Revises step 9. of Table B-1, Daily Inspection – Before First Flight of the Day, What to Inspect (Power OFF), Right Side – Fuel Tank, Clutch Assembly, V-belts, and Pulleys.	CSP-C-2	6 Aug 2014
269A-25	Incorporated	Adds step 48. to Table B-2, Periodic Inspections, What to Inspect – 100-hour Inspection.	CSP-C-2	6 Aug 2014
269A-26			CSP-C-2	Not Issued
269A-27	Incorporated	Replaces Figure 9-1. Tail Rotor Control System.	CSP-C-2	9 Mar 2015
269A-28	Incorporated	Revises step e. of paragraph 9-40, Inspection of Tail Rotor Control System.	CSP-C-2	9 Mar 2015
269A-29	Rescinded	Revises step 6. of Table B-2, Periodic Inspections, What to Inspect – 100-Hour Inspection.	CSP-C-2	9 Mar 2015
269A-30	Rescinded	Revises step 4. of Table B-2, Periodic Inspections, What to Inspect – 600-Hour Inspection.	CSP-C-2	9 Mar 2015

Number	Status	Subject	Publication No.	Date
269A-31	Incorporated	Revises Item No. 46 Table 2-2, Consumable Materials (Maintenance Supplies).		22 Dec 2014
269A-32	Incorporated	Revises Item No. 140 and adds Item No. 155 and 156 to Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-2	22 Dec 2014
269A-33	Incorporated	Revises paragraph 10-83, Periodic and Overspeed Inspection of Lower Coupling Drive Shaft.	CSP-C-2	22 Dec 2014
269A-34	Incorporated	Revises Table 10-4, Magnetic Particle Technique.	CSP-C-2	22 Dec 2014
269A-35	Incorporated	Revises step 24. of What to Inspect - 100-hour Inspection to Table B-2, Periodic Inspections.	CSP-C-2	22 Dec 2014
269A-36	Incorporated	Adds What to Inspect - 150-hour Inspection to Table B-2, Periodic Inspections.	CSP-C-2	22 Dec 2014
269A-37	Incorporated	Revises step 5. of What to Inspect - 300-hour Inspection, Table B-2, Periodic Inspections.	CSP-C-2	22 Dec 2014
269A-38	Incorporated	Revises Appx. C Part 6 Title page.	CSP-C-2	9 Mar 2015
269A-39	Incorporated	Revises note in paragraph 1-1, General, and paragraph 1-2, Landing Gear Differences.	CSP-C-2	9 Mar 2015
269A-40	Incorporated	Adds Item No. 10. to Table 1-2. Repair Materials.	CSP-C-2	9 Mar 2015
269A-41	Incorporated	Revises step o. of paragraph 5-3, Reassembly.	CSP-C-2	9 Mar 2015
269A-42	Incorporated	Revises note in paragraph 5-3, Reassembly, and step e. of paragraph 5-4, Damper Assembly Charging.	CSP-C-2	9 Mar 2015
269A-43	Incorporated	Revises step c. of paragraph 5-5A, Load/Stroke Inspection.	CSP-C-2	9 Mar 2015
269A-44	Incorporated	Revises step c. of paragraph 5-5A, Load/Stroke Inspection.	CSP-C-2	9 Mar 2015
269A-45	Incorporated	Adds new step d. to paragraph 5-6, Final Preparation.	CSP-C-2	9 Mar 2015

Number	Status	Subject	Publication No.	Date
269A-46	Incorporated	Revises paragraph 2-29, Lubrication of Sealed Bearings - General.		13 Jul 2015
269A-47	Incorporated	Revises paragraph 2-29, Lubrication of Sealed Bearings - General.		13 Jul 2015
269A-48	Incorporated	Revises Items No. 3 and 9 of Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-2	13 Jul 2015
269A-49	Incorporated	Adds a new inspection to Table 2-2A, Inspection of Ball Bearings and Roller Bearings.	CSP-C-2	13 Jul 2015
269A-50	Incorporated	Revises Item No. 9 of Table 2-4, Ground Support Equipment and Special Tools.	CSP-C-2	13 Jul 2015
269A-51	Incorporated	Revises Items No. 34 and 35 of Table 2-4, Ground Support Equipment and Special Tools.	CSP-C-2	13 Jul 2015
269A-52	Incorporated	Revises of paragraph 10-10, Repair and Corrosion Treatment of Oil-Filled Main Rotor Drive Shaft.	CSP-C-2	13 Jul 2015
269A-53	Incorporated	Revises Figure 10-3, Main Rotor Driveshaft Inspection Limits and Paint Scheme (Sheet 1 of 3).	CSP-C-2	13 Jul 2015
269A-54	Incorporated	Adds new paragraph 10-17A, Main Rotor Transmission Oil Seal Collar Usage.	CSP-C-2	13 Jul 2015
269A-55	Incorporated	Revises Figure 10-4, Main Transmission – Major Drive and Housing Components (cutaway side view).	CSP-C-2	13 Jul 2015
269A-56	Incorporated	Revises paragraph 10-19, Inspection of Installed Main Transmission.	CSP-C-2	13 Jul 2015
269A-57	Incorporated	Adds paragraph 10-19B, Replacement of Pinion Shaft Oil Seal.	CSP-C-2	13 Jul 2015
269A-58	Incorporated	Revises of paragraph 10-23, Installation of Main Transmission.	CSP-C-2	13 Jul 2015
269A-59	Incorporated	Revises Figure 10-7, Belt Drive Clutch Control Installation.	CSP-C-2	13 Jul 2015
269A-60	Incorporated	Revises Figure 10-7, Belt Drive Clutch Control Installation (Sheet 2 of 5).	CSP-C-2	13 Jul 2015
269A-61	Incorporated	Revises Figure 10-7, Belt Drive Clutch Control Installation (Sheet 3 of 5).	CSP-C-2	13 Jul 2015

Number	Status	Subject	Publication No.	Date
269A-62	Incorporated	Revises Figure 10-7, Belt Drive Clutch Control Installation (Sheet 4 of 5).	CSP-C-2	13 Jul 2015
269A-63	Incorporated	Revises Figure 10-7, Belt Drive Clutch Control Installation (Sheet 5 of 5).	CSP-C-2	13 Jul 2015
269A-64	Incorporated	Revises paragraph 10-30, 50 Hour Inspection of 269A5483 and 269A5590 Spring Assemblies.	CSP-C-2	13 Jul 2015
269A-65	Incorporated	Revises paragraph 10-31, Disassembly and Inspection of 269A5483 and 269A5590 Clutch Assemblies.	CSP-C-2	13 Jul 2015
269A-66	Incorporated	Revises paragraph 10-48, Removal of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-67	Incorporated	Revises paragraph 10-50, Inspection of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-68	Incorporated	Revises paragraph 10-50, Inspection of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-69	Incorporated	Revises paragraph 10-51, Inspection and Lubrication of Installed H-Frame Bearings and paragraph 10-52, Reassembly of Late Model Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-70	Incorporated	Revises paragraph 10-52, Reassembly of Late Model Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-71	Incorporated	Revises paragraph 10-53, Reassembly of Early Model Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-72	Incorporated	Revises paragraph 10-54, Installation of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-73	Incorporated	Revises paragraph 10-54, Installation of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-74	Incorporated	Revises paragraph 10-54, Installation of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-75	Incorporated	Revises paragraph 10-54, Installation of Belt Drive Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-76	Incorporated	Revises paragraph 10-58, Inspection of Belt Drive Transmission V-Belts.	CSP-C-2	13 Jul 2015
269A-77	Incorporated	Revises Figure 10-25, Adapter-Mounted Idler Pulley – Assembly Detains.	CSP-C-2	13 Jul 2015

Number	Status	Subject	Publication No.	Date
269A-78	Incorporated	Revises paragraph 10-66, Servicing of Idler Pulley Bearings.	CSP-C-2	13 Jul 2015
269A-79	Incorporated	Revises paragraph 10-67, Reassembly of Idler Pulley Assembly.	CSP-C-2	13 Jul 2015
269A-80	Incorporated	Revises paragraph 10-68, Installation of Adapter-Mounted Idler Pulley Assembly.	CSP-C-2	13 Jul 2015
269A-81	Incorporated	Revises Figure 10-27A, One-Piece Hub Upper Pulley Assembly.	CSP-C-2	13 Jul 2015
269A-82	Incorporated	Revises Figure 10-27B, One-Piece Hub Upper Pulley Assembly (Assembled View).	CSP-C-2	13 Jul 2015
269A-83	Incorporated	Revises paragraph 10-75, Reassembly of Upper Pulley Assembly – Three-Piece Hub/Spacer.	CSP-C-2	13 Jul 2015
269A-84	Incorporated	Revises paragraph 10-76, Reassembly of Upper Pulley Assembly – One-Piece Hub.	CSP-C-2	13 Jul 2015
269A-85	Incorporated	Revises paragraph 10-77B, Upper Pulley Coating Repair.	CSP-C-2	13 Jul 2015
269A-86	Incorporated	Revises paragraph 10-81B, Lower Pulley Coating Repair.	CSP-C-2	13 Jul 2015
269A-87	Incorporated	Revises paragraph 10-82, Removal and Installation of Lower Pulley Drive Shaft.	CSP-C-2	13 Jul 2015
269A-88	Incorporated	Revises paragraph 10-92, Removal of LTS Tail Rotor Transmission.	CSP-C-2	13 Jul 2015
269A-89	Incorporated	Revises paragraph 10-93A, Periodic Torque Check of Driven Spline Sleeve Retaining Nut.	CSP-C-2	13 Jul 2015
269A-90	Incorporated	Revises paragraph 10-94A, Repair of Elongated Bellcrank Attachment Hole.	CSP-C-2	13 Jul 2015
269A-91	Incorporated	Revises Figure 10-32, Replacement of LTS Tail Rotor Transmission Accessories.	CSP-C-2	13 Jul 2015
269A-92	Incorporated	Revises paragraph 10-96, Installation of LTS Tail Rotor Driveshaft and Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-93	Incorporated	Revises paragraph 10-96, Installation of LTS Tail Rotor Driveshaft and Transmission Assembly.	CSP-C-2	13 Jul 2015
269A-94	Incorporated	Revises paragraph 10-102, Replacement of Wear Sleeve on Tail Rotor Driveshaft.	CSP-C-2	13 Jul 2015

Number	Status	Subject	Publication No.	Date
269A-95	Incorporated	Revises paragraph 10-107, Replacement of LTS Tail Rotor Driveshaft Forward or Aft Bumper Plug.	CSP-C-2	13 Jul 2015
269A-96	Incorporated	Revises paragraph 10-110, Removal of HTS Tail Rotor Transmission.	CSP-C-2	13 Jul 2015
269A-97	Incorporated	Revises Figure 10-37, HTS Tail Rotor Drive Assembly.	CSP-C-2	13 Jul 2015
269A-98	Incorporated	Revises paragraphs 10-111, Maintenance of HTS Tail Rotor Transmission, 10-112A, Repair of Housing Support Arm, and 10-113, Installation of HTS Tail Rotor Transmission.	CSP-C-2	13 Jul 2015
269A-99	Incorporated	Revises Item No. 6 Table 2-1, Servicing Materials (Operating Supplies).	CSP-C-2	13 Jul 2015
269A-100	Incorporated	Revises Table 2-1, Servicing Materials (Operating Supplies).	CSP-C-2	13 Jul 2015
269A-101	Incorporated	Rescinds Temporary Revision No. 269A-29 and revises step 5. of Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection.	CSP-C-2	14 Jul 2015
269A-102	Incorporated	Adds step 12. to Table B-2, Periodic Inspections, What to Inspect - 400-Hour Inspection.	CSP-C-2	14 Jul 2015
269A-103	Incorporated	Rescinds Temporary Revision No. 269A-30 and revises step 4. of Table B-2, Periodic Inspections, What to Inspect - 600-Hour Inspection.	CSP-C-2	14 Jul 2015
269A-104	Incorporated	Adds new paragraphs 8-76A, Removal of Torque Tube Installation, 8-76B, Inspection of Torque Tube Installation, 8-76C, Removal and Installation of Torque Tube Bearings, and 8-76D, Installation of Torque Tube Installation.	CSP-C-2	04 Aug 2015
269A-105	Incorporated	Revises Table 10-2, Troubleshooting Belt Drive Transmission Vibration.	CSP-C-2	20 Aug 2015
269A-106	Incorporated	Revises paragraph 10-47, Periodic Check of Torque of Upper Pulley Aft Pinion Nut of Aft Locknut.	CSP-C-2	20 Aug 2015
269A-107	Incorporated	Revises paragraph 10-47, Periodic Check of Torque of Upper Pulley Aft Pinion Nut of Aft Locknut.	CSP-C-2	20 Aug 2015
269A-108	Incorporated	Revises paragraph 10-47, Periodic Check of Torque of Upper Pulley Aft Pinion Nut of Aft Locknut.	CSP-C-2	20 Aug 2015

Number	Status	Subject	Publication No.	Date
269A-109	Incorporated	Rescinds Temporary Revision No. 269A-74 and revises paragraph 10-54, Installation of Belt Drive Transmission Assembly.	CSP-C-2	20 Aug 2015
269A-110	Incorporated	Revises step 26. and 27. of Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection.	CSP-C-2	20 Aug 2015
269A-111	Incorporated	Revises step 6. of Table B-3, Requirements at Times Other Than Table B-2 Time Intervals.	CSP-C-2	20 Aug 2015
269A-112	Active	Revises Figure 10-7. Belt Drive Clutch Control Installation (Sheet 1 of 5).	CSP-C-2	29 Feb 2016
269A-113	Active	Revises Figure 10-7. Belt Drive Clutch Control Installation (Sheet 5 of 5).	CSP-C-2	29 Feb 2016
269A-114	Active	Revises paragraph 10-26, Removal of Belt Drive Clutch Control Spring Assembly.	CSP-C-2	29 Feb 2016
269A-115	Active	Revises paragraph 10-29, Inspection of Installed Clutch Control Assemblies.	CSP-C-2	29 Feb 2016
269A-116	Active	Revises paragraph 10-36, Installation and Adjustment of Belt Drive Clutch Control Installation.	CSP-C-2	29 Feb 2016
269A-117	Active	Revises paragraph 10-36, Installation and Adjustment of Belt Drive Clutch Control Installation.	CSP-C-2	29 Feb 2016
269A-118	Active	Revises step 48. of Table B-2, Periodic Inspections, What to Inspect - 100-hour Inspection.	CSP-C-2	29 Feb 2016
269A-119	Active	Revises Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection by adding steps 49 and 50.	CSP-C-2	3 Mar 2016
269A-120	Active	Revises paragraph 8-62, Rigging of Cyclic and Collective Pitch Controls.	CSP-C-2	3 Mar 2016
269A-121	Active	Adds paragraph 8-111A, Inspection of Main Rotor Flight Control Rod.	CSP-C-2	3 Mar 2016
269A-122	Active	Revises paragraph 8-88, Inspection of Rod End and Self-Aligning Bearings.	CSP-C-2	3 Mar 2016
269A-123	Active	Adds new step g. to paragraph 9-42, Removal, Inspection, and Installation of Tail Rotor Control Rod and Swashplate Bellcrank.	CSP-C-2	3 Mar 2016
269A-124	Active	Adds Item No. 157 and 158 to Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-2	3 Mar 2016
269A-125	Active	Revises Table B-1, Daily Inspection - Before First Flight of the Day, What to Inspect (Power OFF), FRONT - Canopy and Pilot's Compartment by adding new step 13. and renumbering subsequent steps.	CSP-C-2	30 Jun 2016

Number	Status	Subject	Publication No.	Date
269A-126	Active	Revises Table B-1, Daily Inspection - Before First Flight of the Day, What to Inspect (Power OFF), RIGHT SIDE - Pilot's Compartment and Canopy by adding new step 3. and renumbering subsequent steps.	CSP-C-2	30 Jun 2016
269A-127	Active	Revises Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection by adding steps 51. and 52.	CSP-C-2	30 Jun 2016
269A-128	Active	Revises paragraph 13-18, General, and adds new paragraph 13-18A, Inspection.	CSP-C-2	30 Jun 2016
269A-129	Active	Adds Item No. 159 to Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-2	30 Jun 2016
269A-130	Active	Adds new paragraph 8-68A, Inspection of Collective Friction Installation.	CSP-C-2	30 Nov 2016
269A-131	Active	Revises Table B-2, Periodic Inspections, What to Inspect – 100-Hour Inspection by adding step 11A.	CSP-C-2	30 Nov 2016
269C-1	Incorporated	New Warning Related to the use of components from aircraft with crash damage.	CSP-C-10	Aug 2011
269C-2	Incorporated*	Caution related to fretting that may occur in the Ring Gear Carrier Assembly P/N 269A5194.	CSP-C-13A	12 Dec 11
269C-3	Incorporated*	Incorporates a Ring Gear Mounting Surface Inspection for fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C-13A	12 Dec 11
269C-4	Incorporated*	Incorporates a Note to gear mating areas for fretting and adds inspection for gear mating areas for cracks of Ring Gear Carrier Assembly P/N 269A5194	CSP-C-13A	12 Dec 11
269C-5	Incorporated*	Incorporates procedures to repair Ring Gear Carrier Assembly P/N 269A5194 fretting that may occur	CSP-C-13A	12 Dec 11
269C-6	Incorporated*	Incorporates changes to maintenance instructions for ring gear to carrier assembly due to fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C-13A	12 Dec 11
269C-7	Incorporated	100-Hour Periodic Inspection Requirement	CSP-C-10	15 Mar 12
269C-8	Incorporated	400-Hour Periodic Inspection Requirement	CSP-C-10	15 Mar 12
269C-9	Incorporated	Adds step to inspect the Damper Assembly	CSP-C-10	1 Mar 13

* Data moved from HMI to CMM

Number	Status	Subject	Publication No.	Date
269C-10	Incorporated	Incorporates changes to Disassembly Inspection and Reassembly of Tail Rotor Driveshaft Damper Block.	CSP-C-10	1 Mar 13
269C-11	Incorporated	100-Hour Periodic Inspection Requirement.	CSP-C-10	1 Mar 13
269C-12	Incorporated	Adds new step to inspect the tail rotor damper block assembly.	CSP-C-10	26 Aug 13
269C-13	Incorporated	Updates inspection of tail rotor damper block and adds a new paragraph to inspect installed damper assembly.	CSP-C-10	26 Aug 13
269C-14	Incorporated	Updates inspection of splined drive sleeve.	CSP-C-10	26 Aug 13
269C-15	Incorporated	Updates inspection of driven spline.	CSP-C-10	26 Aug 13
269C-16	Incorporated	Modifies Table 2-1. Servicing Materials (Operating Supplies), Item No. 2., 3., and 6.	CSP-C-10	24 Jan 2014
269C-17	Incorporated	Adds Footnote 9. to Table 2-1. Servicing Materials (Operating Supplies).	CSP-C-10	24 Jan 2014
269C-18	Incorporated	Replaces Figure 2-9. Lubrication Chart (Sheet 1 of 5).	CSP-C-10	24 Jan 2014
269C-19	Incorporated	Replaces Figure 2-13. Sample Lubrication Check Sheet (Sheet 1 of 3).	CSP-C-10	24 Jan 2014
269C-20	Incorporated	Revises step a of paragraph 5-5, Leakage Check and adds new paragraph 5-5A, Load/Stroke Inspection to Section 5, Reassembly, Charging and Leakage Check.	CSP-C-10	15 Apr 2014
269C-21	Incorporated	Revises step c. of paragraph 13-13, Inspection of Main Rotor Mast.	CSP-C-10	6 Aug 2014
269C-22	Incorporated	Revises step 72. of Table B-2, Periodic Inspections, What to Inspect – 100-Hour Inspection.	CSP-C-10	6 Aug 2014
269C-23	Incorporated	Revises steps g. and h. of paragraph 10-26, Inspection of Clutch Control Installation.	CSP-C-10	6 Aug 2014
269C-24	Incorporated	Revises step 58. of Table B-2, Periodic Inspections, What to Inspect – 100-hour Inspection.	CSP-C-10	6 Aug 2014

Number	Status	Subject	Publication No.	Date
269C-25	Incorporated	Replaces Figure 9-1. Tail Rotor and Control System (Sheet 1 of 2).	CSP-C-10	9 Mar 2015
269C-26	Incorporated	Revises steps b. and c. and adds steps d. to paragraph 9-33, Inspection of Tail Rotor Control Pedal Installation.	CSP-C-10	9 Mar 2015
269C-27	Rescinded	Revises step 20. of Table B-2, Periodic Inspections, What to Inspect – 100-hour Inspection.	CSP-C-10	9 Mar 2015
269C-28	Rescinded	Revises step 4. of Table B-2, Periodic Inspections, What to Inspect – 800-hour Inspection.	CSP-C-10	9 Mar 2015
269C-29	Incorporated	Revises Item No. 33 and 38 of Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-10	22 Dec 2014
269C-30	Incorporated	Revises Item No. 43 of Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-10	22 Dec 2014
269C-31	Incorporated	Revises Item No. 119 of Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-10	22 Dec 2014
269C-32	Incorporated	Revises paragraph 10-74, Periodic and Overspeed Inspection of Lower Coupling Drive Shaft.	CSP-C-10	22 Dec 2014
269C-33	Incorporated	Revises Table 10-3, Magnetic Particle Technique.	CSP-C-10	22 Dec 2014
269C-34	Incorporated	Adds What to Inspect - 150-hour Inspection to Table B-2, Periodic Inspections.	CSP-C-10	22 Dec 2014
269C-35	Incorporated	Revises step 1. of What to Inspect - 150-hour Inspection to Table B-2, Periodic Inspections.	CSP-C-10	22 Dec 2014
269C-36	Incorporated	Adds Item No. 9. to Table 1-2. Repair Materials.	CSP-C-10	9 Mar 2015
269C-37	Incorporated	Revise note of paragraph 5-3, Reassembly.	CSP-C-10	9 Mar 2015
269C-38	Incorporated	Revise note of paragraph 5-4, Damper Assembly Charging.	CSP-C-10	9 Mar 2015
269C-39	Incorporated	Revises step c. of paragraph 5-5A, Load/Stroke Inspection.	CSP-C-10	9 Mar 2015
269C-40	Incorporated	Revises step c. of paragraph 5-5A, Load/Stroke Inspection.	CSP-C-10	9 Mar 2015

Number	Status	Subject	Publication No.	Date
269C-41	Incorporated	Adds new step d. to paragraph 5-6, Final Preparation.	CSP-C-10	9 Mar 2015
269C-42	Incorporated	Revises paragraph 2-28, Lubrication of Sealed Bearings.	CSP-C-10	13 Jul 2015
269C-43	Incorporated	Revises paragraph 2-28, Lubrication of Sealed Bearings.	CSP-C-10	13 Jul 2015
269C-44	Incorporated	Adds a new tool to Table 2-4, Ground Support Equipment and Special Tools.	CSP-C-10	13 Jul 2015
269C-45	Incorporated	Adds a new inspection to Table 2-6, Inspection of Ball Bearings and Roller Bearings.	CSP-C-10	13 Jul 2015
269C-46	Incorporated	Revises Figure 10-3A, Oil Seal Collar Differences.	CSP-C-10	13 Jul 2015
269C-47	Incorporated	Revises paragraph 10-17, Inspection of Installed Main Transmission.	CSP-C-10	13 Jul 2015
269C-48	Incorporated	Adds new paragraph 10-17A, Replacement of Pinion Shaft Oil Seal.	CSP-C-10	13 Jul 2015
269C-49	Incorporated	Revises paragraph 10-45, Inspection of Belt Drive Transmission Assembly.	CSP-C-10	13 Jul 2015
269C-50	Incorporated	Revises paragraph 10-46, Inspection and Lubrication of Installed H-Frame Bearings	CSP-C-10	13 Jul 2015
269C-51	Incorporated	Revises paragraph 10-58, Servicing of Idler Pulley Bearings.	CSP-C-10	13 Jul 2015
269C-52	Incorporated	Revises Table 2-1, Servicing Materials (Operating Supplies).	CSP-C-10	13 Jul 2015
269C-53	Incorporated	Revises Table 2-1, Servicing Materials (Operating Supplies).	CSP-C-10	13 Jul 2015
269C-54	Incorporated	Rescinds Temporary Revision No. 269C-27 and revises step 19. of Table B- 2, Periodic Inspections, What to Inspect - 100-Hour Inspection.	CSP-C-10	14 Jul 2015
269C-55	Incorporated	Adds step 16. to Table B- 2, Periodic Inspections, What to Inspect - 400-Hour Inspection.	CSP-C-10	14 Jul 2015
269C-56	Incorporated	Rescinds Temporary Revision No. 269C-28 and revises step 4. of Table B- 2, Periodic Inspections, What to Inspect - 800-Hour Inspection.	CSP-C-10	14 Jul 2015

Number	Status	Subject	Publication No.	Date
269C-57	Incorporated	Adds paragraphs 8-72A, Removal of Torque Tube Installation, 8-72B, Inspection of Torque Tube Installation, 8-72C, Removal and Installation of Torque Tube Bearings, and 8-72D, Installation of Torque Tube Installation.	CSP-C-10	04 Aug 2015
269C-58	Incorporated	Revises paragraph 10-42, Periodic Check of Torque of Upper Pulley Aft Pinion Nut.	CSP-C-10	20 Aug 2015
269C-59	Incorporated	Revises paragraph 10-42, Periodic Check of Torque of Upper Pulley Aft Pinion Nut.	CSP-C-10	20 Aug 2015
269C-60	Incorporated	Revises paragraph 10-48, Installation of Belt Drive Assembly.	CSP-C-10	20 Aug 2015
269C-61	Incorporated	Revises sub-step (d) of step 47., Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection.	CSP-C-10	20 Aug 2015
269C-62	Incorporated	Revises step 5. of Table B-3, Special Inspections, Requirements at Times Other Than Table B-2 Time Intervals.	CSP-C-10	20 Aug 2015
269C-63	Active	Revises paragraph 10-23, Removal of Belt Drive Clutch Control Installation.	CSP-C-10	29 Feb 2016
269C-64	Active	Revises Figure 10-7, Belt Drive Clutch Control Installation (Sheet 1 of 4), renumbers subsequent figure sheet numbers, and adds new Figure 10-7, Belt Drive Clutch Control Installation (Sheet 5 of 5).	CSP-C-10	29 Feb 2016
269C-65	Active	Revises paragraph 10-23, Removal of Belt Drive Clutch Control Installation and paragraph 10-26, Inspection of Clutch Control Installation.	CSP-C-10	29 Feb 2016
269C-66	Active	Revises paragraph 10-30, Installation and Adjustment of Belt Drive Clutch Control Installation.	CSP-C-10	29 Feb 2016
269C-67	Active	Revises step 58. of Table B-2, Periodic Inspections, What to Inspect - 100-hour Inspection.	CSP-C-10	29 Feb 2016
269C-68	Active	Revises Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection by adding steps 82. and 83.	CSP-C-10	3 Mar 2016
269C-69	Active	Revises paragraph 8-57, Final Rigging Adjustments.	CSP-C-10	3 Mar 2016
269C-70	Active	Adds paragraph 8-107A, Inspection of Main Rotor Flight Control Rod.	CSP-C-10	3 Mar 2016
269C-71	Active	Revises paragraph 8-83, Inspection of Rod End and Self-Aligning Bearings.	CSP-C-10	3 Mar 2016
269C-72	Active	Adds new step n. to paragraph 9-36, Removal, Inspection, and Installation of Tail Rotor Control Rods.	CSP-C-10	3 Mar 2016

Number	Status	Subject	Publication No.	Date
269C-73	Active	Adds Item No. 139 and 140 to Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-10	3 Mar 2016
269C-74	Active	Revises Table B-2, Periodic Inspections, What to Inspect - 100-Hour Inspection by adding steps 84. and 85.	CSP-C-10	30 Jun 2016
269C-75	Active	Revises paragraph 13-17, Removal and Installation of Cabin Doors, and adds new paragraph 13-17A, Inspection.	CSP-C-10	30 Jun 2016
269C-76	Active	Adds Item No. 141 to Table 2-2, Consumable Materials (Maintenance Supplies).	CSP-C-10	30 Jun 2016
269C-77	Active	Adds new paragraph 8-65A, Inspection of Collective Friction Installation.	CSP-C-10	30 Nov 2016
269C-78	Active	Revises Table B-2, Periodic Inspections, What to Inspect – 100-Hour Inspection by adding step 16 A.	CSP-C-10	30 Nov 2016
269I-A-1	Incorporated	Modifies Index Number -10 in Figure 18	CSP-C-7 (V1)	18 Jun 13
269I-A-2	Incorporated	Modifies Index Numbers -38, and -44 in Figure 18	CSP-C-7 (V1)	18 Jun 13
269I-A-3	Incorporated	Revises Index Numbers -1, -13 and -15 of Figure 80. Torque Tube Installation.	CSP-C-7 (V1)	01 Jun 2015
269I-A-4	Incorporated	Revises Figure 80, Torque Tube Installation.	CSP-C-7 (V1)	04 Aug 2015
269I-A-5	Incorporated	Adds Index Number -26 to Figure 80. Torque Tube Installation parts list.	CSP-C-7 (V1)	04 Aug 2015
269I-A-6	Active	Revises Figure 30. Belt Drive Clutch Control Installation (TH-55A and 269A).	CSP-C-7 (V1)	29 Feb 2016
269I-A-7	Active	Revises index numbers -10 and -13 of Figure 30. Belt Drive Clutch Control Installation (TH-55A and 269A) Parts List.	CSP-C-7 (V1)	29 Feb 2016
269I-C-1	Incorporated	Adds a new main rotor bearing spacer tube, P/N 269A1318-008, S/N 26 and subsequent	CSP-C-9	12 Dec 11
269I-C-2	Incorporated	Modifies Index Numbers -18, and -28 in Figure 3-4	CSP-C-9	18 Jun 13
269I-C-3	Incorporated	Modifies Index Number -33 in Figure 3-4	CSP-C-9	18 Jun 13
269I-C-4	Incorporated	Updates Figure 2-9. Faining Assembly (S/N 1736 & Subs.)	CSP-C-9	20 Aug 2013

Number	Status	Subject	Publication No.	Date
269I-C-5	Incorporated	Adds Index Numbers -19, -21 and -22 in Figure 2-9.	CSP-C-9	20 Aug 2013
269I-C-6	Incorporated	Updates Figure 3-4. Gear Box Assembly – Tail Rotor	CSP-C-9	20 Aug 2013
269I-C-7	Incorporated	Adds Index Number -39 in Figure 3-4.	CSP-C-9	20 Aug 2013
269I-C-8	Incorporated	Revises Index Numbers -5 and -6 of Figure 3-7B. Extended Hub Upper Pulley – Belt Drive Transmission.	CSP-C-9	13 Jul 2015
269I-C-9	Rescinded	Revises Index Number -2 of Figure 4-15. Torque Tube – Collective Pitch Control.	CSP-C-9	01 Jun 2015
269I-C-10	Incorporated	Revises Figure 4-15. Torque Tube – Collective Pitch Control.	CSP-C-9	04 Aug 2015
269I-C-11	Incorporated	Rescinds Temporary Revision No. 269I-C-9, revises Index Number -2, and adds Index Number -13 to Figure 4-15. Torque Tube – Collective Control parts list.	CSP-C-9	04 Aug 2015
269I-C-12	Active	Revises Figure 3-14. Clutch Control Installation.	CSP-C-9	29 Feb 2016

This page is intentionally left blank.