



# SCHWEIZER SERVICE LETTER

## - SERVICE ALERT -

**SUBJECT:** ENGINE/TRANSMISSION OIL COOLER IMPELLERS

**MODELS AFFECTED:** Models 269D Helicopters

**REFERENCE:** Model 269D and 269D Configuration "A" HMI Section 6 and Appendix B and Configuration "M" HMI Chapters 7 and 30.

Customer Support has received a number of reports that 269D4526 series impellers have experienced cracked and separated air vanes. Schweizer recommends that all operators perform the maintenance actions outlined in Service Bulletin DB-027 (DB-027 is a mandatory service bulletin).

Schweizer strongly recommends this inspection be done on a more frequent basis: Recommended interval is before the first flight of each day.

Investigation into this important matter is continuing and a revision of DB-027 is forthcoming.

This Service Letter has been mailed to all US registered owners and all Schweizer Service Centers and Distributors.

Service Centers and Distributors outside the United States are asked to advise owners of affected aircraft in their respective areas of this Service Letter, and to forward the requested data to Schweizer.