



**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-129

DATE 15 February 1982

PAGE 1 OF 1

TOTALLY INCORPORATED INTO HMI (APPB)

TO—All owners and operators of Hughes Helicopters

SUBJECT: PN 269A5050-74 IDLER PULLEY BEARING AND PN 269A5050-78
BELT DRIVE H-FRAME UPPER BEARING - SERVICE LIFE
INCREASED TO 3000 HOURS

MODELS AFFECTED: Model 269 Series Helicopters equipped with
PN 269A5447 Series Idler Pulley Assembly
and/or PN 269A5593 Series H-Frame Assembly

Reference

269 Series - Basic HMI Issued 1 April 1980
269 Series - HMI Appendix B, Issued 1 April 1980

The service life of the PN 269A5050-74 idler pulley bearing and the PN 269A5050-78 H-frame upper bearing has been increased to 3000 hours. This information is to be considered as a part of the HMI and will be incorporated in Table B-4 Component Overhaul Schedule of the next scheduled revision to the above referenced HMI Appendix B.

It is to be noted that the replacement schedule for the PN 269A5050-57 H-frame lower bearing remains at 1800 hours time in service.

Edward Koch, Manager
Customer Service Department
Hughes Helicopters, Inc.

Customer Service Department