



SCHWEIZER SERVICE INFORMATION LETTER

Letter No. L-143

Date: 2 Jan 1987

Page 1 of 1

TO: All owners and operators of 269 Series Helicopters.

SUBJECT: OVERHAUL SCHEDULE UPDATE.

MODELS AFFECTED: All 269 Series Helicopters equipped with a 269A5175-15 or -17 Main Transmission or a 269A5103-21 or -31 Input Pinion Assembly.

REFERENCE: 269 Series - HMI Appendix B, Reissued 15 August 1982

It has come to SAC'S attention that the overhaul schedule of several components have not been incorporated into Table B-4 of the 269 Series Appendix B. A revision of Appendix B, to incorporate this and other pertinent information, is presently in progress. In the interim, Table 1 of Service Revision R-6 shall serve as a supplement to the Component overhaul schedule provided in Appendix B.

It should be noted that all rules and notes which apply to Table B-4, also apply to its supplement. In addition, Table B-4 and all applicable service bulletins should continue to be used to determine the overhaul schedules of components which are not included in the supplement.

The information given in this Service Information Letter and in Service Revision R-6 are to be considered as part of the HMI and will be incorporated at the next scheduled revision of 269 Series HMI Appendix B.

REFERENCE SHEET

SERVICE INFORMATION NOTICES AND LETTERS

ACTION REFERENCE: Refer to Service Information Letter L-143
for additional overhaul schedules.

HMI REFERENCE: Insert this sheet in 269 Series
Appendix B, Section 2, Page 2-20a.

This reference sheet shall be kept as part of the manual
until the data is incorporated at the next revision of the
269 series Appendix B. (See Service Information Summary,
page i of HMI Appendix B.)