

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-62

DATE October 8, 1971

PAGE 1 OF 1

TOTALLY Incorporated in HMI

TO—All owners and operators of Hughes Helicopters

SUBJECT: BENDIX ELECTRICAL COMPONENTS DIVISION -
SERVICE BULLETIN NO. 551, DATED SEPTEMBER 1971 -
NEW DISTRIBUTOR BLOCK LUBRICANT

MODELS AFFECTED: All 269 Series Helicopters

Your attention is directed to the subject information reprinted as a part of this Service Information Letter.

The instructions provide information on an improved lubricant to be used on distributor block bushings and felt washers. Data is also given defining the method to be used to clean and relubricate the affected parts. The manufacturer recommends that all owners and operators comply with the Bulletin at their earliest convenience.



Edward Koch
Customer Service Department
Hughes Tool Company - Aircraft Division