



**HUGHES  
SERVICE INFORMATION  
LETTER**

LETTER NO. L-8

DATE October 4, 1966

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: ILLUMINATION INTENSITY - ENGINE INSTRUMENTS

MODELS AFFECTED: 269A-1 Serial No's. 0019 through 0041 and 269B  
Serial No's. 0145 through 0268

Engineering evaluation indicates that the light level on the engine instruments (fuel qty., fuel pressure, cht, engine oil temp. ammeter eng. oil press.) is below expected brilliance. Replacement of the existing four light tubes with ones of greater intensity provides the solution.

The tubes are easily installed by removing the circuit board, removing the old and installing the new tubes. The new light tube P/N AC 6455809 may be obtained on a gratis basis by contacting Helicopter Support Services, Parts Department. The Hughes Tool Company HSS Service Department recommends that owners and operators take advantage of the above as soon as possible.