



**SCHWEIZER
SERVICE INFORMATION
LETTER**

LETTER NO. L-80
DATE 1 April 1974
PAGE 1 OF 1

**SUBJECT: HIGH TIP SPEED TAIL ROTOR P/N 269A6004
--SPARE ASSEMBLY AND COMPONENT AVAILABILITY**

**REFERENCE: 269 Basic Handbook of Maintenance Instructions,
Issue 1 April 1973, Revision #2, 1 January 1974.
269 Series Illustrated Parts Catalog, Issue 1 March 1974**

MODELS AFFECTED: 269A, TH-55A, 269A-1 and 269B Helicopters

This Letter is to advise Owners and Operators that Hughes will no longer stock spare high tip-speed tail rotor assemblies or components of the high tip-speed system after 31 July 1975. This will provide adequate time so that the change over to the low speed tail rotor system kit may be scheduled with the least amount of inconvenience to the customer.

The low tip-speed tail rotor installation may be procured by ordering Hughes Kit P/N M10011.

Edward Koch, Manager
Customer Service Department
HUGHES HELICOPTERS
DIVISION OF SUMMA CORPORATION