

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-83
DATE 11 November 1974
PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: REPLACEMENT - TAIL ROTOR CONTROL PEDAL RETAINING PINS

MODELS AFFECTED: All 269A, A-1, TH-55A and B Model Helicopters;
269C Helicopter Serial No's 0001 through 0359.

REFERENCE: 269 Series - Basic HMI, Issued 1 April 1973;
Revision No. 2, 1 January 1974.

A new tail rotor pedal retaining pin PN 269A4596 has been authorized and is currently being installed on production aircraft. The new pin provides a more positive retention of the pedals and is less subject to deterioration in service. The new pin is usable on all 269 Series Helicopter with no modification required. The pins may be obtained by ordering them from your Hughes Service Center or Distributor.



Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California