

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-85

DATE 5/5/75

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: BENDIX FUEL INJECTION SYSTEM FLOW DIVIDER
INSTALLED ON HIO-360 SERIES ENGINES —
INSPECTION/MODIFICATION.

MODELS AFFECTED: All 269 Series Helicopters equipped with Flow Divider,
Part Numbers listed in Reference 2.


Reference

1. AVCO Lycoming Division —
Service Bulletin No. 382,
Dated January 17, 1975
2. Bendix Energy Controls Division —
Service Bulletin - Fuel System No. RS43,
Dated 16 December 1974.

This Service Information letter is to bring to the attention of owners and operators the provisions of References 1. and 2., reprinted in their entirety, as a part of this letter.

Reference 1. (AVCO) is a cover for Reference 2. Reference 2. outlines an inspection to be performed on the listed Flow Dividers to determine that the current gasket is installed. Further, a procedure for replacement of the gasket is given. The inspection and replacement is to be performed within the next 25 hours time in service.

Hughes recommends the provision of the Bulletin be complied with, within the prescribed time.



Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California