

**PUBLICATIONS INDEX**

**FOR**

**SCHWEIZER**

**MODELS 269C-1 HELICOPTERS**

**Publications Index No. CSP-P1-1**  
**Reissued 23 Jan 2020**

**Warning:**

This document, or an embodiment of it in any media, discloses information which is proprietary, is the property of Schweizer RSG and/or its subsidiaries, is an unpublished work protected under applicable copyright laws, and is delivered on the express condition that it is not to be used, disclosed, reproduced, in whole or in part (including reproduction as a derivative work), or used for manufacture for anyone other than Schweizer RSG and/or its subsidiaries without its written consent, and that no right is granted to disclose or so use any information contained herein. All rights reserved. Any act in violation of applicable law may result in civil and criminal penalties

Model 269C-1 - Publications Index

LIST OF EFFECTIVE PAGES

INSERT LATEST CHANGED PAGES, DESTROY SUPERSEDED PAGES.

<b>PAGE</b>	<b>ISSUED/REISSUED/REVISED</b>
Title .....	23 Jan 2020
i .....	23 Jan 2020
Section 1	
<b>Service Publications and Kits</b>	
1-1 thru 1-3 .....	23 Jan 2020
1-4 .....	25 Jan 2013
Section 2	
<b>Service Information Notices and Service Bulletins</b>	
2-1 .....	08 Feb 2005
2-2 .....	08 Feb 2005
2-3 .....	02 May 2013
2-4 .....	07 Dec 2012
2-5 .....	02 May 2013
2-6 .....	15 Apr 2014
Section 3	
<b>Service Information Letters and Service Letters</b>	
3-1 .....	07 Dec 2012
3-2 .....	08 Feb 2005
Section 4	
<b>Temporary Revisions</b>	
4-1 .....	30 Sep 2013
4-2 .....	15 Apr 2014

**SERVICE PUBLICATIONS AND KITS**

NOTE

The following index provides a complete list of publications available to support Schweizer RSG Models 269C-1 Helicopter.

Publication No.	Title	Issued/Reissued	Latest Revision
<b>MODEL 269C-1 PILOT'S FLIGHT MANUAL</b>			
CSP-C1-1	269C-1 Pilot's Flight Manual	Reissued 16 Jan 2019	---
<b>MODEL 269C-1 PILOT'S FLIGHT MANUAL SUPPLEMENTS</b>			
CSP-C1-1A	Instrument/Avionics Installations	03 Oct 1995	29 Mar 2001
CSP-C1-1B	Engine Overspeed Installation Part No. 269A4997-1	01 Dec 1995	13 Mar 1997
CSP-C1-1C	Cabin Heater Kit Installation Part No. 269A4451-1 or -3	01 Dec 1995	21 May 1997
CSP-C1-1D	OBSOLETE		
CSP-C1-1E	Cargo Hook Installation Kit Part No. 269A4971-39	20 Sep 1996	25 Aug 2005
CSP-C1-1F	Engine Winterization Kit	03 Mar 1997	---
CSP-C1-1G	Left-Hand Pilot-In-Command (PIC) Helicopter Assy.	23 Dec 1996	01 Apr 2005
CSP-C1-1H	Special Requirements for Aircraft Exported to China	04 Jun 2002	---
CSP-C1-1I	"STAR" System Startup RPM Limiter/Automatic Engagement/Rotor Low RPM Warning Installation	04 Jun 2002	24 Oct 2002
CSP-C1-1J	Rotorcraft Amphibious Float Landing Gear Part No. 269A4300-15	11 Aug 2004	01 Apr 2005
<b>MODEL 269C-1 HANDBOOK OF MAINTENANCE INSTRUCTIONS (HMI)</b>			
CSP-C1-2	Basic Handbook of Maintenance Instructions (Basic HMI)	14 Jul 1995	30 Sep 2013
	Section 1	14 Jul 1995	28 Mar 2003
	Section 2	14 Jul 1995	30 Sep 2013
	Section 3	14 Jul 1995/28 Mar 2003	30 Sep 2013

**MODEL 269C-1 HANDBOOK OF MAINTENANCE INSTRUCTIONS (HMI) (Cont)**

<u>Publication No.</u>	<u>Title</u>	<u>Issued/Reissued</u>	<u>Latest Revision</u>
	Section 4	14 Jul 1995/13 Dec 2004	30 Sep 2013
	Section 5	14 Jul 1995/28 Mar 2003	30 Sep 2013
	Section 6	14 Jul 1995	30 Sep 2013
	Section 7	14 Jul 1995	30 Sep 2013
	Section 8	14 Jul 1995/29 Jan 2007	30 Sep 2013
	Section 9	14 Jul 1995/29 Jan 2007	07 Dec 2012
	Section 10	14 Jul 1995/17 Oct 2008	30 Sep 2013
	Section 11	14 Jul 1995/02 May 2003	30 Sep 2013
	Section 12	14 Jul 1995	30 Sep 2013
	Section 13	14 Jul 1995	30 Sep 2013
	Section 14	14 Jul 1995	30 Sep 2013
	Section 15	14 Jul 1995	30 Sep 2013
	Section 16	14 Jul 1995	26 Feb 2010
	Section 17	14 Jul 1995	08 Sep 1995
CSP-C1-3	Optional Equipment (HMI Appendix A)	13 Jul 1999	30 Sep 2013
CSP-C1-4	Periodic Inspections Overhaul and Retirement Schedule and Weight and Balance Procedures (HMI Appendix B)	14 Jul 1995	30 Sep 2013
CSP-C1-5	Component Overhaul (HMI Appendix C)	Listed on each Part:	
	Part I-Deleted		07 Dec 2012
	Part II-Deleted		07 Dec 2012
	Part III-Landing Gear Damper	14 Jul 1995	30 Sep 2013
	Part IV-Tail Rotor Pitch Control Assembly	14 Jul 1995	30 Sep 2013
CSP-A-3	Corrosion Control Manual (HMI Appendix D)	30 Aug 1994	30 Sep 2013

**269C-1 ILLUSTRATED PARTS CATALOG (IPC)**

<u>Publication No.</u>	<u>Title</u>	<u>Issued/Reissued</u>	<u>Latest Revision</u>
CSP-C1-6	Illustrated Parts Catalog (IPC)	10 May 1996/11 Mar 2005	30 Sep 2013

**KITS**

<u>Publication No.</u>	<u>Title</u>	<u>Issued/Reissued</u>	<u>Latest Revision</u>
CKP-C-47.2	SA-269K-063-01 & -03, Exhaust Pipe Installation Kit	29 Sep 1994	30 Oct 2008
CKP-C-58	SA-269K-074-01, Cabin Heater Kit	05 Dec 1995	---
CKP-C-62.1	SA-269K-078-01, Cabin Heater Retrofit Kit	26 Jan 1996	30 Jan 1996
CKP-C-68.1	SA-269K-085-03 & -05, Auxiliary Fuel Tank Kits	03 Feb 1997	15 May 1997
CKP-C-71	SA-269K-088-01, -03, -05 & -07, Cabin Heater Kits	11 Apr 1997	---
	SA-269K-095 Kit-Oil Filler Dipstick Installation	17 Nov 1997	---
CKP-C-76	SA-269K-096 SAC/Lycoming Carburetor Kit	23 Apr 1998	---
	SA-269K-098, Switch Installation Kit-Weight-On-Skids	10 Jun 1998	---
	SA-269K-099, Reversing Trim Installation Kit	18 Aug 1998	---
	SA-269K-100, Tail Rotor-Elastomeric Bearing Kit	21 May 1999	---
	SA-269K-101, Rollover Fuel Vent Installation	08 Aug 2000	16 Aug 2000
	SA-269K-107, Installation of 269A3227 Bushing in Landing Gear Skid Tube	09 May 2002	---
CKP-C-82	SA-269K-088-09 & -011, Cabin Heater Kits	03 Jul 2003	---
CKP-C-108.3	SA-269K-108, Kit, Fuel Injection Conversion	09 Apr 2003	10 Oct 2008
CKP-C-110.2	SA-269K-110-01 & -013 Star System Kits	05 Aug 2003	17 Nov 2003
	SA-269K-111, Installation of 269A5590-15 Cable Sub-Assy.	07 Feb 2003	---
CKP-C-113.1	SA-269K-113-01, 269A3202-109/-110 Over Center Ground Handling Wheels Kit	08 Oct 2003	12 Sep 2008
	SA-269K-114, Retrofit Installation of 269A5800-1 Spring Assy.	23 Jan 2004	---
	SA-269DK-024 T/R Driveshaft Kit	20 Nov 2001	---

Reissued: 23 Jan 2020

1-3

**269C-1 COMPONENT MAINTENANCE MANUAL (CMM)**

<u>Publication No.</u>	<u>Title</u>	<u>Issued/Reissued</u>	<u>Latest Revision</u>
CSP-C1-5A	Component Manintenance Manual	25 Jan 2013	---

## SERVICE INFORMATION NOTICES AND SERVICE BULLETINS

- NOTES:**
- a. Check helicopter aircraft records to ensure that all applicable status † Service Information Notices and Service Bulletins have been accomplished. Obtain copy of document and perform applicable procedure(s) if compliance is not indicated.
  - b. Where conflicts exist between the Publications Index and the document (i.e. Notice or Bulletin), the document shall prevail.
  - c. Red letterhead Service Information Notices and Service Bulletins are mandatory and must be performed on the helicopter models indicated. Blue letterhead Service Information Notices are performed at owner's / operator's discretion.

---

### STATUS NOTATION KEY

- © Indicates document which is current. This document must be maintained as part of the Models 269C-1 Service Bulletin and Service Letter Set.
- † Indicates outdated Service Information Notice or Service Bulletin outlining one-time procedures. Check helicopter aircraft records for compliance, as applicable.
- k Indicates optional Kit Installation Instructions, available upon request (or when kit is ordered).
- ‡ Indicates optional Maintenance Information, available upon request only.
- ⇒ Indicates that Status is specified under Notes column.
-

Bulletin No.	Status Notation	Subject	Date Issued	Letterhead	Corresponding FAA AD Service Note	Notes
C1B-001.1	©	269A6050-005 Tail Rotor Pitch Control Assembly, Torque Verification of 269A6258 Nut, and Application of Torque Stripes	23 Jul 1996	Red		
C1B-002	©	One-Time Inspection of Tail Rotor Blades	29 Jan 1997	Red		
C1B-003	©	50-Hour Inspection of Main Rotor Blade Abrasion Strip	28 Jan 1997	Red		
C1B-004	©	Textron Lycoming Service Bulletin No. 527C (Recall of Piston Part No. LW-14077)	24 Jul 1997	Red		
C1B-005.1	©	Primer Hose Replacement	14 Jul 1998	Red		
C1B-006	©	Inspection of Main Transmission Pinion Splines; New Torque Check Requirement for Aft Pinion Nut	20 Mar 1998	Red		
C1B-007	©	One-Time Inspection of Main Rotor Hub and Shaft, and New Assembly Procedure	14 Jul 1998	Red		
C1B-008.1	©	Inspection of 269A5104-007 Main Transmission Ring Gears with Specific Serial Numbers and Reporting of Inspection Results	08 Jan 2001	Red		Refer to Models Affected for Serial Numbers



Models 269C-1 - Publications Index

Section 2  
Service Information Notices and Service Bulletins

Bulletin No.	Status Notation	Subject	Date Issued	Letterhead	Corresponding FAA AD Service Note	Notes
C1B-009.1	©	Tail Rotor Swashplate Shaft Inspection	14 Oct 1999	Red	2000-16-05	
C1B-010	©	Inspection/Replacement Criteria for Certain Upper H-Frame Bearings (Sikorsky P/N 269A5050-78)	18 Feb 2000	Red		
C1B-011	©	Textron Lycoming Special Advisory No. 62-1200	02 Jan 2001	Red		
C1B-012	©	One-Time Inspection for Condition and Modification of Certain Idler Pulley Support Assemblies	12 Mar 2001	Red		
C1B-013.1	©	Main Rotor Swashplate Bearings P/N 269A1301	14 Nov 2001	Red		Refer to Models Affected
C1B-014	©	One-Time Inspection of 269A2172-5 Aft Mast Support Tube Forward Fitting	09 Aug 2002	Red		
C1B-015	©	Modification of 269A5590-1 Clutch Spring Assembly	04 Nov 2003	Red		Refer to Models Affected
C1B-016.1	©	Support Bracket (269A8460-1) Throttle Bellcrank, Inspection for Cracks	24 Sep 2004	Red		Refer to Models Affected
C1B-017.1	©	Inspection and Modification of 269A7316-13 Lateral Control Trim Assembly	04 Mar 2005	Red	2005-10-12	Refer to Models Affected

Models 269C-1 - Publications Index

Section 2  
Service Information Notices and Service Bulletins

Bulletin No.	Status Notation	Subject	Date Issued	Letterhead	Corresponding FAA AD Service Note	Notes
C1B-018.1	©	Modification of Locknut/Hoist Eye Assembly	17 Mar 2006	Red		Refer to Models Affected
C1B-019.1	©	Tail Rotor Swashplate Bellcrank Assembly Safety Washer Installation	29 Jan 2007	Red		Refer to Models Affected
C1B-020	©	Slick Service Bulletin SB1-06A	29 Nov 2006	Red		Refer to Models Affected
C1B-021.1	©	Main Transmission Input Pinion Corrosion Protection	24 Aug 2010	Red		Refer to Models Affected
C1B-022.1	©	Tail Rotor Drive Shaft Splined Fittings Inspection	21 Apr 2008	Red		Refer to Models Affected
C1B-023	©	Precision Airmotive Mandatory Service Bulletin (PRS-107, Rev. 3)	28 Apr 2008	Red	2008-06-51	Refer to Models Affected
C1B-024.1	©	Throttle Control Restriction	24 Nov 2008	Red		Refer to Models Affected
C1B-025.1	©	Installation of Single Wheel Ground Handling Wheel Locking Device	26 Sep 2008	Red		Refer to Models Affected
C1B-026	©	Landing Gear Skid Tube Aft Sleeve Inspection	26 Sep 2008	Red		Refer to Models Affected
C1B-027	©	Fuel Strainer Leak Check	03 Oct 2008	Red		Refer to Models Affected
C1B-028	©	Modification of Cabin Door Hinges	24 Oct 2008	Red		Refer to Models Affected

Models 269C-1 - Publications Index

Section 2  
Service Information Notices and Service Bulletins

Bulletin No.	Status Notation	Subject	Date Issued	Letterhead	Corresponding FAA AD Service Note	Notes
C1B-029	©	Incorrect Grease Identification in Certain Serial Number Helicopters	09 Jan 2009	Red		Refer to Models Affected
C1B-030	©	Center Control Cover Contacting Lateral Cyclic Control Rod	24 Aug 2010	Red		Refer to Models Affected
C1B-031	©	Incorrect Bushing used in 269C-1 Flight Controls	24 Aug 2010	Red		Refer to Models Affected
C1B-032.1	©	Inspections and Modification of Tail Boom Support Strut Adjustable Diameter Bolt	28 Feb 2012	Red		Refer to Models Affected
C1B-033	©	Clevis Pin Chaffing of Fuel Tank	05 Jan 2011	Red		Refer to Models Affected
C1B-034.1	©	Inspection of Main Rotor Drive Thrust Bearing Journal Radium	06 Oct 2011	Red		Refer to Models Affected
C1B-035	©	Powertrain: One-Time Inspection of Belt Drive Idler Pulley Hardware for Presence and Security	04 Jan 2012	Red		Refer to Models Affected
C1B-036.1	©	Drivetrain: Tail Rotor Drive Shaft Splined Fittings - Perform a One-Time Inspection and Implement a Recurring Inspection for Wear	13 Feb 2012	Red		Refer to Models Affected
C1B-037	©	One-Time Inspection to Remove from Service and/or Rotor Tachometer Cables with Hexagonal Connector on One End	18 Apr 2012	Red		Refer to Models Affected

Models 269C-1 - Publications Index

Section 2  
Service Information Notices and Service Bulletins

Bulletin No.	Status Notation	Subject	Date Issued	Letterhead	Corresponding FAA AD Service Note	Notes
C1B-039	†	One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer	02 May 2013	Red		Refer to Models Affected
C1B-041	†	One-Time Load/Stroke Inspection of Landing Gear Dampers to be Performed at an Overhaul or Repair Facility	15 Apr 2014	Red		Refer to Models Affected

Number	Status	Nomenclature	Date
L-148	Active	Lubricating Oil	01 Feb 1989
L-161	Active	New Improved Clutch Spring Retainer	07 Apr 1997
L-163	Active	Exchange Program for Elastomeric Tail Rotor Fork	27 Sep 1999
L-165	Active	Compliance with Airworthiness Directive AD-99-17-10	02 Sep 1999
L-166	Active	New Retirement Time Life for 269A5103-51 Input Pinion and 269A5194 Carrier Assembly Installed in Model 269C-1 Helicopters	13 Dec 1999
L-168	Available Upon Request	New SA-269K-101 Fuel System Vent Kits (UK Only)	10 Aug 2000
L-169	Active	New SA-269K-101 Fuel System Vent Kits	01 Sep 2000
L-170	Active	Introduction of New 269A5175-35 and -37 Main Rotor Transmission Assemblies	01 Dec 2000
L-171	Active	Orientation of Main Rotor Transmission Backlash Shim	01 Dec 2000
L-172.1	Active	New Design-Tail Rotor Driveshaft	25 Jan 2002
L-173	Active	Special Inspection of Main Rotor Transmission Magnetic Plug	22 Aug 2001
L-174	Active	Introduction of New Lower Pulley Bearing Removal Tool	11 Sep 2001
L-180	Active	Function of Tail Rotor Driveshaft Damper Block	26 Sep 2008
L-181	Active	Retirement of Certain Engine and Rotor Tachmeter Cables	09 Jan 2009
L-182	Active	ELT Direct Replacement Authorization	17 Jun 2009
L-183	Active	Technical Publications - Policy & Price Changes, 2010	11 Mar 2010
L-184	Active	2010 Publications Schedule	11 Mar 2010

**This page is intentionally left blank**

Number	Status	Subject	Publication No.	Date
269C1-1	Incorporated	New Warning related to the use of components from aircraft with crash damage.	CSP-C1-2	Aug 2011
269C1-2	Incorporated*	Caution related to fretting that may occur in the Ring Gear Carrier Assembly P/N 269A5194.	CSP-C1-5A	12 Dec 2011
269C1-3	Incorporated*	Incorporates a Ring Gear Mounting Surface Inspection for fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C1-5A	12 Dec 2011
269C1-4	Incorporated*	Incorporates a Note to gear mating areas for fretting and adds inspection for gear mating areas for cracks of Ring Gear Carrier Assembly P/N 269A5194.	CSP-C1-5A	12 Dec 2011
269C1-5	Incorporated*	Incorporates procedures to repair Ring Gear Carrier Assembly P/N 269A5194 fretting that may occur.	CSP-C1-5A	12 Dec 2011
269C1-6	Incorporated*	Incorporates Changes to maintenance instructions for ring gear to carrier assembly due to fretting of Ring Carrier Assembly P/N 269A5194.	CSP-C1-5A	12 Dec 2011
269C1-7	Incorporated	100-Hour Periodic Inspection Requirement.	CSP-C1-2	15 Mar 2012
269C1-8	Incorporated	600-Hour Periodic Inspection Requirement.	CSP-C1-2	15 Mar 2012
269C1-9	Incorporated	Adds step to inspect the Damper Assembly.	CSP-C1-2	01 Mar 2013
269C1-10	Incorporated	Incorporates changes to Disassembly Inspection and Reassembly of Tail Rotor Driveshaft Damper Block.	CSP-C1-2	01 Mar 2013
269C1-11	Incorporated	100-Hour Periodic Inspection Requirement.	CSP-C1-2	01 Mar 2013
269C1-12	Incorporated	Adds new step to inspect the tail rotor damper block assembly.	CSP-C1-2	26 Aug 2013
269C1-13	Incorporated	Updates inspection of tail rotor damper block and adds a new paragraph to inspect installed damper assembly.	CSP-C1-2	26 Aug 2013
269C1-14	Incorporated	Updates inspection of splined drive sleeve.	CSP-C1-2	26 Aug 2013
269C1-15	Incorporated	Updates inspection of driven spline.	CSP-C1-2	26 Aug 2013

\* Data moved from HMI to CMM

## Section 4

## Model 269C-1 - Publications Index

## Temporary Revisions

Number	Status	Subject	Publication No.	Date
269C1-16	Active	Replaces Figure 17-2 (Sheet 9 of 9)	CSP-C1-2	15 Nov 2013
269C1-17	Active	Modifies Table 2-1. Servicing Materials (Operating Supplies), Item No. 2, 3, and 6.	CSP-C1-2	24 Jan 2014
269C1-18	Active	Adds footnote 12 to Table 2-1. Servicing Materials (Operating Supplies).	CSP-C1-2	24 Jan 2014
269C1-19	Active	Modifies Figure 2-9. Lubrication Chart (Sheet 1 of 5).	CSP-C1-2	24 Jan 2014
269C1-20	Active	Revises step o. (1), and step o. (2) of paragraph 5-3, Reassembly.	CSP-C1-2	15 Apr 2014
269C1-21	Active	Revises step b of paragraph 5-5, Leakage Check and adds new paragraph 5-5A, Load/Stroke Inspection to Section 5, Reassembly, Charging and Leakage Check.	CSP-C1-2	15 Apr 2014
269I-C1-1	Incorporated	Adds a new main rotor thrust bearing spacer tube, P/N 269A1318-005, S/N 95 and subsequent.	CSP-C1-6	13 Dec 2011
269I-C1-2	Incorporated	Modifies Index Numbers -21, -26, and -30 in Figure 3-26	CSP-C1-6	18 Jun 2013
269I-C1-3	Incorporated	Updates Figure 2-5. Fairing Assy-Center	CSP-C1-6	20 Aug 2013
269I-C1-4	Incorporated	Adds Index Numbers -58 thru -64 in Figure 2-5.	CSP-C1-6	20 Aug 2013
269I-C1-5	Incorporated	Updates Figure 3-26. Gearbox Assembly - Tail Rotor	CSP-C1-6	20 Aug 2013
269I-C1-6	Incorporated	Adds Index Number -39 in Figure 3-26	CSP-C1-6	20 Aug 2013