



**HUGHES  
SERVICE INFORMATION  
NOTICE**

NOTICE NO. 5  
DATE May 18, 1966  
PAGE 1 OF 1

FAA Approved

SUBJECT: INSPECTION - BELT DRIVE TRANSMISSION  
STRUT P/N 5423

MODELS AFFECTED: All 269A, 269A-1 and 269B Helicopters

TIME OF COMPLIANCE: At next 50 hour periodic inspection and at each  
50 hour periodic inspection thereafter.

PREFACE: To determine that the struts structural integrity  
is intact.

Reference

269A/A-1 Handbook of Maintenance Instructions

269B Handbook of Maintenance Instructions

- a. Visually inspect flange ends of strut for cracks and evidence of physical damage.

NOTE

If damage is found, make repairs in accordance with FAR 43. Replace strut if damage is in excess of limits.