



**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-108

DATE 1 January 1980

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: NEW WEDGE BASE LAMP SOCKET, PN 2973932, FOR
BOTH INSTRUMENT CLUSTER ASSEMBLIES

MODELS AFFECTED: All Model 269 Series Helicopters

Reference

269 Series — Basic HMI, Issued 1 April 1973; Revision No. 5, 1 February 1978

A new General Motors PN 2973932 wedge base lamp socket is now available as a replacement, when required, for existing PN 2965510 socket used in both 296A4111/4112 instrument cluster assemblies. The new socket is less susceptible to distortion from heat build up in the cluster assembly.

The PN 2973932 socket may be procured through your local Hughes Helicopter Service Center or Distributor.

Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California