



SCHWEIZER SERVICE INFORMATION LETTER

LETTER NO. L-126.1*
DATE 1 September 1982
PAGE 1 OF 1

*Supersedes Service Information Letter
No. L-126, dated 12 October 1981

TO—All owners and operators of Hughes Helicopters

SUBJECT: SUMMARY OF FAA SUPPLEMENTAL TYPE CERTIFICATES FOR
HUGHES MODEL 269 SERIES HELICOPTERS

MODELS AFFECTED: All Model 269 Series Helicopters

Reference

FAA Summary of Supplemental Type Certificates, Issued 1 April 1982
FAA Approved Rotorcraft Flight Manual for Model 269A, 269A (TH-55A), 269A-1,
269B or 269C Helicopters as applicable
Model 269 Series Basic HMI, Reissued 15 March 1982
Model 269 Series HMI Appendix A, Optional Equipment, Reissued 1 April 1980

The attached listing provides a summary of FAA Supplemental Type Certificates for optional kit items applicable to Hughes Model 269 Helicopters. The listing will be updated periodically in conjunction with later revision to the above referenced FAA STC Summary.

It is noted that STC items not tested or not specifically approved by Hughes Helicopters, Inc., are installed at owner/operator discretion and responsibility. Installation of each STC item is also limited to its compatibility with existing equipment installed on the helicopter, and to operating limitations and procedures prescribed by the Rotorcraft Flight Manual.

A flight manual Supplement is provided by the STC holder, when necessary, for specific optional STC kit items installed on Model 269 helicopters. Where provided, these Supplements must be carried in the Rotorcraft Flight Manual when the helicopter is modified by installation of kits. Except as modified by the flight manual Supplement, operation in compliance with Section I of the Approved Rotorcraft Flight Manual is mandatory. Other sections of the RFM or Supplements are recommended procedures.

Edward Koch, Manager
Customer Service Department
Hughes Helicopters, Inc.

(|) Denotes portion of text revised.

Customer Service Department

SCHWEIZER AIRCRAFT CORP. P.O. Box 147 Elmira, NY 14902

FEDERAL AVIATION ADMINISTRATION

SUPPLEMENTAL TYPE CERTIFICATES

AIRCRAFT

HUGHES HELICOPTERS

APRIL 1, 1982

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
269 Series; T.C. 4H12	SH1WE	Two 30-gallon tanks and spraying equipment.	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
269 Series; T.C. 4H12	SH3WE	Dust tanks and associated equipment (restricted category only).	WE	03250	Agricultural Aviation Engineering Company 858 Civic Center Drive Santa Clara, CA 95050
269 Series; T.C. 4H12	SH6WE	Aluminum frame cargo rack on front and rear beam assembly.	NW	71770	Simplex Manufacturing Company 5224 NE 42nd Avenue Portland, OR 97218
269 Series; T.C. 4H12	SH7WE	Installation of Columbia Helicopters P/N 4747-1 cargo rack on left-hand side and P/N 4747-2 on right-hand side. Reissued 7/24/70.	NW	25000	Columbia-Construction Helicopters, Inc. 4747 N. Channel Avenue Portland, OR 97217
269 Series; T.C. 4H12	SH8WE	Luggage/cargo carrier.	NW	25000	Columbia Helicopters, Inc. Swan Island Portland, OR 97208
269 Series; T.C. 4H12	SH11WE	Overlay instrument panel to accommodate Motorola ADF T-128, Sperry Horizon, Schwien turn and bank.	WE	23400	Clover Field Radio Supply 3231 Airport Avenue Santa Monica, CA 90406
269 Series; T.C. 4H12	SH14WE	Full flow lube oil filter 30#09A with element 1A0235.	WE	86625	Winslow Aerofilter Corporation 4069 Hollis Street Oakland, CA 94608
269 Series; T.C. 4H12	SH18WE	Cargo racks left and right sides.	WE	84635	Waters Helicopter Corporation International Airport Oakland, CA 94614
269 Series; T.C. 4H12	SH22WE	Landing gear conversion kit 100. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH23WE	Cargo sling unit with release mechanism. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH24WE	Modified spray system. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH26WE	Cargo sling unit with release mechanism. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4H12	SH31WE	Spray equipment.	WE	03250	Agricultural Aviation Engineering Company 1040 Di Giulio Avenue Santa Clara, CA 95050
269 Series; T.C. 4H12	SH34WE	Installation of "Tote-All" luggage/cargo carrier. Reissued 7/27/70.	NW	25000	Columbia-Construction Helicopters, Inc. 4747 N. Channel Avenue Portland, OR 97217
269 Series; T.C. 4H12	SH35WE	Spray system. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050
269 Series; T.C. 4A12	SH37WE	Floats. Amended 5/11/66.	EA	07250	Air Cruisers Company Div. of Garrett Corporation P.O. Box 180 Belmar, NJ 07719
269 Series; T.C. 4A12	SH40WE	Dust dispensing equipment. Amended 12/8/66.	WE	03250	Agricultural Aviation Engineering Company P.O. Box 450 Santa Clara, CA 95050

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODF	STC HCLDEF
160 Ser. T.C. 4H	SH41WE	MB64 spray equipment of MB 12CF seeding equipment.	WE	41755	Heli-Birds, Inc. 8103 Billy Mitchell Drive Santee, CA 92071
269 Series; T.C. 4H12	SH5AAL	Tundra boards.	AL	60158	Bill Moore Air Service P.O. Box 3687 Anchorage, AK 99500
269 Series; T.C. 4H12	SH60WE	Lycoming H10-460-B1B engine.	WE	62080	Pacific Airmotive Corporation Aviation Products Division 3411 Tulare Avenue Burbank, CA 91502
269 Series; T.C. 4H12	SH8AAL	Cargo racks.	AL	60158	Bill Moore Air Service P.O. Box 3687 Anchorage, AK 99500
269, 269A-1, 269A-2, 269B, 269C; T.C. 4H12	SA586EA	Installation of Hartzell anti-overspeed kit. Amended 12/19/72.	GL	41000	Hartzell Propeller, Inc. P.O. Box 909 350 Washington Avenue Piqua, OH 45356
269A; T.C. 4H12	SH69WE	Installation of float kit, P/N 269A4300-7. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230
269A Series; T.C. 4H12	SH74WE	Installation of Lycoming H10-360-A1A engine. Issued 1/31/67.	RM	47758	Kensair Corporation Jefferson County Airport Broomfield, CO 80020
269A; T.C. 4H12	SA589WE	Installation of full-flow lube oil filters on aircraft for the benefit of the engine. Amended 3/7/78.	WE	87500	Worldwide Aircraft Filter Corp. 1687 Akram Court P.O. Box 175B San Leandro, CA 94577
269A, 269A-1, 269B; T.C. 4H12	SH180WE	Installation of night advertising sign. Issued 5/16/75.	WE	64420	Edward L. Phipps 14404 Astoria Street Sylmar, CA 91342
269A, 269A-1, 269B; T.C. 4H12	SA630WE	Installation of oil filter assemblies. Reissued 8/29/74.	GL	61525	Nelson Filter Div. of Nelson Industries, Inc. P.O. Box 280 Stoughton, WI 53589
269A, 269A-1, 269B; T.C. 4H12	SA1003CE	Replacement of Hughes P/N 269A5501 idler pulley with Hughes P/N 269A5414 idler pulley. Reissued April 1974.	SW	38086	Global Helicopters, Inc. P.O. Box 51112 Tulsa, OK 74101
269A, 269A-1, 269B, 269C; T.C. 4H12	SH12CE	Installation of type AAF-102 AC filter. Amended 5/25/71.	GL	00750	AC Spark Plug Division General Motors Corporation 930 Harriet Street Flint, MI 48556
269A, 269A-1, 269B, 269C; T.C. 4H12	SH749SW	Installation of Heleco Model A-2-Z quick change combination dispersal system for both wet xxxx Amended 4/29/74.	WE	43344	Hughes Helicopter Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230
269A, 269A-1, 269B, 269C; T.C. 4H12	SA800EA	Installation of aviation white anti-collision strobe lights, Whelen Models A429, A430, A43A, A450, A408R/white, A408R/W or A470R/W (red/white), A500, A625 or A650 and associated power supplies or Model SA strobe light system. Amended 8/25/81.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
269A, 269A-1, 269B, 269C; 269, A, B, BM, BS, BE; T.C. 4H12, H3WE	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti-collision lights. Amended 8/25/81.	NE	85500	Whelen Engineering Company, Inc. Winter Avenue Deep River, CT 06417
269A, 269A-1, 269B, 269C; T.C. 4H12	SH1017CE	Install miscellaneous plastic fairings. Amended June 1977.	CE	59400	Milair, Inc. Route 81 Coddard, KS 67052
269A, B; T.C. 4H12	SH1018CE	Install landing gear damper piston. Issued May 1974.	SW	48500	Kinzie Industries, Inc. P.O. Box 847 Alva, OK 73717
269A, B; T.C. 4H12	SH1047CE	Install modified landing gear damper. Reissued November 1974.	SW	48500	Kinzie Industries, Inc. P.O. Box 847 Alva, OK 73717

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
269A, B, C; T.C. 4B12	SH152AWE	Installation of SKI/Hoskins Model 700801 anti-collision light system. Issued 8/18/72.	WE	77250	Symbolic Displays, Inc. P.O. Box 4322 1762 McGaw Avenue Irvine, CA 92664
269A, 269B, 269C; T.C. 4B12	SH157WE	Installation of fiberglass/aluminum baggage compartment. Issued 7/6/73.	WE	39300	Gould Engineering, Inc. Falcon Field Airport 4600 E. McKellips Road Mesa, AZ 85205
269A, 269B, 269C; T.C. 4B12	SH249WE	Installation of a searchlight kit. Issued 9/5/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4B12	SH258WE	Installation of MCT-10 mounting rack. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269A, 269B, 269C; T.C. 4B12	SH259WE	Installation of utility compartment. Issued 11/21/79.	WE	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B; T.C. 4B12	SA123WE	Installation of E.O.S. 1 KW searchlight and Technical Engineering & Manufacturing Co., Inc. Model TA-30 alternator.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4B12	SH128WE	Installation of Nightsun SX-10 searchlight Kit No. 019600 when: A TA-30 dual voltage alternator is installed per STC SH131WE; the helicopter is equipped with a Dovsek Model 200C or 300B light mounts, the mount's indicator light conforms to Hughes Service Information Notice #N92. Reissued 3/21/80.	WE	74500	Spectrolab, Inc. 12500 Gladstone Avenue Sylmar, CA 91342
269B, 269C; T.C. 4B12	SH131WE	Installation of EMPAC (U.S. Energy Corporation) Model TA-30 dual voltage alternator system (12 volts/60 amperes and 28 volts/68 amperes) in lieu of 12-volt alternator. Issued 7/7/71.	WE	80890	United State Energy Corporation 2780 Temple Avenue Long Beach, CA 90806
269B, 269C; T.C. 4B12	SH145WE	Installation of modified oil filler tube and dipstick. Issued 5/31/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4B12	SH146WE	Installation of utility window. Issued 6/2/72.	WE	65328	Progressive Aviation Limited Reid-Hillview Airport San Jose, CA 95122
269B, 269C; T.C. 4B12	SH202WE	Installation of controls for pilot-in-command on right side. Issued 4/28/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
269B, 269C, Normal Category; T.C. 4B12	SH245WE	Installation of searchlight. Issued 7/31/79.	WE	19986	Carter Engineering Company, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
269B, 269C; T.C. 4B12	SH286WE	Installation of Tayburn antenna deployment system. Issued 4/10/81.	WP	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
269B, 269C; T.C. 4B12 Only those rotorcraft having Hughes P/N 269A4593 or 269A8241, or 269A4593 muffler installed.	SH113BCE	Installation of engine exhaust tail pipe extension. Issued May 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052
269C; T.C. 4B12	SH134WE	Installation of Spectrolab Nightsun SX-16C searchlight. Amended 3/3/75.	WE	65328	Progressive Aviaitor Limited Reid-Hillview Airport San Jose, CA 95122
269C; T.C. 4B12	SH224WE	Installation of heated pitot. Issued 9/13/78.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
269C; T.C. 4B12	SH539GL	Installation of Sorensen 90-gallon sprayer system. Issued 7/8/81.	GL	73800	Sorensen Sprayers, Inc. Box 344, Airport Road Worthington, MN 56187
269C; T.C. 4B12	SH1099CE	Installation of cabin heater and engine exhaust tail pipe extension. Issued March 1975.	CE	59400	Milair, Inc. Route #1 Goddard, KS 67052

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
300 Series (269C); T.C. 4H12	SH333NW	Installation of automatic flagman. Issued 10/28/76.	NW	03500	Air Ag, Inc. Route 4 City-County Airport Walla Walla, WA 99362
369; T.C. H3WE	SH390NW	Installation of electronic weighing system. Reissued 4/19/77.	NW	56890	Measurement Systems International 580 South Lucille Street Seattle, WA 98108
369 Series; T.C. H3WE	SH598NW	Installation of load readout device. Issued 5/18/78.	NW	61842	Onboard Weighing Systems P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH667NW	Installation of fiberglass fuel tanks under rear seat. Issued 9/15/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369 Series; T.C. H3WE	SH829NW	Installation of a weighing system. Issued 9/6/79.	NW	61842	Onboard Weighing System P.O. Box 03413 Portland, OR 97203
369 Series; T.C. H3WE	SH1258SO	Installation of Utah Research and Development Co. Model 124BC101 battery charging system. Issued 8/10/81.	SO	82376	Van Dusen Aircraft Engineering 101A Space Park South Drive Nashville, TN 37211
369, 369A, 369H, 369HM, 369HS, 369HE, 369D; T.C. H3WE	SH207WE	Installation of range extension fuel tank in cargo area of Hughes 369 series helicopters. Issued 1/10/78.	WE	68501	Robertson Aircraft, Inc. P.O. Box 968 Tempe, AZ 85281
369A, 369D, 369H; 369HE, 369HM, 369HS; T.C. H3WE	SH215WE	Installation of floodlights on fuselage. Reissued 2/20/80.	SW	30002	Devore Aviation Corporation Suite B 6104 Kircher Street, N.E. Albuquerque, NM 87109
369A, H, HM, HE, HS; T.C. H3WE	SH358AL	Installation of Airglas L2700-369 skis. Amended 6/26/74.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369A, H, HS, HE; T.C. H3WE	SH1657SW	Full length, hard surface, skid shoes on standard skid landing gear. Issued 6/18/73.	SW	61650	Northrup Worldwide Aircraft P.O. Box 108 Lawton, OK 73501
369D; T.C. H3WE	SH220WE	Installation of a "HCS-500D" helicopter computer system. Issued 7/28/78.	WE	25772	Computer Avionics Corporation 398 Martin Avenue Santa Clara, CA 95050
369D; T.C. H3WE	SH246WE	Installation of ATI Model 13-004a, 13-0045 and 13-0046 speaker kits. Issued 8/17/79.	WE	14129	Avionics Technology, Inc. 2577 Robert Fowler Way San Jose, CA 95122
369D; T.C. H3WE	SH543GL	Installation of Astronautics autopilot system. Issued 7/27/81.	GL	13275	Astronautics Corp. of America 907 South First Street Milwaukee, WI 53201
369D; T.C. H3WE	SH654AL	Install Airglas Model L2700-369HD skis. Issued 10/24/78.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH678AL	Installation of Airglas skis. Issued 12/28/79.	AL	08125	Airglas Engineering Co., Inc. P.O. Box 6107 Anchorage, AK 99502
369D; T.C. H3WE	SH1172SO	Installation of an AFE Model 3000 canopy defogger system. Issued 1/14/81.	SO	01480	Advanced Flight Engineering, Inc. Interior Building St. Petersburg - Clearwater Inter'l Airport Clearwater, FL 33515
369D (H500D); T.C. H3WE	SH1546CE	Installation of Collins APS-841HAFCS. Issued 7/7/80.	CE	24250	Collins Avionics Division 400 Collins Road, N.E. Cedar Rapids, IA 52406
369D, 369HS; T.C. H3WE	SH493GL	Installation of a Shadin Co. 910510 fuel flow indicating system. Amended 8/25/81.	GL	71503	Shadin Company, Inc. 6950 Wayzata Boulevard Minneapolis, MN 55426
369D, 369H Series; T.C. H3WE	SH567NW	Installation of engine driven pump, tank hoses and spray nozzles for fire fighting. Issued 2/24/78.	NW	20750	Chadwick, Inc. 4375 Southwest 142nd Avenue Beaverton, OR 97005
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH112GL	Installation of Marathon CA1700-1 nickel cadmium storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213
369D, 369HE, 369HM, 369HS; T.C. H3WE	SA123GL	Installation of SAFT 1656-1 nickel cadmium electrical storage battery. Reissued 10/26/77.	GL	02480	Aero Quality Sales Company, Inc. 19717 East Nine Mile Road St. Clair Shores, MI 48213

4/1/82

HUGHES HELICOPTERS 5

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDER
369D, 369HE, 369HS; T.C. H3WE	SH236WE	Installation of searchlight. Issued 4/26/79.	WE	19986	Carter Engineering, Inc. 232 South Glasgow Avenue Inglewood, CA 90301
369D, HE, HM, HS; T.C. H3WE	SH552NW	Installation of cargo hook electronic scale system. Issued 1/4/78.	NW	73067	Marvin A. Smith 5503 West Flowing Lake Road Snohomish, WA 98290
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH183WE	Installation of turbine overtemper- ature warning system. Amended 4/4/77.	WE	60425	MRSC Incorporated 10959 San Diego Mission Road San Diego, CA 92108
369D, 369H, 369HE, 369HS; T.C. H3WE	SH290WE	Installation of a "T" instrument console. Issued 10/9/81.	WP	09280	ALEXAIR 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HM, 369HS; T.C. H3WE	SH401GL	Installation of Ni-Cad Model No. 72639 engine lubrication system scavenge filter. Issued 4/18/80.	GL	61546	Ni-Cad, Incorporated 24800 U.S. 20 West South Bend, IN 46628
369D, H, HE, HM, HS; T.C. H3WE	SH1142EA	Installation of APC starter- generator, P/N 150SG111Q. Issued 4/23/79.	EA	05750	Aircraft Parts Corporation 160 Finn Court Farmingdale, NY 11735
369D, H, HE, HM, HS; T.C. H3WE	SH1172SO	Installation of an AFE Model 3000 canopy defogger system. Reissued 3/30/81.	SO	01480	Advanced Flight Engineering, Inc. Interair Building St. Petersburg/Clearwater Int'l Arpt. Clearwater, FL 33520
369D, 369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1227SO	Installation of a wire strike protection system. Issued 5/18/81.	SO	17299	Bristol Aerospace, Ltd. P.O. Box 1177 Tri-Cities Airport Blountville, TN 37617
369D, HE, HM, HS; T.C. H3WE	SH958SO	Installation of SAFT 16156 nickel cadmium battery. Amended 1/17/79.	SO	69800	SAFT America, Inc. P.O. Box 1886 Valdosta, GA 31601
369D, 369HE, 369HS; T.C. H3WE	SH189WE	Installation of searchlight kit. Amended 3/16/79.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH190WE	Installation of P.A. speaker kit. Amended 4/14/77.	WE	09280	Alexair 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS. T.C. H3WE	SH250WE	Installation of a P.A. speaker kit. Issued 9/17/79.	WE	09280	ALEXAIP 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH281WE	Installation of VIP single passenger seats. Issued 2/5/81.	WP	09280	ALEXAIP 2955 Airport Drive Torrance, CA 90505
369D, 369HE, 369HS; T.C. H3WE	SH898EA	Installation of pod type cargo container kits. Amended 11/22/78.	EA	72263	Skypods Limited P.O. Box 221 Auriprior, Ontario, Canada
369D, 369HE, 369HS; T.C. H3WE	SH1134EA	Installation of external cargo container (POD) kit. Amended 2/11/82.	EA	83757	Viking Helicopters, Ltd. P.C. Box 5104 - Station "F" Ottawa, Ontario, K2C3H4 Canada
369H; T.C. H3WE	SH184NW	Installation of Chadwick C-500 aerial spray system. Issued 5/23/75.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369H; T.C. H3WE	SH431NW	Installation of Model 500 spray system. Amended 5/9/77.	NW	71770	Simplex Manufacturing Company 5224 Northeast 42nd Avenue Portland, OR 97218
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH155WE	Installation of battery temperature monitor system. Reissued 3/24/76.	WE	48750	F S Avionics, Inc. 18145 Judy Street Castro Valley, CA 94546
369H, 369HE, 369HM, 369HS; T.C. H3WE	SH1054EA	Installation of Garrett AiResearch environmental control system. (Carson Kit No. C500-10-50000). Amended 9/8/77.	EA	19950	Carson Helicopters, Inc. 32-H Blooming Glen Road Perkasie, PA 18944
369HE, 369HM, 369HS; T.C. H3WE	SH129WE	Installation of Chadwick C-20 auxiliary fuel systems. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH132WE	Installation of two side cargo racks P/N DMC-023-200-1. Issued 8/25/71.	NW	61798	Olympic Helicopters, Inc. 8241 Perimeter Road South Boeing Field Seattle, WA 98108

AIRCRAFT MAKE, MODEL & T.C. NO.	STC NO.	DESCRIPTION	RG	STC CODE	STC HOLDEP
369HE, 369HM, 369HS; T.C. H3WE	SA133WE	Installation of C-75 cargo rack set, P/N 75-0000-00. Amended 5/22/72.	NW	20750	Chadwick, Inc. 4375 S.W. 142nd Avenue Beaverton, OR 97005
369HE, 369HM, 369HS; T.C. H3WE	SH516AL	Installation of Model L2700-369HS skis. Issued 5/1/74.	AL	08125	Airglas Engineering Company, Inc. P.O. Box 6107 Anchorage, AK 99502
369HS; T.C. H3WE	SH214WE	Installation of external neutron detector moduel and associated cockpit displays. Issued 4/18/78.	WE	31225	EG & G, Incorporated P.O. Box 1912 Las Vegas, NV 89101
369HS; T.C. H3WE	SH242NW	Installation of battery in Hughes 369HS helicopter to replace original. Issued 12/11/75.	NW	47708	Keefer Aircraft Engineer 11457 Glendale Way South Seattle, WA 98168
369HS; T.C. H3WE	SH690SO	Installation of SunAir Electronics Model ASE-60 or ASE-125 HF radio transceiver and associated system. Reissued 6/20/73.	WE	43344	Hughes Helicopters Div. of Summa Corporation Centinela & Teale Streets Culver City, CA 90230