



SCHWEIZER SERVICE INFORMATION LETTER

LETTER NO. L-137
DATE: 11 FEB 1986
PAGE: 1 OF 1

TO: All Owners and Operators of Model 269 Series Helicopters

SUBJECT: Replacement of Aircraft Identification Plates

MODELS AFFECTED: All 269 Series Helicopters

PREFACE: In order to avoid possible misuse of aircraft I.D. plates, Schweizer Aircraft Corporation has instituted a stringent policy which will be followed for all requests of replacement I.D. plates. The following procedure is acceptable to and in compliance with recommendations set forth by the FAA.

POLICY:

- a) The customer must submit to Schweizer Aircraft Corporation a written request outlining the circumstances surrounding the need for a replacement I. D. plate.
- b) Prior to issuance of the I.D. plate, Schweizer will submit the request to the appropriate FAA office to allow the FAA to determine the validity of the need to replace the I.D. plate.
- c) The FAA will then notify Schweizer Aircraft as to whether or not the request is valid. The FAA will also authorize the requester to affix the replacement I.D. plate to the product: as required by FAR 45.13 (c).
- d) The old I.D. plate (when available) must be submitted to the FAA or Schweizer Aircraft Corp. for proper disposition.

WARNING

THE I.D. PLATE AS INSTALLED BY THE PRODUCT MANUFACTURER MUST REMAIN WITH THE PARTICULAR PRODUCT THROUGHOUT ITS USEFUL SERVICE LIFE. NO I.D. PLATE CAN BE REMOVED OR THE INFORMATION CONTAINED THEREON BE CHANGED UNLESS AUTHORIZED BY THE ADMINISTRATOR