

SUBJECT: SERVICE FACILITIES, FOR CORROSION DAMAGE INSPECTION AND REPAIR OF THE MAIN ROTOR DRIVESHAFT PART NUMBER 269A5305. REFERENCE SERVICE BULLETIN B-243.

Schweizer Aircraft Corp. (SAC) is offering full inspection and repair services for compliance with Service Bulletin B-243. Although not required by Service Bulletin B-243, a coating of manganese phosphate will be offered only by SAC. The manganese phosphate is currently applied to all new manufactured drive shafts prior to prime and paint. Contact SAC Product Support for associated pricing and turn around time.

For your convenience, Schweizer has compiled below a list of field service facilities that have notified Schweizer that they have the resources available to comply with the subject inspection and repair procedures. Please contact the service facility most convenient to you for price and turn around quotations.

Schweizer Aircraft Corp., does not warrant or otherwise take responsibility for the capabilities or workmanship of the field service facilities listed herein.

EUROPEAN COUNTRIES:

S.P. Helicopter - Service GmbH

Industriegebiet W5461 Dattenberg/Linz Federal Republic of Germany

Attn: John A. Adams

Phone: 49/2644/560834

49/2644/560837

Fax: 49/2644/560840

Hell Holland Bv Kanaal B ZZ 3 Emmercompascuum

The Netherlands Attn: Rene Haring

Aun. Hone Hanny

Phone: 59-12-4318/1251

Fax: 59-12-2769

SAAB Helikopter AB Stockholm - Skavsta Airport Box 326

S-611 27 NyKoping

Sweden

Phone: 46-155-217640

Fax: 46-155-285248

UNITED STATES:

Schweizer Aircraft Corp. 1250 Schweizer Road

Big Flats, NY 14814 Attn: Gene Nailor

Phone: 607/739-3821 Fax: 607/796-2488 Sterling Helicopters

Pier 36

Delaware Ave. & Catherine St. Penn's Landing Heliport

Philadelphia, PA 19147

Attn: Phil Bidden

Phone: 215/271-2510 Fax: 215/271-7794

2001 Airway Avenue

Fort Collins, CO 80524

Phone: 303/484-6804

Fax: 303/224-3899

Century Helicopters, Inc.

Attn: Les Batman, Maintenance Director

Omniflight Helicopters, Inc.

Route 7, Highway 51 South Janesville, Wisconsin 53546

Attn: John Feeney, Director of Component Overhaul

Phone: 608/755-4700 Fax: 608/755-4714

CANADA:

AOG Heliservices

Norman Rogers Airport Kingston, Ontario Canada, K7M 4V8

Attn: Rob Pritchard, Director of Maintenance

Phone: 613/389-8596 Fax: 613/389-5586

ASIAN COUNTRIES:

Aeronautical Maintenance Services Pte Ltd

Building 227A West Camp Seletar Airbase Singapore 2879

Attn: Mr. Kevin W. Smith, Manager

Phone: 4815733, 4813742, 4823235

Fax: 4819290

Tlx: RS23807 Airman

SCHWEIZER AIRCRAFT CORP.

David J. Roemer, Group Manager

Helicopter Program Office