



SCHWEIZER SERVICE LETTER

SUBJECT: ADDITIONAL LUBRICANTS FOR LOWER COUPLING DRIVE SHAFT

MODELS AFFECTED: 269A, TH-55A, 269A-1, 269B, and 269C Helicopters

In addition to EP #1 (Basic HMI, Table 2-1, Item 6) the following heavy duty greases are approved and preferred for lubrication of the lower coupling drive shaft:

- Anderol 786

Huls America, Inc
Turner Place
P.O. Box 365
Piscataway, NJ 08855
Phone (800) 631-5275
FAX (908) 980-6708

- Syn-Tech 3913G, Federal Stock No. 9150-00-506-8497 (Bell Helicopter grease No. 204-040-755-5 also meets this requirement and can be purchased direct from Bell or an authorized Bell Customer Service Facility.)

Syn-Tech, Ltd.
1433 W. Fullerton Ave.
Addison, IL 60101
Phone (708) 620-7050
FAX (708) 620-4832

The Basic HMI will be updated to include the Anderol and Syn-Tech greases at the next scheduled revision.

Mixing any of the above greases is prohibited. When changing to a different grease type, it is necessary to remove the old grease and clean the affected parts before applying new grease.

Lubrication instructions for the lower coupling drive shaft remain as specified in the Basic HMI.

SCHWEIZER AIRCRAFT CORP.

A handwritten signature in cursive script that reads "David J. Roemer".

David J. Roemer, Manager

Customer Support Services