



**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-2

DATE June 8, 1966

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: RECOMMENDED OVERHAUL PERIODS - ROTORCRAFT
POWERPLANT

MODELS AFFECTED: All 269A, TH55A, 269A-1 and 269B Helicopters

Reference

AVCO Lycoming Division Service Instruction No. 1009H dated April 22, 1966, Sub: Recommended Overhaul Periods, and No. 1088B dated December 17, 1965, Sub: Inspection Procedure to Determine Exhaust Valve Wear

The above referenced instruction states that the factory recommended overhaul period for Lycoming engines O-360-C2B, C2D, HO360, H1O-360-A, -B series used in Hughes helicopters is now 900 hours.

In addition it is recommended that owners and operators engaged in agricultural application adhere to valve inspection defined in the second reference.

The Hughes Tool Company strongly urges owners and operators to comply with the engine manufacturer's recommendations.