



TRAINING

HUGHES
SERVICE INFORMATION
LETTER

LETTER NO. L-37
DATE Jan. 2, 1968
PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: INTERIM REVISION - HANDBOOK OF MAINTENANCE
INSTRUCTIONS (HMI) RE: OVERHAUL CYCLE, MAIN
ROTOR GEAR DRIVE ASSEMBLY

MODELS AFFECTED: All 269 Series Helicopters

Reference

269A/A-1/TH-55A Handbook of Maintenance Instructions, Reissued 15 Dec. 1967
269B Handbook of Maintenance Instructions, Reissued 15 August 1967
Handbook of Maintenance Instructions, HMI Overhaul Addendum,
Main Rotor Gear Drive Assembly, Part No. 5175, dated 1 August 1966

The information given in this Service Information Letter lists new limited life and component overhaul data for the P/N269A5175 Main Rotor Gear Drive Assembly. The finite life and overhaul cycle for the above assembly has been increased to 2250 hours. This data supersedes applicable data in the current HMI and is to be considered a part of the HMI until formal incorporation is accomplished during the next revision cycle.

269A/A-1/TH-55A HANDBOOK OF MAINTENANCE INSTRUCTION, Page 1-32.
269B HANDBOOK OF MAINTENANCE INSTRUCTION, Page 1-31.

Table 1-7. Limited Life and Component Overhaul List

Under "Overhaul Cycle (Hours)" for Drive Assembly - Main Rotor Gear

DELETE: 1780

And replace with the following: 2250