



HUGHES  
SERVICE INFORMATION  
LETTER

LETTER NO. L-56  
DATE June 12, 1970  
PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: OIL PRESSURE LIMITATIONS

MODELS AFFECTED: Model 269A(TH-55A) Helicopter Serial Nos. 0315  
and subsequent

Reference

269A/A-1/TH-55A Handbook of Maintenance Instruction,  
Revised 15 March 1969

Hughes Model TH-55A U.S. Army Trainer Owners Manual,  
DOA/WE-1 Approved 8 November 1967

A minimum oil pressure reading of 25 PSI for engine idling speeds, and a new 60-100 PSI oil pressure range for normal engine operation are authorized for the TH-55A helicopter. These new oil pressure limitations are in accordance with the Lycoming Engine Operator's Manual and Engine Specification for the HIO-360-B1A engine.

Edward Koch, Manager  
Customer Service Department  
Hughes Tool Co. - Aircraft Division