

**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-91

DATE 26 July 1976

PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters


SUBJECT: ALTERNATE LAMP FOR ENGINE INSTRUMENT 3-PACK
UNITS, PN 269A4111 SERIES AND 269A4112 SERIES

MODELS AFFECTED: 269A(TH-55A) Helicopter Serial No. 0315 and subsequent
269A-1 Helicopter Serial No. 0019 and subsequent
269B Helicopter Serial No. 0145 and subsequent
269C Helicopter Serial No. 0004 thru 0509

Reference

269 Series - Basic HMI, Issued 1 April 1973; Revision No. 3, 15 March 1975

A longer-life lamp, GE No. 161, is now available as replacement, when required, for existing No. 194 or No. 158 lamps used on the subject engine instrument 3-pack units. Installation of the alternate lamp is also recommended where excessive temperatures may cause deformation of the plastic lamp holders. The lamp generates less heat and will thus reduce the possibility of heat damage. List price for the GE No. 161 lamp is \$0.77 each.



Edward Koch, Manager
Customer Service Department
Hughes Helicopters

Customer Service Department - Hughes Helicopters - Culver City, California