



## SCHWEIZER SERVICE LETTER

**SUBJECT:** UPGRADE OF 269A4564-5 LINEAR ACTUATOR

**MODELS AFFECTED:** Model 269C Helicopters

**REFERENCE:** Schweizer Service Bulletin B-284

As specified in Service Bulletin B-284, the subject actuator must be upgraded to the current configuration (P/N 269A4564-9).

In order to accomplish this modification, the following SA-269K-116-001 Kit is required.

Kit List Price: \$2,096.89

This kit may be ordered from SAC.