



**HUGHES
SERVICE INFORMATION
LETTER**

LETTER NO. L-26
DATE July 7, 1967
PAGE 1 OF 1

TO—All owners and operators of Hughes Helicopters

SUBJECT: INTERIM REVISION - HANDBOOK OF MAINTENANCE
INSTRUCTIONS (HMI) RE: B1145-1 MAIN ROTOR BLADE
ASSEMBLY

MODELS AFFECTED: All 269 Series Helicopters

Reference

269A/A-1 Handbook of Maintenance Instructions
TH55A HMI Addendum
269B Handbook of Maintenance Instructions

The information given in this Service Information Letter is to be considered a part of the HMI until formal incorporation is accomplished at the next revision cycle.

Page 1-28, Table 1-7, Limited Life and Component Overhaul List, Model 269A/A-1 Handbook of Maintenance Instructions, as reissued 1 March 1967.

ADD:

<u>Nomenclature</u>	<u>Part No.</u>	<u>Part Life (Hours)</u>
Blade Assembly-Main Rotor	269B1145-1	1366
Blade Assembly-Main Rotor	269A1131-1	1366

Page 1-15, Table 1-6, Limited Life Parts List, Model 269B Handbook of Maintenance Instructions, as reissued 15 September 1965.

ADD:

<u>Nomenclature</u>	<u>Part No.</u>	<u>Part Life (Hours)</u>
Blade Assembly-Main Rotor	269B1145-1	1366
Blade Assembly-Main Rotor	269A1131-1	1366

HELICOPTER SUPPORT SERVICES • HUGHES TOOL COMPANY • AIRCRAFT DIVISION • CULVER CITY, CALIFORNIA