

ASB DB-055
Revision A – December 14, 2015

TRANSMITTAL

Alert Service Bulletin (ASB) DB-055 dated April 1, 2014 has been revised. This page accompanies Revision A, dated December 14, 2015.

ASB DB-055A dated December 14, 2015 supersedes the Basic Issue of ASB DB-055, dated April 1, 2014. Text changes are indicated by a vertical line in the outer margin of the page. Illustration changes are indicated by a vertical line next to the figure title.

INSTRUCTIONS TO OPERATORS:

Operators that have complied with the original released ASB, contact Sikorsky Aircraft. Revision A rescinds this ASB in its entirety. No further action required.

HIGHLIGHTS OF THIS REVISION:

ASB DB-055, dated April 1, 2014 is rescinded in its entirety.



Sikorsky Aircraft Corporation


6900 Main Street P.O. Box 9729
Stratford, Connecticut 06615-9129
(203) 386-4000

269D™ HELICOPTER

ALERT SERVICE

BULLETIN

NON-FAA CERTIFIED HELICOPTER



NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLUDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN SIKORSKY AIRCRAFT CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

EXPORT WARNING: THESE COMMODITIES, TECHNICAL DATA OR SOFTWARE ARE SUBJECT TO THE EXPORT CONTROL OF EITHER THE INTERNATIONAL TRAFFIC IN ARMS REGULATIONS (ITAR) OR THE EXPORT ADMINISTRATION REGULATIONS (EAR) AND CANNOT BE EXPORTED WITHOUT THE PRIOR AUTHORIZATION OF EITHER THE DEPARTMENT OF STATE OR THE DEPARTMENT OF COMMERCE. THE TERM "EXPORT" INCLUDES ANY DISCLOSURE AND/OR PROVISION OF ACCESS TO COMMODITIES, TECHNICAL DATA OR SOFTWARE TO OR BY FOREIGN NATIONALS (WHETHER LOCATED IN THE UNITED STATES OR ABROAD). THIS REQUIREMENT ALSO APPLIES TO FOREIGN NATIONAL EMPLOYEES OF U.S. COMPANIES AND THEIR FOREIGN SUBSIDIARIES.

269D™ IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION.

ASB DB-055

April 1/14

Revision A • December 14/15

SUBJECT: KAflex® Drive Shaft and Coupling Assembly Service Life Expiration

Alert Service Bulletin No. DB-055, dated April 1, 2014, is rescinded in its entirety. The Calendar Service Life of KAflex Drive Shaft and Coupling Assembly, Part Numbers (P/N) SKCP2738-5 and SKCP2738-7, is no longer valid.

Reduced
Service Life

Page 1 of 1

This document does not contain export controlled technical data.

(Fold over and tape closed)

SIKORSKY AIRCRAFT CORPORATION

FACSIMILE NUMBER (860) 998-7565

EMAIL ADDRESS: GPSIKSASProductSafet@utc.com

ATTENTION: PRODUCT SAFETY MANAGER
SIKORSKY AIRCRAFT CORPORATION



IMPORTANT NOTICE

Upon **COMPLIANCE** with the attached ASB, Sikorsky requests your cooperation in completing and returning this **ENTIRE PAGE** by **MAIL, FAX, or scan & EMAIL**.

Please fill in the requested information at the bottom of the page, so we may maintain proper records documenting the configuration of your aircraft. This information is useful when determining configuration and effectivity of issues affecting fielded aircraft.

This request is in keeping with our policy to assure that our customers receive the latest information applicable for the maintenance of your aircraft. Thank you.

ALERT SERVICE BULLETIN: No. DB-055A **Compliance Record Card**

TITLE: Kaflex® Drive Shaft and Coupling Assembly Service Life Expiration

OWNER/OPERATOR: _____

SUBMITTED BY: _____ **DATE:** _____

FOLLOWING SERIAL NUMBERS ARE NOT AFFECTED BY THIS ASB

ASB HAS BEEN COMPLIED WITH ON HELICOPTER SERIAL NUMBERS:

(Fold Up to Arrows)



No Postage
Necessary

BUSINESS REPLY MAIL
FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT

POSTAGE WILL BE PAID BY ADDRESSEE

SIKORSKY AIRCRAFT CORPORATION
Commercial Systems and Services
Mailstop K100
124 QUARRY ROAD
TRUMBULL, CT 06611 U.S.A.
ATTENTION: PRODUCT SAFETY MANAGER
SIKORSKY AIRCRAFT CORPORATION

Please complete the form on the reverse side and FAX to
FACSIMILE NUMBER (860) 998-7565
Or scan and email to:
EMAIL ADDRESS: GPSIKSASProductSafet@utc.com
or fold and return ENTIRE form to Sikorsky Aircraft Corporation